

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21012096/KES3Q2**Date:** 28/02/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SMZ3423C **Insured Vehicle No :** SLV6961D
 Date of Loss: 23/11/2021 Nature of Claim: TP Claim No: MFL2021D0005120

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ3423C**
 Make & Model: HONDA VEZEL, 1.5 X HYBRID CVT (A) Engine No: L15B4036061
 Reg. Date: 07/04/2017 (Man. Year: 2016) Chassis No: RU11116055
 Colour: Metallic Blue Odometer: 51407 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Double Star 2 mm Rear Left Side: Dunlop 4 mm
 Front Right Side: Double Star 2 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,071.92	1,556.80	1,515.12	49.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	825.00	1,375.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,271.92	2,381.80	2,890.12	54.82
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	5,271.92	1,900.00	3,371.92	63.96
+ GST 7.00/7.00% (S\$)	369.03	133.00	236.03	63.96
Nett Amount (S\$)	5,640.95	2,033.00	3,607.95	63.96
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		2,369.45		

INSPECTION

Date of Assignment: 29/11/2021
 Date Inspected: 30/11/2021 Inspected At: COMPLETE VMS PTE LTD (HQ)
 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex
 Singapore 575721
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Jan 2022)

Parts: M1-SUV HONDA VEZEL 1.5 X HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMZ3423C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,057.00 FL	*953.00 FL
2	1		*TAIL GATE LOCK	Dented	133.10 FL	*133.10 FL
3	1		*TAIL GATE INNER TRIM BOARD	Serviceable	204.80 FL	*- FL
4	1		*TAIL GATE HONDA LOGO	Not Necessary	39.30 FL	*- FL
5	1		*VEZEL EMBLEM	Necessary	54.60 FL	*54.60 FL
6	1		*REAR BUMPER	Buckled	555.30 FL	*555.30 FL
7	2		*REAR BUMPER RETAINER	Serviceable	87.20 FL	*- FL
8	2		*REAR BUMPER REFLECTOR	Serviceable	357.00 FL	*- FL
9	1		*REAR END PANEL	Repair	490.20 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Serviceable	76.60 FL	*- FL
11	1		*TAIL GATE LATCH	Repair	41.30 FL	*- FL
12	1		*TAIL GATE WEATHERSTRIP	Serviceable	105.20 FL	*- FL
13	2		*REVERSE SENSOR	Torn	460.64 FS	*200.00 FS
14	10		*TAIL GATE INNER TRIM BOARD CLIP	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,712.24	1,896.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	640.32	339.20
Total Parts (\$\$)	3,071.92	1,556.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT DAMAGE PARTS TO FACILITATE REPAIR	New	1,000.00	400.00
2	SPRAI PAINT DAMAGE AFFECT AREA	New	800.00	200.00
3	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE AND REFIT TAIL GATE MECHANISM TO FACILITATE REPAIR	New	120.00	60.00
5	RUST PROOFING TRETMENT	New	80.00	30.00
6	CHECK WIRING	New	50.00	15.00
Gross Labour Cost (\$)			2,200.00	825.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >