

ASS. REC. BY:

REF:

GRB/ 210120861Kc

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

859K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SM 8 3423C

Yr Regn:

04, 17

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c

1496

Colour:

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

51407

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RUI

1116055

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

Pirelli Star 215/60R16

R: Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

2

mm

R/Bal.

4

mm

L/Bal.

2

mm

L/Bal.

4

mm

D.O.A.

23/11/21

D.O.I.

30/11/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/12 21 Reg 819002 Car

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



COMPLETE VMS PTE LTD
176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.cometevms.com.sg

The Premier One Stop Vehicle Accident Claims Centre

Tay Ann Ji
636, Ang Mo Kio Avenue 6, #05-5173
Singapore 560636

Attention: Owner
Contact: 97946258

Not Notified
61 Day @ 1900hr
Recovery After Paint

ESTIMATE ES010145
Date 29/11/2021
Vehicle Number SMZ3423C
Make / Model HONDA VEZEL 1.5X CVT
Engine Number L15B4036061
Chassis Number RU11116055
Accident Date 23 Nov 2021
Policy Number 5122045617

Description

8 days

Qty Unit Price Amount

Parts

List Items

Tail Gate	<i>953</i>	<i>Bz</i> 1	S\$1,057.00	S\$845.60	<i>✓</i>
Tail Gate Lock		<i>nd A</i> 1	S\$133.10	S\$106.48	<i>✓</i>
Tail Gate Inner Trim Board		<i>Ln</i> 1	S\$204.80	S\$163.84	<i>X</i>
Tail Gate Honda Logo		<i>nn</i> 1	S\$39.30	S\$31.44	<i>X</i>
Vezel Emblem		<i>Ln</i> 1	S\$54.60	S\$43.68	<i>✓</i>
Rear Bumper		<i>Bu</i> 1	S\$555.30	S\$444.24	<i>✓</i>
Rear Bumper Retainer		<i>Ln</i> 2	S\$43.60	S\$69.76	<i>X</i>
Rear Bumper Reflector		<i>Ln</i> 2	S\$178.50	S\$285.60	<i>X</i>
Rear End Panel		<i>n</i> 1	S\$490.20	S\$392.16	<i>X</i>
Rear End Panel Top Garnish		<i>Ln</i> 1	S\$76.60	S\$61.28	<i>X</i>
Tail Gate Latch		<i>n</i> 1	S\$41.30	S\$33.04	<i>X</i>
Tail Gate WeatherStrip		<i>Ln</i> 1	S\$105.20	S\$84.16	<i>X</i>
Reverse Sensor		<i>Tn</i> 2	S\$287.90	S\$460.64	<i>200hr</i>

Discount 20% applied \$3,021.92

Special Nett Items

Tail Gate Inner Trim Board Clip	<i>nn</i> 10	S\$5.00	S\$50.00	<i>X</i>
			\$50.00	

Labour

Nett

To Remove And Refit Damage Parts To Facilitate Repair	1	S\$1,000.00	S\$1,000.00	<i>400hr</i>
Spray Paint Damage Affect Area	1	S\$800.00	S\$800.00	<i>200hr</i>

Pages

1 / 2

COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which may be require after the work has begin



Tay Ann Ji
636, Ang Mo Kio Avenue 6, #05-5173
Singapore 560636

Attention: Owner
Contact: 97946258

COMPLETE VMS PTE LTD
176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.cometevms.com.sg

The Premier One Stop Vehicle Accident Claims Centre

ESTIMATE ES 010145
Date 29/11/2021
Vehicle Number SMZ3423C
Make / Model HONDA VEZEL 1.5X CVT
Engine Number L15B4036061
Chassis Number RU11116055
Accident Date 23 Nov 2021
Policy Number 5122045617

Description	Qty	Unit Price	Amount
Remove & Reinstall Rear Windscreen	1	S\$150.00	S\$150.00 120/
To Remove And Refit Tail Gate Mechanism To Facilitate Repair	1	S\$120.00	S\$120.00 60/
Rust Proofing Treatment	1	S\$80.00	S\$80.00 30/
Check Wiring	1	S\$50.00	S\$50.00 15/
Discount	applied		\$2,200.00
Total			\$5,271.92

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: