



Tay Ann Ji
636, Ang Mo Kio Avenue 6, #05-5173
Singapore 560636

Attention: Owner
Contact: 97946258

COMPLETE VMS PTE LTD
176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.cometevms.com.sg

The Premier One Stop Vehicle Accident Claims Centre

ESTIMATE

ES 010145

Date

29/11/2021

Vehicle Number

SMZ3423C

Make / Model

HONDA VEZEL 1.5X CVT

Engine Number

L15B4036061

Chassis Number

RU11116055

Accident Date

23 Nov 2021

Policy Number

5122045617

8 days

Description

Qty

Unit Price

Amount

Parts

List Items

Tail Gate

953

By 1

S\$1,057.00

S\$845.60

✓

Tail Gate Lock

nd R 1

S\$133.10

S\$106.48

✓

Tail Gate Inner Trim Board

R 1

S\$204.80

S\$163.84

X

Tail Gate Honda Logo

rr 1

S\$39.30

S\$31.44

X

Vezel Emblem

R 1

S\$54.60

S\$43.68

✓

Rear Bumper

Bu 1

S\$555.30

S\$444.24

✓

Rear Bumper Retainer

R 2

S\$43.60

S\$69.76

X

Rear Bumper Reflector

R 2

S\$178.50

S\$285.60

X

Rear End Panel

R 1

S\$490.20

S\$392.16

X

Rear End Panel Top Garnish

R 1

S\$76.60

S\$61.28

X

Tail Gate Latch

R 1

S\$41.30

S\$33.04

X

Tail Gate WeatherStrip

R 1

S\$105.20

S\$84.16

X

Reverse Sensor

Tn 2

S\$287.90

S\$460.64

2000

Discount 20% applied

\$3,021.92

Special Nett Items

Tail Gate Inner Trim Board Clip

rr 10

S\$5.00

S\$50.00

X

\$50.00

Labour

Nett

To Remove And Refit Damage Parts To Facilitate Repair

1

S\$1,000.00

S\$1,000.00

4000

Spray Paint Damage Affect Area

1

S\$800.00

S\$800.00

200

Pages

1 / 2

COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which may be require after the work has begin



Tay Ann Ji
636, Ang Mo Kio Avenue 6, #05-5173
Singapore 560636

Attention: Owner
Contact: 97946258

COMPLETE VMS PTE LTD
176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.cometevms.com.sg

The Premier One Stop Vehicle Accident Claims Centre

ESTIMATE ES010145
Date 29/11/2021
Vehicle Number SMZ3423C
Make / Model HONDA VEZEL 1.5X CVT
Engine Number L15B4036061
Chassis Number RU11116055
Accident Date 23 Nov 2021
Policy Number 5122045617

Description	Qty	Unit Price	Amount
Remove & Reinstall Rear Windscreen	1	S\$150.00	S\$150.00 1201
To Remove And Refit Tail Gate Mechanism To Facilitate Repair	1	S\$120.00	S\$120.00 601
Rust Proofing Treatment	1	S\$80.00	S\$80.00 301
Check Wiring	1	S\$50.00	S\$50.00 151

Discount applied \$2,200.00

Total \$5,271.92

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: