

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

29-Nov-21

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD1176D

|          |                                                   |    |                      |
|----------|---------------------------------------------------|----|----------------------|
| 1 pc     | Bonnet grille                                     | \$ | 385.00/scr           |
| 2 pcs    | Front n/s & o/s head lamps @ \$1028.00            | \$ | 2,056.00RH/uf/LH?    |
| 1 pc     | Front bumper                                      | \$ | 531.00/cut           |
| 1 pc     | Front bumper upper reinforcement                  | \$ | 40.00?               |
| 1 pc     | Front bumper emblem                               | \$ | 44.00/nic            |
| 1 pc     | Front bumper centre grille                        | \$ | 174.00/DIS           |
| 1 pc     | Front bumper lower stiffer                        | \$ | 134.00?              |
| 1 pc     | Front bumper tow hook cover                       | \$ | 14.00/DIS            |
| 1 pc     | Front bumper inner sponge                         | \$ | 110.00?              |
| 1 pc     | Front bumper reinforcement                        | \$ | 328.00?              |
| 2 pcs    | Front bumper n/s & o/s side retainer @\$16.00     | \$ | 32.00/nic            |
| 2 pcs    | Front bumper n/s & o/s upper bracket @\$16.00     | \$ | 32.00/nic            |
| 2 pcs    | Front bumper n/s & o/s support bracket @\$16.00   | \$ | 32.00/nic            |
| 2 pcs    | Front bumper n/s & o/s protector @\$51.00         | \$ | 102.00RH Det/LH SVC  |
| 2 pcs    | Front bumper n/s & o/s fog light cover @\$66.00   | \$ | 132.00RH/DIS/LH SVC? |
| 1 pc     | Boot lid                                          | \$ | 1,119.00XR           |
| 1 pc     | Boot lid lock                                     | \$ | 99.00XSVC            |
| 1 pc     | Bootlid lock cable                                | \$ | 35.00XSVC            |
| 1 pc     | Bootlid striker                                   | \$ | 21.00XSVC            |
| 1 pc     | Bootlid emblem                                    | \$ | 27.00XSVC            |
| 1 pc     | Bootlid CRDi                                      | \$ | 29.00XSVC            |
| 1 pc     | Boot lid rubber weatherstrip                      | \$ | 96.00/Det            |
| 1 pc     | Boot lid lower garnish                            | \$ | 290.00XR             |
| 2 pcs    | Bootlid hinges                                    | \$ | 132.00XSVC           |
| 1 pc     | Bootlid inner trim                                | \$ | 190.00XSVC           |
| 1 pc     | End panel inner garnish                           | \$ | 74.00/DIS            |
| 1 pc     | Rear bumper                                       | \$ | 696.00/cut           |
| 1 pc     | Rear bumper lower cover                           | \$ | 206.00/Det           |
| 2 pcs    | Rear bumper n/s & o/s side bracket @ \$29.00      | \$ | 58.00/nic            |
| 1 pc     | Rear bumper inner sponge                          | \$ | 114.00?              |
| 1 pc     | Rear bumper reinforcement                         | \$ | 607.00?              |
| 2 pcs    | Rear bumper stay o/s & n/s @ \$54.00              | \$ | 108.00?              |
| 2 pcs    | Rear bumper reinforcement lower bracket @ \$18.00 | \$ | 36.00?               |
| 2 pcs    | Rear bumper reinforcement upper bracket @ \$18.00 | \$ | 36.00?               |
| 2 pcs    | Rear bumper reflector n/s & o/s @ \$46.00         | \$ | 92.00XSVC            |
| 2 pcs    | Rear n/s & o/s tail lamp @ \$421.00               | \$ | 842.00XSVC           |
| 2 pcs    | Bootlid n/s & o/s reflector @ \$350.00            | \$ | 700.00XSVC           |
|          |                                                   | \$ | 9,753.00             |
| Less 10% |                                                   | \$ | 975.30               |
|          |                                                   | \$ | 8,777.70             |

29-Nov-21

# ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1176 D

## S/NETT

|       |                                                                                                                                                        |    |                         |
|-------|--------------------------------------------------------------------------------------------------------------------------------------------------------|----|-------------------------|
| 1 set | Front bumper clips                                                                                                                                     | \$ | 48.00 / nec             |
| 1 pc  | Front no. plate with casing                                                                                                                            | \$ | 50.00 / scr             |
| 1 set | Rear bumper clips                                                                                                                                      | \$ | 48.00 / nec             |
| 1 set | End panel inner garnish clips                                                                                                                          | \$ | 30.00 / nec             |
| 1 set | Bootlid inner trim clips                                                                                                                               | \$ | 52.00 X Svc             |
| 1 set | Bootlid lower garnish clips                                                                                                                            | \$ | 60.00 / nec             |
| 1 set | Bootlid stickers                                                                                                                                       | \$ | 100.00 / nec 80         |
| 1 set | Reverse sensor                                                                                                                                         | \$ | 280.00 / cut            |
| 1 pc  | Rear no. plate with casing                                                                                                                             | \$ | 50.00 X Svc             |
|       | Sundry                                                                                                                                                 | \$ | 50.00 X Svc             |
|       | To check for wiring and to focus head lamps                                                                                                            | \$ | 80.00 <del>XXX</del> 30 |
|       | To dismantle / replace reverse sensor to new bumper and reset to the same                                                                              | \$ | 120.00 30               |
|       | To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.                                 | \$ | 180.00 40               |
|       | To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc | \$ | 1,400.00 720            |
|       | To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, front bumper                                                    | \$ | 1,000.00 720            |
|       | To apply rustproofing on the repaired and replaced panels.                                                                                             | \$ | 80.00 30                |
|       |                                                                                                                                                        | \$ | <u>12,405.70</u>        |

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Thuan@Lkhauto.com

82235769

29/11/21 1730

L/S after repair photo

wp 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: