

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Estimate

Vehicle No:

SMQ5974M

Make and model:

Honda Vezel

Chassis:

RU11107390

Qty Spare parts

List price

2016

1	Tailgate	\$	✓	953.30	DDV ✓
1	Tailgate "Vezel" emblem	\$		56.30	NECV ✓
1	Tailgate windscreen glasss upper rubber moulding	\$	46.00	✓ 52.00	} NECV
1	Tailgate windscreen glasss lower rubber moulding	\$		✓ 52.00	
1	Tailgate windscreen glasss RH rubber moulding	\$		✓ 52.00	
1	Tailgate windscreen glasss LH rubber moulding	\$		✓ 52.00	
1	Tailgate LH lamp	\$		413.30	} NNX
1	Tailgate LH lamp gasket	\$		38.50	
1	Tailgate RH lamp	\$		413.30	
1	Tailgate RH lamp gasket	\$		38.50	
1	Tailgate outer garnish	\$		231.00	NDX
1	Tailgate outer garnish emblem	\$		✓ 29.00	NECV ✓
1	Tailgate reverse camera	\$		1,020.74	NDX
1	Tailgate inner trim board	\$		✓ 154.70	BRV ✓
1	Tailgate lock	\$		✓ 189.00	JM ✓
1	Tailgate lock catch	\$		27.50	NNX
1	Tailgate inner pull handle	\$		27.50	NDX
1	Tailgate weatherstrip	\$		✓ 96.80	TNV ✓
1	Rear bumper	\$		✓ 465.70	DDV ✓
1	Rear bumper lower cover	\$		✓ 251.00	BRV ✓
1	Rear bumper LH reflector	\$		141.10	NDX
1	Rear bumper LH side cover	\$		✓ 198.00	BRV ✓
1	Rear bumper LH side retainer	\$		✓ 26.50	NECV
1	Rear bumper RH reflector	\$		141.10	} NDX
1	Rear bumper RH side cover	\$		198.00	
1	Rear bumper RH side retainer	\$		✓ 26.50	NECV
1	LH taillamp	\$		487.60	} NDX
1	LH taillamp gasket	\$		44.20	
1	RH taillamp	\$		487.60	
1	RH taillamp gasket	\$		44.20	
1	End panel	\$		415.60	DDX R
1	End panel inner garnish	\$	92.30	109.00	BRV ✓
1	End panel antenna sensor	\$		65.10	} NSX
1	End panel buzzer sensor	\$		85.60	
1	Rear compartment panel tray garnish	\$		485.90	} NDX
1	Rear compartment panel tray garnish top cover board	\$		430.30	
1	Rear LH fender arch moulding	\$		198.00	} NDX
1	Rear RH fender arch moulding	\$		198.00	

S 2736.80 8,396.44
 -20% S 547.36 1,679.29
 S 2189.44 6,717.15

Qty Spare parts

Special Nett price

1 Tailgate windscreen glass sealant
 1 Tailgate windscreen glass inner seal
 1set Tailgate inner trim board clips
 1set Tailgate outer garnish clips
 1set Rear bumper clips
 1set Rear bumper reverse sensors
 1set Rear fender RH arch moulding clips
 1set Rear fender LH arch moulding clips
 1 End panel joint sealant
 1set End panel inner garnish clips

S 30.00 70.00
 S 30.00 50.00
 S 30.00 60.00
 S 30.00 50.00
 S 30.00 70.00
 S 200.00 280.00
 S 70.00 70.00
 S 70.00 70.00
 S 30.00 80.00
 S 30.00 60.00
 380.00

NECV
 NNX
 NECV
 SCV
 NNX
 NECV
 NECV

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
 To panel beating, cut / weld and re-align all affected panels

S 800.00 1,000.00 ✓

Spray painting on affected panels

S 600.00 1,000.00 ✓

Check wiring and lighting system

S 80.00 80.00
 S 70.00 70.00
 NNX

Apply rust coating chemical on affected panels

S 70.00 70.00

Remove and reinstall tailgate windscreen glass to assist repair

S 120.00 200.00 ✓

Remove and replace tailgate inner components to assist repair

S 80.00 180.00

Remove and replace tailgate reverse camera to assist repair

S 100.00 100.00 NNX

Remove and replace rear bumper reverse sensors to assist repair

S 60.00 70.00 ✓

Remove and replace rear inner trims, garnish and boards to assist repair

S 220.00 220.00 NNX

Survey + Resurvey
 30/11/2021
 TGM in line
 1555 LRS

Lump sum repair
 Repair days 6

1660.00

Total: S 10,497.15

Parts 2,052.60
 SN 380.00
 Labour 1,660.00
 4,092.60
 @ 20% 818.52
 3,274.08

LS 3250/2

TGM in line
 25/12/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: