## Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12 Singapore 737856 Tel: Fax: Email:

## INSURER: AIG ASIA PACIFIC INSURANCE PTE LTD

**PARTICULARS OF CLAIM** 

Claim Type: TP Ref. No: YTMG/TP/2111/011

Policy No: 5122879337 Date of Loss: 22.11.2021

Vehicle Reg. No.: SNA7808U Driveable? no

Driver Age: 29/03/1952 Third Party Vehicle No.: SLL1171C Any Injuries? Third Party Vehicle No.: 93848999

Insured/Claimant: GOH PENG SOON Driver: GOH PENG SOON

**PARTS MODEL** 

Make/Model: Honda, Shuttle GK8 Vehicle Reg. Date: Vehicle Colour: Engine Number: Odometer:

Total Loss? Est. Duration of Repair(Day)

**DESCRIPTION OF ACCIDENT/LOSS** 

Description of Accident/loss REFER TO GIA REPORT

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS		Amount
Parts		9,096.58
Miscellaneous Items		750.00
Labour		1,190.00
Paintwork Labour		950.00
Towing		0.00
	Gross Total(S\$):	11,986.58
	GST 7.00%(S\$):	839.06
	Nett Amount(S\$):	12.825.64

This claim is handled by: Tee Shu yi

## REPAIR DETAILS

Estima	ites On Pa	arts			
No.	Qty	Particulars	Amount	%Disc	After
				_	Disc
1	1	REAR BUMPER	1,900.20	-20.00	1,520.16
2	1	REAR BUMPER SIDE RETAINER RH	30.10	-20.00	24.08
3	1	REAR BUMPER SIDE RETAINER LH	30.10	-20.00	24.08
4	1	REAR BUMPER TOW COVER	25.40	-20.00	20.32
5	1	REAR BUMPER REFLECTOR RH	64.60	-20.00	51.68
6	1	REAR BUMPER REFLECTOR LH	64.60	-20.00	51.68
7	1	REAR TAILGATE	2,200.60	-20.00	1,760.48
8	1	REAR TAILGATE LAMP RH	580.10	-20.00	464.08
9	1	REAR TAILGATE LAMP LH	580.10	-20.00	464.08
10	1	REAR TAILGATE INNER BOARD	438.10	-20.00	350.48
11	1	REAR TAILGATE RUBBER	140.60	-20.00	112.48
12	1	REAR TAILGATE LOCK	287.10	-20.00	229.68
13	1	REAR BUMPER REINFORCEMENT	210.50	-20.00	168.40
14	1	REAR END PANEL	468.20	-20.00	374.56
15	1	REAR BUMPER BRACKET RH	56.20	-20.00	44.96
16	1	REAR BUMPER BRACKET LH	56.20	-20.00	44.96
17	1	REAR BUMPER UNDERCOVER	100.20	-20.00	80.16
18	1	REAR TAILGATE HINGE RH	59.60	-20.00	47.68
19	1	REAR TAILGATE HINGE LH	59.60	-15.00	50.66
20	1	REAR TAILGATE DAMPER RH	186.70	-20.00	149.36
21	1	REAR TAILGATE DAMPER LH	196.70	-20.00	157.36
22	1	REAR TAILLAMP RH	540.80	-20.00	432.64
23	1	REAR TAILLAMP LH	540.80	-20.00	432.64
24	1	REAR SPARE TYRE PANEL	1,901.50	-20.00	1,521.20
25	1	REAR SPARE TYRE COMPARTMENT BOX	459.80	-20.00	367.84
26	1	REAR END PANEL TOP CHROME	188.60	-20.00	150.88

	<b>Total Parts (</b>	S\$)	9,096.58
--	----------------------	------	----------

Estimates of Miscellaneous Items					
No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS	40.00	0.00	40.00
2	1	REAR END PANEL TOP GARNISH CLIPS	40.00	0.00	40.00
3	1	REAR WINDSCREEN GLASS SEALANT	80.00	0.00	80.00
4	1	REAR REVERSE CAMERA	350.00	0.00	350.00
5	1	REAR TAILGATE INNER BOARD CLIPS	40.00	0.00	40.00
6	1	REAR BUMPER SENSOR	200.00	0.00	200.00

Sub Total (S\$)	750.00
SUD TOTAL (SS)	/ 50.00

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00
3	1	To Transfer Rear Tailgate.	80.00	0.00	80.00
4	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00
5	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace	30.00	0.00	30.00

No.	Qty	Particulars	Amount	%Disc	After Disc
		Damaged Parts.			
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	0.00	800.00

<b>Gross Labour Cost (S\$)</b>	1,190.00
0.000 = 0.000 (04)	

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	100.00	0.00	100.00
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	750.00	0.00	750.00
3	1	To Carry-Out Body Cavity Preservation.	100.00	0.00	100.00
		Gross Labou	r Cost (S\$)		950.00

## < END OF ESTIMATES >