

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER <i>de</i>	1,900.20	-20.00	1,520.16 ✓
2	1	REAR BUMPER SIDE RETAINER RH <i>Xnn</i>	30.10	-20.00	24.08 X
3	1	REAR BUMPER SIDE RETAINER LH <i>Xnn</i>	30.10	-20.00	24.08 X
4	1	REAR BUMPER TOW COVER <i>Xnn 2 Xnn</i>	25.40	-20.00	20.32 X
5	1	REAR BUMPER REFLECTOR RH <i>Xnn</i>	64.60	-20.00	51.68 X
6	1	REAR BUMPER REFLECTOR LH <i>Xnn</i>	64.60	-20.00	51.68 X
7	1	REAR TAILGATE <i>bt</i>	2,200.60	-20.00	1,760.48 ✓
8	1	REAR TAILGATE LAMP RH <i>Xnn</i>	580.10	-20.00	464.08 X
9	1	REAR TAILGATE LAMP LH <i>Xnn</i>	580.10	-20.00	464.08 X
10	1	REAR TAILGATE INNER BOARD <i>? Xnn</i>	438.10	-20.00	350.48 X
11	1	REAR TAILGATE RUBBER <i>na</i>	140.60	-20.00	112.48 ✓
12	1	REAR TAILGATE LOCK <i>Xnn</i>	287.10	-20.00	229.68 X
13	1	REAR BUMPER REINFORCEMENT <i>Xnn</i>	210.50	-20.00	168.40 X
14	1	REAR END PANEL <i>bt photo</i>	468.20	-20.00	374.56 ✓
15	1	REAR BUMPER BRACKET RH <i>Xnn</i>	56.20	-20.00	44.96 X
16	1	REAR BUMPER BRACKET LH <i>? Xnn</i>	56.20	-20.00	44.96 X
17	1	REAR BUMPER UNDERCOVER <i>? Xnn</i>	100.20	-20.00	80.16 X
18	1	REAR TAILGATE HINGE RH <i>Xnn</i>	59.60	-20.00	47.68 X
19	1	REAR TAILGATE HINGE LH <i>Xnn</i>	59.60	-15.00	50.66 X
20	1	REAR TAILGATE DAMPER RH <i>Xnn</i>	186.70	-20.00	149.36 X
21	1	REAR TAILGATE DAMPER LH <i>Xnn</i>	196.70	-20.00	157.36 X
22	1	REAR TAILLAMP RH <i>Xnn</i>	540.80	-20.00	432.64 X
23	1	REAR TAILLAMP LH <i>Xnn</i>	540.80	-20.00	432.64 X
24	1	REAR SPARE TYRE PANEL <i>Xnn</i>	1,901.50	-20.00	1,521.20 X
25	1	REAR SPARE TYRE COMPARTMENT BOX <i>Xnn</i>	459.80	-20.00	367.84 X
26	1	REAR END PANEL TOP CHROME <i>CX (Bumper)</i>	188.60	-20.00	150.88 ✓

Total Parts (\$\$) 9,096.58

3918.56

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS <i>na</i>	40.00	0.00	40.00 <i>30</i>
2	1	REAR END PANEL TOP GARNISH CLIPS <i>na</i>	40.00	0.00	40.00 <i>30</i>
3	1	REAR WINDSCREEN GLASS SEALANT <i>na</i>	80.00	0.00	80.00 <i>50</i>
4	1	REAR REVERSE CAMERA <i>Xnn</i>	350.00	0.00	350.00 X
5	1	REAR TAILGATE INNER BOARD CLIPS <i>na</i>	40.00	0.00	40.00 ✓
6	1	REAR BUMPER SENSOR <i>? Xnn</i>	200.00	0.00	200.00 <i>? X</i>

Sub Total (\$\$) 750.00

150

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00 <i>60</i>
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 <i>60</i>
3	1	To Transfer Rear Tailgate.	80.00	0.00	80.00 <i>60</i>
4	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00 ✓
5	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace	30.00	0.00	30.00 <i>Xnn</i>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
6	1	Damaged Parts. To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	0.00	800.00 600

Gross Labour Cost (\$\$) 1,190.00

880

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	100.00	0.00	100.00 60
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	750.00	0.00	750.00 600
3	1	To Carry-Out Body Cavity Preservation.	100.00	0.00	100.00

Gross Labour Cost (\$\$) 950.00

660

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068

6 days

4s

30/11/20 @ 1500

Resurvey after repair

P - 3918.56
S/N - 1501.00
L - 9880.00
1660.00
Supp - 168.40
T - 5776.96
20%
4621.56

L/S - \$4,600

Estimate Report
Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

11/29/2021

Mega@Woodlands, 39 Woodlands Close #01-12
Singapore 737856

Tel: Fax: Email:

INSURER : AIG ASIA PACIFIC INSURANCE PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTMG/TP/2111/011
Policy No:	5122879337	Date of Loss:	22.11.2021
Vehicle Reg. No.:	SNA7808U	Driveable?	no
Driver Age:	29/03/1952	Third Party Vehicle No.:	SLL1171C
Any Injuries?	no	Contact No:	93848999
Insured/Claimant:	GOH PENG SOON	Driver:	GOH PENG SOON

PARTS MODEL

Make/Model:	Honda, Shuttle GK8	Vehicle Reg. Date:	
Vehicle Colour:		Engine Number:	
Chassis No:		Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss REFER TO GIA REPORT
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	9,096.58
Miscellaneous Items	750.00
Labour	1,190.00
Paintwork Labour	950.00
Towing	0.00
Gross Total(S\$):	11,986.58
GST 7.00%(S\$):	839.06
Nett Amount(S\$):	12,825.64

This claim is handled by: Tee Shu yi