



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556  
ATTN: CHARLOTTE CHEW

Ref: CS/INC21012104/Utf3e2

Date: 13/01/2022

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKV 6201B	<b>Veh. Inspected</b>	SMW 9664A
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1152639-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	LIM CHAN HENG	<b>Assign Date</b>	30/11/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	B.M.W. 216I GRAN TOURER (A)	<b>c.c</b>	1499
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
<b>Chassis No.</b>	WBA6V120205S51410	<b>Colour</b>	BEIGE
<b>Odometer</b>	31620 KM	<b>Steering</b>	AFFECTED
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/55 R17	MICHELIN	6 mm
<b>L/H Front Tyre</b>	205/55 R17	MICHELIN	6 mm
<b>R/H Rear Tyre</b>	205/55 R17	MICHELIN	6 mm
<b>L/H Rear Tyre</b>	205/55 R17	MICHELIN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  
  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	27/11/2021	<b>Inspect Date / Time</b>	30/11/2021 ( 10:52 AM )
<b>Survey held at</b>	1ST AUTO PRO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**