

ASS. REC. BY:

REF:

CTZ/ 21012113/ke

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

8/12 11 PM @ 2700- Car

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

) \$ - RS. SI

) Extras

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Veh No:

SMG 5692D

Yr Regn:

12, 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pirus

C.C

1797

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

262737

T/Radio:

Insured / Std / NI / NA

Eng/No:

4844

C/No:

ZVW50

6050829

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/RIm / STD A/RIm or

Tyre Size:

F:

Sailun

195/65R15

R:

APlus

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

S

mm

Rear

R/Bal.

6

mm

L/Bal.

S

mm

L/Bal.

6

mm

D.O.A.

26/11/21

D.O.I.

1/12/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

26/11/2021

Owner: LEE THIAM LENG

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8S A - SMG5692D

1pc	rear tailgate "PRIUS" emblem	
1pc	rear tailgate "HYBRID" emblem	
1pc	rear tailgate "TOYOTA" logo	
1pc	rear tailgate outer garnish	741.35
1pc	rear tailgate inner lock	
1pc	rear tailgate inner rubber	
1pc	rear bumper	497.50
2pcs	rear bumper side retainer @\$141.40	
1pc	rear bumper diffuser	
1pc	rear bumper reinforcement	379
1pc	rear bumper towing cover	
1pc	rear end panel	
1pc	rear end panel inner garnish	381.90
1pc	rear end panel sensor	281.50

na	\$	61.75	✓
na	\$	53.75	✓
na	\$	61.10	✓
mfcm	\$	741.35	✓
na	\$	381.85	X
na	\$	281.50	X
na	\$	928.35	✓
na	\$	282.80	X
na	\$	379.00	✓
na	\$	458.00	✓
na	\$	61.00	X
R	\$	970.25	X
mfcm	\$	381.90	✓
cm	\$	281.50	✓

less 25%

\$ 5,324.10
\$ 1,331.03
\$ 3,993.08

1set	rear parking sensor	
1set	rear number plate & casing	

scx s.nett \$ 280.00 2005n
s.nett \$ 50.00 455n

tuffkote
wiring
spray painting
labour charges
Total

na \$ 80.00 X
\$ 80.00 15h
\$ 1,000.00 600l
\$ 1,000.00 400l
\$ 6,433.08



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: