

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

26/11/2021

Owner: LEE THIAM LENG

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8S A - SMG5692D

1pc	rear tailgate "PRIUS" emblem	\$ 61.75
1pc	rear tailgate "HYBRID" emblem	\$ 53.75
1pc	rear tailgate "TOYOTA" logo	\$ 61.10
1pc	rear tailgate outer garnish	\$ 741.35
1pc	rear tailgate inner lock	\$ 381.85
1pc	rear tailgate inner rubber	\$ 281.50
1pc	rear bumper	\$ 928.35
2pcs	rear bumper side retainer @\$141.40	\$ 282.80
1pc	rear bumper diffuser	\$ 379.00
1pc	rear bumper reinforcement	\$ 458.00
1pc	rear bumper towing cover	\$ 61.00
1pc	rear end panel	\$ 970.25
1pc	rear end panel inner garnish	\$ 381.90
1pc	rear end panel sensor	\$ 281.50
		\$ 5,324.10
less 25%		
		\$ 1,331.03
		\$ 3,993.08

1set rear parking sensor s.nett \$ 280.00

tuffkote	\$ 80.00
wiring	\$ 80.00
spray painting	\$ 1,000.00
labour charges	\$ 1,000.00
Total	
	\$ 6,433.08

