

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMZ2799A**LAD2111-010***Not Notified
Returning B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

29 NOV 2021**SMZ2799A**

JTDKB3FU803091614

TOYOTA

PRIUS GEN 4

07/11/2021

AIG.

20/04/2021

PART		LIST	
1	COVER, REAR BUMPER	\$	485.60 —
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	332.70 7
1	COVER, REAR BUMPER, LOWER	\$	22.00 —
1	GUARD, REAR BUMPER, CENTER	\$	374.50 —
1	RETAINER, REAR BUMPER SIDE, LH	\$	132.60 X
1	RETAINER, REAR BUMPER SIDE, RH	\$	132.60 X
1	COVER, DECK TRIM, REAR	\$	126.70 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	651.00 X
TOTAL		\$	2,257.70
25%		\$	564.43
		\$	1,693.28

Special Nett

1SET PARKING AID	\$	700.00 X
1SET REAR BUMPER CLIP	\$	95.00 505M
1SET REAR BUMPER RETAINER CLIP	\$	85.00 X
1 END PANEL TRIM CLIP	\$	65.00 X
1 REAR NUMBER PLATE WITH MOULDING	\$	200.00 X
TOTAL	\$	1,145.00

TOTAL PARTS \$ 2,838.28**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Trans-cab Auto Services Pte Ltd**LAD2111-010**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMZ2799A

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	2001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn 180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn 250.00	X
Towing Fees	\$	nn 150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	2201
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd**LAD2111-010**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMZ2799A

To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	220.00	X
To replace, refix and top up coolant for radiator	\$	170.00	X
To lift-up / out engine with gear box and refit.	\$	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	380.00	X
TOTAL	\$	10,290.00	
Over All Total	\$	13,128.28	

(PART-BY-PART) Repair Days**25 DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: