



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI21012117/Tny3e2 Date: 11/10/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLK 807P	Veh. Inspected	SDM 7393D
Policy No.		Coverage (\$)	0.00
Claim No.	C10012656/KY	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	30/11/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	MR053REH104511823	Colour	GREY
Odometer	102883 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	6 mm
L/H Front Tyre	205/55 R16	MICHELIN	6 mm
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/11/2021	Inspection Date	06/12/2021
Survey held at	TSL AUTO GARAGE 4 JOO CHIAT ROAD, #12-1171, SINGAPORE 420004		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	