

ASS. RPT. BY: Steve 1 15277 CS/SMR21012121/Euf3

ASSIGNMENT

Front: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 TO INSPECT VEHICLE NO: \_\_\_\_\_  
 at Workshop no: \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_  
 (Client's Record)  
 Make of Vch: \_\_\_\_\_  
 (Policy Condition)  
 Remarks: The vehicle exhibited the  
 repair at the time of inspection.  
 Det. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? Yes or No  
 SIA / PR Sect: \_\_\_\_\_ Consistent? Yes or No  
 Est. Repair: \_\_\_\_\_ days Rep. Yes or No  
 Cum Sum: \_\_\_\_\_ % 3 Vol. Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN/OUT

Vch No: SGT 2620J Yr Regn: 15/2/17  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Hyundai Elantra C.B. 1591  
 Colour: Silver A/O: Insured / Stolen /  
 Sp. Reading: 829.01 Y/Ratio: Insured / Stolen /  
 Eng/No: \_\_\_\_\_  
 O/No: KMHD841CMH4332467  
 Gen. Cond: Good / Poor / Poor / Bump  
 Steering: Locked / Jammed / Locked / Burnt or  
 Brake: Inter / Jammed / Locked / Burnt or  
 Mod: III / III / III / III or  
 Tyre Size: P1 225/45ZR17  
R1 \_\_\_\_\_  
 BY/DUN/EXNOVA/GY/FS/LIZA/MIG/OHTSU/PIA/SUMI/  
 TOYO/YOKO or \_\_\_\_\_  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Wal: 4 mm R/Wal: 4 mm  
 U/Wal: 4 mm U/Wal: 4 mm  
 D.O.A. 26/11/17 Mova  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Front / Rear / O/S / H/S / U/C / Reqd or  
 The U/C / SH/SH/SH frame / Body structure affected due to collision



Date/Time	Action/Instruction
	MV = 55K
	RV = 38,978
	NV = 16,079
	limit repair 16K

Method, File, Report:  Prelim. Report  Final Report  
 Date/Time, File, Report: \_\_\_\_\_  
 Days of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  Site Insp (\$) \_\_\_\_\_  
 Interview (\$) \_\_\_\_\_  
 Tech. Invo (\$) \_\_\_\_\_  
 Vch. Invo (\$) \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transport: \_\_\_\_\_  
 S.P.S. (\$): \_\_\_\_\_  
 Fuel: \_\_\_\_\_  
 Other: \_\_\_\_\_  
 TOTAL: \_\_\_\_\_

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-008864-2

# Estimate

29/11/2021

**MS FIRST CAPITAL INSURANCE LIMITED**  
36 Robinson Road  
#16-01 City House  
Singapore 068877.

Attention :- XA026

Page # :- 1  
Veh # :- SGT2620J  
Veh Model :- HYUNDAI AVANTE  
Estimate# :- CK422579  
Claim # :-  
ACC. Date :- 26/11/21  
Terms :- C.O.D Days  
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
<b>LIST ITEMS :</b>				
1.	REAR BOOT / <i>DD</i>	1	1,782.00	1,782.00
2.	REAR BOOT LOGO - <i>nec</i>	1	58.00	58.00
3.	REAR BOOT EMBLEM "ELANTRA" - <i>nec</i>	1	59.00	59.00
4.	REAR BOOT EMBLEM "ELITE" - <i>nec</i>	1	59.00	59.00
5.	REAR BOOT LOCK	1	146.00	146.00
6.	REAR BOOT CATCH	1	39.00	39.00
7.	REAR BOOT RUBBER	1	159.00	159.00
8.	REAR BOOT HINGE L+R	2	105.00	210.00
9.	REAR BOOT NUMBER PLATE LAMP	2	30.00	60.00
10.	REAR BOOT PUSH BUTTOM X	1	99.00	99.00
11.	REAR BOOT LAMP L+R	2	664.00	1,328.00
12.	REAR LAMP L+R	2	876.00	1,752.00
13.	REAR LAMP CLIPS L+R x (LH) - BR (RH) ?	2	5.00	10.00
14.	REAR LAMP PANEL L+R	2	193.00	386.00
15.	REAR WINDSCREEN MOULDING X	1	175.00	175.00
16.	REAR FENDER LH x R	1	1,892.00	1,892.00
17.	REAR FENDER INNER TRIM LH X	1	280.00	280.00
18.	REAR END PANEL - <i>DD</i>	1	549.00	549.00
19.	REAR END PANEL TRIM	1	95.00	95.00
20.	REAR FLOOR PANEL - <i>DD</i> (photo)	1	699.00	699.00
21.	REAR FLOOR PANEL BOARD	1	276.00	276.00
22.	REAR SPARE TYRE SCREW	1	29.00	29.00
23.	REAR BUMPER - BR	1	549.00	549.00
24.	REAR BUMPER SPONGE X	1	40.00	40.00
25.	REAR BUMPER REINFORCEMENT - <i>DD</i>	1	295.00	295.00
26.	REAR BUMPER LOWER (split) - BR	1	215.00	215.00
27.	REAR BUMPER LOWER BRACKET - <i>DD</i>	3	20.00	60.00
28.	REAR BUMPER SIDE BRACKET L+R - BR	2	45.00	90.00
29.	REAR BUMPER RETAINER L+R X	2	48.00	96.00
30.	REAR BUMPER REFLECTOR L+R - BR	2	85.00	170.00
31.	REAR BUMPER CLIPS - <i>nec</i>	10	3.90	39.00
32.	REAR BUMPER SIDE SHIELD L+R X	2	65.00	130.00
33.	REAR BUMPER UNDER COVER LH - CRU	1	480.00	480.00
34.	REAR KEYLESS SENSOR	1	195.00	195.00
35.	BONNET - <i>DD</i>	1	1,970.00	1,970.00
36.	BONNET RUBBER X	1	39.00	39.00
37.	BONNET LOCK X	1	129.00	129.00
38.	BONNET HINGE L+R X	2	49.00	98.00
39.	FRONT GRILLE - BR	1	1,214.00	1,214.00
40.	FRONT GRILLE LOGO - BR	1	35.00	35.00
41.	FRONT GRILLE TOP COVER - BR	1	95.00	95.00
42.	FRONT GRILLE CLIPS - <i>nec</i>	10	3.50	35.00
43.	HEADLAMP L+R - BR	2	1,756.00	3,512.00
44.	HEADLAMP BRACKET	2	44.00	88.00
45.	HEADLAMP CLIPS L+R	2	5.00	10.00
46.	SUPPORT PANEL - BR	1	949.00	949.00
47.	SUPPORT PANEL SIDE GARNISH L+R (LH) - CRU	2	58.00	116.00
48.	SUPPORT PANEL SIDE GARNISH CLIPS - <i>nec</i>	8	3.50	28.00
49.	FRONT BUMPER - BR	1	547.00	547.00
50.	FRONT BUMPER FOG LIGHT LH	1	265.00	265.00
51.	FRONT BUMPER FOG LIGHT COVER LH - LUT	1	115.00	115.00

**Main Office:**

 Mova Building  
 No. 22, Jalan Kilang,  
 Singapore 159419  
 Tel: (65) 6476 3333  
 Fax: (65) 6271 5891  
 www.mova.com.sg

**Workshop Dept:**

 Block 1008,  
 Bukit Merah Lane 3,  
 #01-04/06/08/04  
 Singapore 159722

 Tel: (65) 6272 3892  
 Fax: (65) 6270 8314

 Co. Reg. 198904033G  
 GST Reg. M2-0088864-2

# Estimate

29/11/2021

**MS FIRST CAPITAL INSURANCE LIMITED**  
 36 Robinson Road  
 #16-01 City House  
 Singapore 068877.

Attention :- XA026

Page # :- 1 142980

Veh # :- SGT2620J

Veh Model :- HYUNDAI AVANTE

Estimate# :- CK422579

Claim # :-

ACC. Date :- 26/11/21

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
52.	FRONT BUMPER DAY RUNNING LIGHT	1 PC	174.00	174.00
53.	FRONT BUMPER SPONGE - BR	1 PC	140.00	140.00
54.	FRONT BUMPER REINFORCEMENT - BR	1 PC	695.00	695.00
55.	FRONT BUMPER INNER BRACKET L+R - BR	2 PC	38.00	76.00
56.	FRONT BUMPER INNER BRACKET RIVET - BR	8 PC	3.50	28.00
57.	FRONT BUMPER RETAINER L+R - BR	2 PC	38.00	76.00
58.	FRONT BUMPER CLIPS - NK	10 PC	3.50	35.00
59.	FRONT BUMPER NUMBER PLATE GARNISH - BR	1 PC	50.00	50.00
60.	A/C CONDENSER	1 PC	1,132.00	1,132.00
61.	RADIATOR	1 PC	570.00	570.00
62.	AIR DUCT	1 PC	96.00	96.00
63.	AIR RESONATOR	1 PC	98.00	98.00
64.	FRONT FENDER L+R - REPAIR X R	2 PC		
65.	FRONT FENDER RH - REPAIR X R	1 PC		
66.	REAR CHASSIS MEMBER L+R - REPAIR X R	2 PC		
	LIST TOTAL S\$			24,916.00
	20% DISCOUNT S\$			-4,983.20
				19,932.80
<b>SPECIAL NET ITEMS :</b>				
1.	REAR BOOT TOP GARNISH (SPOILER) - CRN	1 PC	600.00	600.00
2.	REAR WINDSCREEN SEALANT X	1 PC	80.00	80.00
3.	REAR BUMPER LOWER SPOILER - BR	1 PC	850.00	850.00
4.	REAR BUMPER SENSOR - BR	1 PC	250.00	250.00
5.	FRONT BUMPER LOWER SPOILER - BR	1 PC	850.00	850.00
6.	FRONT NUMBER PLATE - BT	1 PC	40.00	40.00
	SPECIAL NET TOTAL S\$			2,670.00
<b>LABOUR :</b>				
TOWING CHARGE				
TO CUT & WELD REAR FLOOR PANEL, REAR FENDER LH, REAR END PANEL. TO REPAIR FRONT FENDER L+R, REAR FENDER RH, REAR CHASSIS MEMBER L+R TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS				
			1700	1,800.00
TO SPRAY AFFECTED AREAS				
			1700	1,800.00
TO REMOVE & REFIX W/S GLASS				
			X	180.00
TO REMOVE & REFIX LAGGAGE COMPARTMENT SIDE GARNISH, SIDE TRIM BOARD, CARPET & OTHER ATTACHMENT PARTS				
			80	100.00
TO REMOVE & REFIX FUEL TANK & OTHER ATTACHMENT PARTS				
			X	60.00

# Estimate

29/11/2021

**MS FIRST CAPITAL INSURANCE LIMITED**  
36 Robinson Road  
#16-01 City House  
Singapore 068877.

Attention :- XA026

Page # :- 1 142980  
Veh # :- SGT2620J  
Veh Model :- HYUNDAI AVANTE  
Estimate# :- CK422579  
Claim # :-  
ACC. Date :- 26/11/21  
Terms :- C.O.D Days  
Remarks :-

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 150419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/04  
Singapore 159722  
Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 138904033G  
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	TO REMOVE & REFIX EXHAUST BOX, EXHAUST PIPE			40.00 ✓
	TO REMOVE & REFIX A/C CONDENSER ELECTRIC FAN VACUUM & REFILLING GAS			120 150.00
	TO CHECK WIRING & FOCUS HEAD LIGHT FOR FUNCTION			30 80.00
	TO CHECK BODY STRUCTURE & CHASSIS ALIGNMENT			7 350.00
	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE			30 60.00
	TO RUST PROOF AFFECTED AREAS			\$49 180.00
	LABOUR TOTAL S\$			4,800.00

E. & O.E

*[Handwritten Signature]*

NON-TAX AMOUNT S	
AMOUNT S\$	27,402.80
GST @ 7 %	1,918.20
<b>AMOUNT DUE S\$</b>	<b>29,321.00</b>

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

*Steve (LKK)*  
*30/11/21, 4.00pm*

*Nil R*  
*L/S*  
*My AL sy*  
*18 dya*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date: