

DING AUTO PTE LTD

Blk 176 #04-06

Sin Ming Drive (Sin Ming Autocare)

Singapore 575721

Tel: 83636141

Fax: 6452 0614

Vehicle:	SFQ18P
Model:	MERCEDES BENZ GLC300 COUPE AMG-HYBRID
Chassis:	W1N2533842F967208

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYOR MARKING
1	FRONT BUMPER <i>Pu</i>	1	\$ 1,692.00	10%	\$ 1,522.80	X
2	FRONT BUMPER LOWER GRILLE <i>Pu</i>	1	\$ 550.00	10%	\$ 495.00	X
3	FRONT BUMPER LOWER LIP GARNISH <i>Pu</i>	1	\$ 547.00	10%	\$ 492.30	✓
4	BUMPER SIDE LOWER GARNISH RHS <i>Pu</i>	1	\$ 115.00	10%	\$ 103.50	X
5	BUMPER SIDE LOWER GARNISH LHS <i>Pu</i>	1	\$ 115.00	10%	\$ 103.50	X
TOTAL :					\$ 2,717.10	

*Not Washed
Reary After Rain
Today*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

