

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

26/11/2021

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SKX572J

Veh Model :- MAZDA 3

Estimate# :- CK422574

Claim # :- TP/CK142960

ACC. Date :- 24/11/21

Terms :- C.O.D Days

Remarks :- MFF 25 NOV 2015 (2015)

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	BOOT LID	1 PC	1,004.00	1,004.00
2.	BOOTLID LOGO	1 PC	77.00	77.00
3.	BOOTLID EMBLEM - MAZDA 3	1 PC	55.00	55.00
4.	BOOTLID EMBLEM - SKYACTIVE	1 PC	66.00	66.00
5.	BOOTLID LAMP LH	1 PC	275.00	275.00
6.	BOOTLID HINGE LH & RH	2 PC	158.00	316.00
7.	BOOTLID LOCK	1 PC	186.00	186.00
8.	BOOTLID RUBBER	1 PC	135.00	135.00
9.	TAILLAMP LH	1 PC	534.00	534.00
10.	REAR BUMPER	1 PC	1,127.00	1,127.00
11.	REVERSE SENSOR LH	1 PC	193.00	193.00
12.	REAR BUMPER TOW COVER LH	1 PC	28.00	28.00
13.	REAR BUMPER REFLECTOR LH	1 PC	55.00	55.00
14.	REAR BUMPER CLIPS	10 PC	5.00	50.00
15.	REAR BUMPER SIDE RETAINER RH & LH	2 PC	38.00	76.00
16.	REAR BUMPER REINFORCEMENT	1 PC	563.00	563.00
17.	END PANEL TOP GARNISH	1 PC	99.00	99.00
18.	END PANEL	1 PC	530.00	530.00
19.	ANTENNA SENSOR	1 PC	143.00	143.00
20.	SPARE TYRE TOP BOARD - CHECK	1 PC		
21.	TOOL SPONGE LH - CHECK	1 PC		
22.	SPARE TYRE PANEL - REPAIR	1 PC		
23.	REAR CHASSIS LH - REPAIR	1 PC		
24.	REAR FENDER LH - REPAIR	1 PC		
25.	TAILLAMP PANEL LH - REPAIR	1 PC		

LIST TOTAL S\$

20% DISCOUNT S\$

5,512.00

-1,102.40

4,409.60

SPECIAL NET ITEMS :

1. REAR NUMBER PLATE

SPECIAL NET TOTAL S\$

1 PC

40.00

40.00

40.00

LABOUR :

TO INSPECT REAR LIGHTING MECHANISM & CHECK WIRING

TO INSTALL REVERSE SENSOR & DIAGNOSE FUNCTION

TO CUT OFF END PANEL, TO KNOCK & STRAIGHTEN ON REAR FENDER LH, TAILLAMP PANEL LH, SPARE TYRE PANEL & CHASSIS MEMBER LH, TO REMOVE & REPLACE DAMAGED ITEMS, REALIGN CONNECTION

TO REMOVE & REFIT REAR COMPARTMENT & FITTING

TO APPLY BODY JOINT SEALANT ON CUTTING AREA

30 80.00

30 80.00

700 500 900.00

50 80.00

30 100.00

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

26/11/2021

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 142960
Veh # :- SKX572J
Veh Model :- MAZDA 3
Estimate# :- CK422574
Claim # :-
ACC. Date :- 24/11/21
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	TO RUST PROOF ON REPAIR AREAS			30 100.00
	TO REMOVE & ALIGN REAR EXHAUST MUFFLER (photo)			80.00 X
	TO SPRAY PAINT ON REPAIRED AREAS			800 900.00
	LABOUR TOTAL S\$			2,320.00

L/S - 4484-80
= 4500
1670
= 5606

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

6,769.60

GST @ 7 %

473.87

AMOUNT DUE S\$

7,243.47

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Jaclyn

Steve CLKKJ
30/11/21, 12.30pm

ML AL
L/S
My AL sy
5 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: