

08/11/13) wef
ASS. REC. BY: Marcus

REF:

CC4/A1921012304193

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Colour

Sp Reading

Eng/No.

C/No

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM / I

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) _ S + RS. _ SI

) Photos

) Others

TOTAL

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

AlG

Owner : Chai Kian Wei (98377387)

Accident Date : 12-Oct-21

Vehicle No : JAS1578

Vehicle Model : Honda PCX150

Estimated Repair Costs

Qty	Description <u>List Items</u>		Amount S(\$)
1	Front fork assy R	not attached	\$ 980.00 X
1	Front rim	new	\$ 355.00 X
1	Front brake disc	11/1/21	\$ 198.00 X
1	Front rim shaft	2/5 #3000	\$ 58.00 X
1	Front rim bearing	4 days	\$ 280.00 X
1	Headlamp LED	change battery	\$ 960.00 /
1	Meter cover		\$ 135.00 /
1	Side mirror	new	\$ 180.00 /
1	Handle bar	new	\$ 135.00 /
1	Handle bar balancer - 1 set		\$ 80.00 /
1	Hand grip - 1 set		\$ 60.00 X
2	Brake lever	new	\$ 104.00 /
2	Footstep panel	new	\$ 310.00 /
1	Main stand	new	\$ 175.00 X
1	Side stand	new	\$ 105.00 /
1	Exhaust assy	new	\$ 680.00 X
1	Exhaust protector	new	\$ 185.00 X
1	Rear lamp assy	new	\$ 380.00 X
1	Fairing cover (1 set)	new	\$ 1,150.00 /
			\$ 6,510.00
		Less 10%	\$ 651.00
			\$ 5,859.00

Special Net Items

2	Fork oils	new	\$ 30.00 X
2	Fork oil seal	new	\$ 56.00 X
1	Steering cone (1 set)	new	\$ 120.00 X
1	Number plate (1 set)	new	\$ 38.00 X
1	PCX emblem	new	\$ 80.00 /
			\$ 324.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Chai Kian Wei (98377387)

Accident Date : 12-Oct-21

Vehicle No : JAS1578

Vehicle Model : Honda PCX150

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service (LOD)	\$	40.00 ✓
2	To check wiring and reset headlamp focussing	\$	17 80.00 X
3	To spray painting	\$	450.00 380
4	To provide labour	\$	480.00 300
		\$	1,050.00
Grand Total		\$	7,233.00

Singapore Dollars: Seven Thousand Two Hundred and Thirty-Three only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3290
17
2461
3761