

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorized ESTIMATE

Sompo Insurance Singapore Pte Ltd
 50 Raffles Place
 #05-01/06, Singapore Land Tower,
 Singapore 048623
 Attn: Accident Claims Department

6/11/21
Mohing Ate Kaim
Ed ??

Date: 29/11/2021
 Vehicle No: SJZ1138A
 Veh Make/Model: Honda City 1.5
 YOM: 2009
 Chassis No: MRHGM26709P020421
 Date of Accident: 27/11/2021

No	Qty	Description	Amount S
		Cost Items:-	
1	1	LH Headlamp	\$ <i>CM</i> 210.00 ✓
2	1	LH Headlamp Lower Bracket	\$ <i>Pu</i> 15.00 X
3	1	RH Headlamp	\$ <i>CM</i> 210.00 ✓
4	1	RH Headlamp Lower Bracket	\$ <i>Sm</i> 15.00 X
5	1	Front Bumper	\$ <i>Bu</i> 160.00 ✓
6	2	Front Bumper Side Retainer	\$ <i>clsdiy</i> 70.00 ✓
7	1	Front Grille Base	\$ <i>nu</i> 80.00 —
8	2	Front Grille Outer	\$ <i>CM</i> 100.00 —
9	1	Front Emblem "H"	\$ <i>nu</i> 16.00 —
10	1	Front Foglamp Garnish LH	\$ <i>Sm</i> 20.00 X
11	1	Front Foglamp LH	\$ <i>Sm</i> 120.00 X
12	1	Front Foglamp Garnish RH	\$ <i>Sm</i> 20.00 X
13	1	Front Foglamp RH	\$ <i>Sm</i> 120.00 X
14	1	Front Reinforcement Bar	\$ <i>Bt</i> 75.00 ✓
15	1	Front Radiator Top Rubber / Seal	\$ <i>Sm</i> 10.00 X
16	1	Front Support Panel	\$ <i>R</i> 180.00 X
17	1	Front Bonnet	\$ <i>Bt</i> 260.00 ✓
18	1	Bonnet Hinge	\$ <i>R</i> 22.00 X
19	1	Bonnet Lock	\$ <i>NY</i> 80.00 ✓
20	1	Bonnet Stand	\$ <i>R</i> 90.00 X
21	1	Bonnet Clip	\$ <i>nu</i> 5.00 —
22	1	Towing Cover	\$ <i>Sm</i> 10.00 X
23	1	Front RH Fender	\$ <i>R</i> 95.00 X
24	1	Front RH Fender Shield	\$ <i>Sm</i> 30.00 X
25	1	<i>condensot</i> <i>Bt</i> ✓	<i>270.00</i> ✓
26			
27			
28			
29			
30			
31			
32			
Total - List Item			\$ 2,013.00
Cost + 10%			\$ 201.30
Total			\$ 2,214.30

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06, Singapore Land Tower,
Singapore 048623
Attn: Accident Claims Department

Date : 29/11/2021
Vehicle No : SJZ1138A
Veh Make/Model : Honda City 1.5
YOM : 2009
Chassis No : MRHGM26709P020421
Date of Accident : 27/11/2021

No	Qty	Description	Amount \$
----	-----	-------------	-----------

Page 1/2

		Balance c/f	
		Special Nett Items:-	
1	1 Set	Front Car Plate Number With Holder	\$ <i>B1</i> 45.00 ✓
2	1 Set	Front Bumper Clips	\$ <i>na</i> 30.00 ✓
3	1 Set	Front Radiator Top Garnish Clips	\$ <i>na</i> 30.00 ✓
4	2 Set	Front LH & RH Side Fender Shield Clips	\$ <i>na</i> 50.00 X
5			
		Total - SN Item	\$ 155.00
		Labour Charges:-	
1		Spray painting on all affected area.	\$ 800.00 <i>800</i>
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ <i>500</i> 800.00 <i>500</i>
3		To check wiring system & light.	\$ 80.00 <i>20</i>
4		Top remove/refix aircon condenser, radiator & etc (top up airocn gas & coolant for replace support panel	\$ 180.00 <i>100</i>
6			
7			
8			
		Total - L/C	\$ 1,860.00
		Sub-Total	\$ 4,229.30
		7% GST	\$ 296.05
		Total	\$ 4,525.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Page 2/2