

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21012136/GPA3Q2**Date:** 09/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000618\_01  
**Claimant Vehicle No :** GBJ3726T **Insured Vehicle No :** SMP3374M  
 Date of Loss: 31/08/2021 Nature of Claim: TP Claim No: MFL2021D0003802

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ3726T**  
 Make & Model: NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A) Engine No: YD25046755B  
 Reg. Date: 08/04/2019 (Man. Year: 2019) Chassis No: JN1MC2E26Z0031035  
 Colour: Orange Odometer: 85541 km  
 Engine Capacity: 2488 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15  
 Front Left Side: OHTSU 6 mm Rear Left Side: OHTSU 6 mm  
 Front Right Side: OHTSU 6 mm Rear Right Side: OHTSU 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 673.02            | 673.02            | 0.00              | 0.00          |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 1,535.00          | 1,270.00          | 265.00            | 17.26         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>2,208.02</b>   | <b>1,943.02</b>   | <b>265.00</b>     | <b>12.00</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>1,550.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 2,208.02          | 1,550.00          | 658.02            | 29.80         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 154.56            | 108.50            | 46.06             | 29.80         |
| <b>Nett Amount (S\$)</b>                        | <b>2,362.58</b>   | <b>1,658.50</b>   | <b>704.08</b>     | <b>29.80</b>  |
| <b>+ Loss of Use (3.0 x S\$80.00/day) (S\$)</b> |                   | 240.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 29.00             |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>1,927.50</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>1,900.00</b>   |                   |               |

INSPECTION

Date of Assignment: 30/11/2021  
 Date Inspected: 01/12/2021 Inspected At: Ethoz Group Ltd - Tampines (HQ)  
 22 TAMPINES STREET 92  
 Singapore 528876  
 Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 25 Feb 2022)**Parts:** N/A NISSAN NV350 2.5 PANEL VAN 5AT 5DR (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBJ3726T)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

| No. | Qty | Part No. | Particulars              | Condition | Repairer's   | Amount        |               |
|-----|-----|----------|--------------------------|-----------|--|---------------|---------------|
| 1   | 1   |          | *REAR BUMPER             | Broken    | 667.80 FL  | *667.80 FL    |               |
| 2   | 1   |          | *REAR BUMPER RETAINER LH | Deformed  | 30.00 FL   | *30.00 FL     |               |
| 3   | 10  |          | *BUMPER CLIPS            | Necessary | 50.00 FL   | *50.00 FL     |               |
|     |     |          |                          |           | <b>Sub Total (\$)</b>                                    | <b>747.80</b> | <b>747.80</b> |
|     |     |          |                          |           | <b>- List Item Discount on L Items 10.00/10.00% (\$)</b> | 74.78         | 74.78         |
|     |     |          |                          |           | <b>Total Parts (\$)</b>                                  | <b>673.02</b> | <b>673.02</b> |

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars                                       | Lab.Type | Repairer's                      | Amount          |
|---------------------|---|----------|---------------------------------|-----------------|
| <b>Labour Items</b> |   |          |                                 |                 |
| 1                   | ADVERTISEMENT STICKER FOR REAR BUMPER & LH FENDER | New      | 750.00                          | 650.00          |
| 2                   | LABOUR TO FACILITATE REPAIR                       | New      | 300.00                          | 200.00          |
| 3                   | TO SPRAY PAINT AFFECTED AREA                      | New      | 450.00                          | 400.00          |
| 4                   | TO REMOVE & RECONNECT NECESSARY WIRINGS           | New      | 35.00                           | 20.00           |
|                     |   |          | <b>Gross Labour Cost (\$\$)</b> | <b>1,535.00</b> |
|                     |   |          |                                 | <b>1,270.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >