

*Not Notaries  
11 Day @  
Passing After Rain*




Jayanthan S O Balakrishnan  
BIR 120 Menair Road #09-S7  
Singapore 320120

File No: SH/2021/095/11/010/TP  
Date: 30-November-2021

*Folio*

Estimated cost of repair for vehicle no: SJW2324M Volkswagen Jetta  
Accident involving vehicle no: SJW2324M & SLM1694E on 28.11.2021

Description	Quantity	Cost Price
Front grille	1	\$ CM 580.00 ✓
Front grille emblem	1	\$ CM 95.00 ✓
Front bumper number plate holder	1	\$ R 30.00 ✓
Front bumper sponge	1	\$ 45.00 ?
Front bumper reinforcement	1	\$ 280.00 ?
Rear boot	1	\$ R 820.00 ✓
Rear boot badge "Jetta"	1	\$ R 60.00 ✓
Rear boot emblem	1	\$ R 70.00 ✓
Rear boot inner lock	1	\$ R 120.00 X
Rear boot weatherstrip	1	\$ D 160.00 ✓
RH Rear boot hinge	1	\$ R 65.00 X
LH Rear boot hinge	1	\$ R 65.00 X
LH outer tail lamp	1	\$ G 190.00 X ✓
Rear bumper	1	\$ R 550.00 ✓
Rear bumper lower centre moulding	1	\$ R 390.00 ✓
Rear bumper reinforcement	1	\$ R 320.00 ✓
Rear bumper sponge	1	\$ 80.00 ?
Rear bumper centre bracket	1	\$ 65.00 ?
Rear end panel	1	\$ R 1,380.00 ✓
Rear end panel top trim	1	\$ 125.00 ?
		\$ 5,490.00
	Add 15%	\$ 823.50
		\$ 6,313.50
Front number plate	1	S. nett \$ R 45.00 ✓
Rear parking sensors (1 set)	1	S. nett \$ 260.00 ?
To remove front damaged parts, to reshape and repair head lamp inner panel, front support panel, front bumper, to replace damaged parts and adjust body panel alignment		\$ 450.00 200
To spray paint affected front and inner damaged portion inclusive of preparatory works and material		\$ 420.00 200



To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member, to replace damaged parts and adjust rear body and boot alignment

\$ 850.00 *600*

To spray paint affected rear and inner damaged portion inclusive of preparatory works and material

\$ 950.00 *600*

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality

\$ 150.00 *7*

To perform computer diagnostic on drivetrain, ABS systems, parking system, headlamp systems, and clear fault codes

\$ 100.00 *600*

To apply anti-corrosion Tuff-Kote

\$ 9,538.50

T/Party: Lonpac Insurance Bhd

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: