

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305496331 Via Fax : Email
Date : 30.11.21 Your Insured : SLG4808G
Time of Fax : - Date of Acc : 29.11.21

Attn: Motor Claims Department

ALG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH A 3070C

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Ms. Loke Wei Yieng (yy)	Tel: 62148355 or HP: 86285336
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

lokewy@sparkcarcare.com
Fax no. 65468156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the insurance company.

Thank you.

Yours faithfully



For Vice President
Taxi Accident Repair

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA3070C

Date: 30/11/2021

Make : HYUNDAI

Insurance: AIG

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER FOG LAMP			\$201.50
1	LICENCE LAMP			\$85.30
	SUB TOTAL			\$1,614.25
	LESS 20%			\$322.85
	DISCOUNTED TOTAL			\$1,291.40
1	REAR FENDER ADVERTISEMENT LOGO LH			\$100.00
1	REAR FENDER ADVERTISEMENT LOGO RH			\$100.00
1	REAR BUMPER RUBBER MAT			\$50.00
1	REAR BUMPER REVERSE SENSOR			\$180.00
				\$430.00
	Labour Charge			
	PANEL BEATING			\$700.00
	SPRAY PAINTING CHARGE			\$300.00
	REMOVE/REFIX REVERSE SENSOR			\$60.00
	TOTAL LABOUR			\$1,060.00
	ESTIMATE TOTAL			\$2,781.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4146825

JC NO305496331


STOMER /MS STOMER NO. DRESS (R) (P) COUNT CARD NO.	REGN NO: SHA3070C	MILEAGE
	MAKE: HYUNDAI	FUEL
	MODEL IONIQ(G2)	DATE/TIME IN 30.11.2021 11:50
	YR OF MANU. 14.05.2019	TARGET DATE
	CHASSIS CODE KMHC851CVKU146088	COMPLETION DATE/TIME:

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

JOB DESCRIPTION

Accident Date: 29.11.2021
NATURE: 3P 29.11.2021

3/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR _____

CUSTOMER'S SIGNATURE _____

Acknowledgement Slip
 No. _____
 Vehicle No.: **SHA3070C** **YY**
 Signature/Date _____
 returned to Service Reception upon collection

Exit Pass
 Vehicle No.: **SHA3070C**
 Name of Service Advisor _____ Date _____
 To be kept by Security Guard