

P/P. SAS-KIU.

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA3070C

Make : HYUNDAI

Model : IONIQ(G3)

Date: 30/11/2021

Insurance: **AIG**

MVA: **MS. LOKE YY**

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER <i>X repair</i>			\$459.40
10	REAR BUMPER CLIPS <i>X NN</i>			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY <i>- ee</i>			\$451.25
1	REAR BUMPER REINFORCEMENT <i>?</i>			\$394.80
1	REAR BUMPER FOG LAMP <i>X NN</i>			\$201.50
1	LICENCE LAMP <i>X NN</i>			\$85.30
	<b>SUB TOTAL</b>			\$1,614.25
	<b>LESS 20% DISCOUNTED TOTAL</b>			\$322.85
				<b>\$1,291.40</b>
1	REAR FENDER ADVERTISEMENT LOGO LH <i>= spec</i>			\$100.00
1	REAR FENDER ADVERTISEMENT LOGO RH <i>= spec</i>			\$100.00
1	REAR BUMPER RUBBER MAT <i>X NN</i>			\$50.00
1	REAR BUMPER REVERSE SENSOR <i>X NN</i>			\$180.00
				<b>\$430.00</b>
	<b>Labour Charge</b>			
	PANEL BEATING			\$700.00
	SPRAY PAINTING CHARGE			\$300.00
	REMOVE/REFIX REVERSE SENSOR			\$60.00
	<b>TOTAL LABOUR</b>			<b>\$1,060.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$2,781.40</b>

350  
280  
40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.  
P/P  
before panel photos.  
Eric Qian  
30/11/21 4:30 pm

**MSK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: