

Thuan elhhaib.kw

82235769

26/12/21 1430

P/p Labour only

after repair photo

2 days wp

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

6-Dec-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8344 A

1 pc	Tailgate lower garnish	\$	362.61 Xr
1 pc	Tailgate weatherstrip	\$	276.98 Xsuc
1 pc	Tailgate Striker	\$	36.50 Xsuc
1 pc	Emblem CRDI	\$	29.40 Xsuc
1 pc	Emblem Hyundai logo	\$	29.40 Xsuc
1 pc	Emblem I30	\$	29.40 Xsuc
1 pc	Rear bumper	\$	811.11 Xr
1 pc	Rear bumper sponge	\$	79.20 Xsuc
1 pc	Rear bumper reinforcement	\$	815.64 Xsuc
1 pc	Rear bumper reinforcement centre	\$	79.20 Xsuc
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40 Xsuc
2 pcs	Rear bumper n/s & o/s reflector	\$	107.50 Xsuc

LKK Auto Consultants hence notify the Repairer of the following:

Less 20%

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/NETT

1 set	Rear bumper clips	\$	48.00 /nec
1 set	Reverse sensor	\$	280.00 /cut
1 set	Tailgate stickers	\$	100.00 /nec
1 set	Tailgate lower garnish clips	\$	38.00 /nec
1 set	End panel inner garnish clips	\$	38.00 Xsuc
1 pc	Rear number plate	\$	50.00 Xsuc
	Sundry	\$	50.00 Xsuc
	To dismantle and replace reverse sensor and test system	\$	80.00 Xs
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 Xnn
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, tailgate, etc	\$	650.00 360
	To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel,	\$	600.00 360
	To apply rustproofing on the repaired and replaced panels	\$	120.00 Xnn

Total

\$ 4,443.07

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

F: 1236