

From:
Esti:
Q:

Auto Insure Pte. Ltd.
 6 Marsiling Lane
 Singapore (739145)
 E: claims01@autoinsure.com.sg
 W: www.autoinsure.com.sg
 T: 3157 2626 F: 6368 0081
GST No.: 201437380M

Page No.1**AUTOMOBILE ASSESSMENT REPORT**Our Ref: **SMD1450C (SIEW)**Your Ref: **GBE3025J**Date: **1-Dec-21**

BY EMAIL ONLY
 (claims01@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT**LONPAC INSURANCE BERHAD**

300 Beach Road
 #17-04/07 The Concourse
 Singapore 199555

Assessed Vehicle No : **SMD1450C**
 Car Make and Model : **VOLKSWAGEN CC 2.0 TSI 3584P6**
 Date of Accident : **30-Nov-21**
 Date of Assessment : **1-Dec-21**

We have carried out a physical assessment of SMD1450C at our workshop Auto Insure Pte Ltd sustained damages to the FRONT portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the FRONT portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount	:	P/P	
Adjusted Amount	:	\$	43,155.49
Est. Repair Days	:		12



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Jur Ref: SMD1450C
Your Ref: GBE3025J

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<u>PARTS REPLACEMENT - LIST ITEMS</u>				
1	1	BONNET <i>ht</i>		\$ 2,370.00
2	1	BONNET HINGE RH <i>?</i>		\$ 248.60
3	1	BONNET HINGE LH <i>?</i>		\$ 248.60
4	1	BONNET INSULATION <i>?</i>		\$ 395.20
5	1	BONNET ABSORBER <i>?</i>		\$ 319.40
6	1	BONNET SAFETY LATCH <i>?</i>		\$ 425.00
7	1	BONNET LOCK LOWER <i>?</i>		\$ 460.00
8	1	WIPER GARNISH <i>cm</i>		\$ 695.00
9	1	HEADLAMP RH <i>bro</i>		\$ 3,899.00
10	1	HEADLAMP HID ECU RH <i>cm</i>		\$ 884.30
11	1	HEADLAMP LEVEL CONTROL ECU RH <i>?</i>		\$ 822.50
12	1	HEADLAMP DRL ECU RH <i>?</i>		\$ 735.90
13	1	HEADLAMP CONERING LAMP ECU RH <i>?</i>		\$ 714.50
14	1	HEADLAMP LOWER BRACKET RH <i>cm</i>		\$ 118.00
15	1	HEADLAMP LH <i>cm</i>		\$ 3,899.00
16	1	HEADLAMP LOWER BRACKET LH <i>x</i>		\$ 118.00
17	1	FRONT GRILLE <i>cm</i>		\$ 1,300.00
18	1	FRONT GRILLE BADGE BRACKET <i>cm</i>		\$ 285.90
19	1	FRONT GRILLE EMBLEM R-LINE <i>cm</i>		\$ 214.50
20	1	FRONT GRILLE LOGO <i>cm</i>		\$ 223.00
21	1	FRONT BUMPER <i>cm</i>		\$ 2,157.00
22	1	FRONT BUMPER PARKING SENSOR OUTER SIDE RH <i>ms</i>		\$ 435.00
23	1	FRONT BUMPER PARKING SENSOR INNER RH <i>at</i>		\$ 383.60
24	1	FRONT BUMPER PARKING SENSOR CENTRE RH <i>ms</i>		\$ 390.00
25	1	FRONT BUMPER PARKING SENSOR OUTER SIDE BRACKET RH <i>re</i>		\$ 32.90
26	1	FRONT BUMPER PARKING SENSOR INNER BRACKET RH <i>re</i>		\$ 32.90
27	1	FRONT BUMPER PARKING SENSOR CENTRE BRACKET RH <i>re</i>		\$ 38.50
28	1	FRONT BUMPER PARKING SENSOR OUTER SIDE BRACKET LH <i>re</i>		\$ 32.90
29	1	FRONT BUMPER PARKING SENSOR INNER BRACKET LH <i>re</i>		\$ 32.90
30	1	FRONT BUMPER PARKING SENSOR CENTRE BRACKET LH <i>re</i>		\$ 38.50
31	1	FRONT BUMPER HEADLAMP WASHER COVER RH <i>re</i>		\$ 125.10
32	1	FRONT BUMPER HEADLAMP WASHER JET RH <i>cm</i>		\$ 386.20
33	1	FRONT BUMPER TOWING COVER RH <i>se</i>		\$ 66.90
34	1	FRONT BUMPER LOWER GRILLE <i>cm</i>		\$ 475.00

35	1	FRONT BUMPER LOWER SPOILER <i>con</i>	\$	510.00
36	1	FRONT BUMPER FOG LAMP RH ?	\$	586.70
37	1	FRONT BUMPER FOG LAMP COVER RH <i>sub</i>	\$	261.00
38	1	FRONT BUMPER FOG LAMP TRIM RH <i>sub</i>	\$	195.00
39	1	FRONT BUMPER FOG LAMP TRIM MOULDING OUTER RH <i>new</i>	\$	98.20
40	1	FRONT BUMPER FOG LAMP TRIM MOULDING INNER RH <i>new</i>	\$	98.20
41	1	FRONT BUMPER WIRE HARNESS <i>cut</i>	\$	782.90
42	1	FRONT BUMPER SIDE RETAINER RH <i>con</i>	\$	86.40
43	1	FRONT BUMPER SIDE RETAINER LH <i>X</i>	\$	86.40
44	1	FRONT BUMPER INNER BRACKET RH <i>con</i>	\$	128.00
45	1	FRONT BUMPER INNER BRACKET LH <i>X</i>	\$	128.00
46	1	FRONT FENDER RH <i>bt</i>	\$	1,220.00
47	1	FRONT FENDER BRACKET FRONT RH <i>bt</i>	\$	155.00
48	1	FRONT FENDER INNER SHIELD FRONT RH <i>cut</i>	\$	135.50
49	1	FRONT FENDER INNER SHIELD REAR RH <i>de</i>	\$	218.10
50	1	FRONT FENDER LH <i>R</i>		REPAIR
51	1	FRONT BUMPER CENTRE GUIDE <i>con</i>	\$	247.10
52	1	FRONT BUMPER SPONGE <i>con</i>	\$	261.00
53	1	FRONT BUMPER REINFORCEMENT <i>bt</i>	\$	918.60
54	1	FRONT SUPPORT PANEL <i>con</i>	\$	1,861.00
55	1	FRONT BRACE PANEL ?	\$	269.40
56	1	HORN RH ?	\$	188.90
57	1	HORN BRACKET RH ?	\$	65.20
58	1	WASHER TANK UPPER <i>de</i>	\$	365.00
59	1	WASHER TANK PUMP UPPER <i>con</i>	\$	295.00
60	1	WASHER TANK LOWER <i>de</i>	\$	311.00
61	1	HEADLAMP WASHER PUMP LOWER ?	\$	270.00
62	1	FRONT AIR DUCT ?	\$	211.90
63	1	FRONT AIR DUCT SLIDE REAR ?	\$	142.50
64	1	AIR CON CONDENSER SIDE COVER RH <i>con</i>	\$	92.30
65	1	AIR CON CONDENSER SIDE COVER LH <i>X</i>	\$	92.30
66	1	AIR CON CONDENSER PROTECT GRILLE ?	\$	135.60
67	1	AIR CON CONDENSER ?	\$	1,679.10
68	1	AIR CON DISCHARGE HOSE ?	\$	477.00
69	1	AIR CON SUCTION HOSE ?	\$	495.00
70	1	INTERCOOLER ?	\$	1,299.00
71	1	INTERCOOLER CHARGE AIR PIPE RH ?	\$	338.00
72	1	RADIATOR ?	\$	1,550.50
73	1	RADIATOR UPPER AIR DUCT ?	\$	155.10
74	1	RADIATOR UPPER BRACKET RH ?	\$	95.50
75	1	RADIATOR LOWER BRACKET RH ?	\$	95.50
76	1	RADIATOR FAN COVER ?	\$	520.00
77	1	FRONT CHASSIS RH <i>R</i>		REPAIR
78	1	FRONT CHASSIS LH <i>R</i>		REPAIR
79	1	FRONT WHEEL HOUSE RH <i>R</i>		REPAIR
80	1	FRONT PILLAR RH <i>R</i>		REPAIR

81	1	FRONT PILLAR LH <i>2</i>		
				REPAIR
			SUB TOTAL	\$ 40,124.70
			LESS 10%	\$ 4,012.47
			TOTAL AMOUNT	\$ 36,112.23

Our Ref: **SMD1450C**
Your Ref: **GBE3025J**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	FRONT NUMBER PLATE & HOLDER		\$ 50 80.00
2	1	FRONT BUMPER CLIPS		\$ 30 60.00
3	1	FRONT BUMPER RIVETS		\$ 30 50.00
4	1	AIR CON GAS		\$ 100 120.00
5	1	RADIATOR COOLANT		\$ 60 80.00
6	2	FRONT FENDER INNER SHIELD CLIPS		\$ 30 60.00
			SUB TOTAL	\$ 460.00
			TOTAL PARTS COST	\$ 36,572.23

Our Ref: **SMD1450C**
Your Ref: **GBE3025J**

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TOWING CHARGES <i>receipt?</i>	\$ 100.00
2	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 130/200 1,400.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 60 80.00
3	TO CONDUCT DIGNOSIS FAULT CODE & RESET	\$ 150 180.00
4	TO REMOVE & REFIT AIR CON CONDENSER & RADIATOR	\$ 100 150.00
6	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 1400 1,600.00
7	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 60 80.00
8	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ 30 60.00
9	TO VACUUM, WAXING & CLEAN	\$ X 60.00
10	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ X 50.00
TOTAL BEFORE GST		\$ 40,332.23
GST 7%		\$ 2,823.26
TOTAL (PARTS & LABOUR):		\$ 43,155.49

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a **sum of \$ 43,155.49** for part by part with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

10 days
L/S

01/12/2021
Resurvey before paint