ASS. REC. BY:  REF: C12/	CS/CTI21012150/Kty3
/ IC RACTA	SIGNMENT
From: Date:	
Estimated Cost:	Veh No: SUZ 6233 EYr Regn: O5, 18
OD VIP IWS / TP RES / OD RES / EVA / INV / MY	Micycle / Bus / Van / Lorry / Taxl / Prime Mover /
to inspect Vehicle No:	Make:
at Workshop m/s Opting	Phrs c.c /+YZ
OI .	insured / Std / NI / NA
Insured:	Sp.Reading 303570 T/Radio: Insured / Std / NI / NA Eng/No:
Policy No.	
Claims No.	- EVW 40' 002737
Sum Insured: Excess:	Gen. Cond: Good / Fair / Poor / Burnt
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: Nii / S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F:
Remark: The veh had commenced its N/S O/S	R: 205/60R16
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or
Bal. or Market Value:	Erons Sunwick
IDAC Accident Rport: Consistent? : Yes or No	R/Bal D Rear
	L/Bal. P mm L/Bal. P mm
	DOA 22/11/10
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at D.O.I. 30/11/2021
CA / DEL / DEL	Des. of Damages : Frt / Rear 7 O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OUT	and the second s
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
FINALISE AT LUMP SUM S	3800, 4DAYS
RED: 3887.50; 50%	
-	
Onto The Co. Co.	
	s Of Repair: 4
1) : Final Report Rest	urvey No. of Trip: Survey Fee:
· · · · · · · · · · · · · · · · · · ·	Transportative:
Add Fee:	: Site Insp (\$ )_s - Rssi
	: Interview (\$ ) Facts
Report Format:	Tech Invs (\$ ) Others
Lump Sum / I.B.I: (S	Weekend (\$
	TOTAL

## OPT/MA///ERKZ

OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W

[] /OptimaWerkz

OptimaWerkz

SINGAPORE Not Asthonk

Date:

29/11/2021

Ulling 8

Third Party Insurer:

**CHINA TAIPING** 

Model:

Vehicle No: SLZ6223E

TOYOTA PRIUS HYBIRD ALPHA 1.8S CVT

Third Party Veh No: Date of Accident:

SJU3899A 27/11/2021

Chassis:

ZVW400027337-2017

**Estimator:** 

**TING AN** 

Reg.Year:

2018

Merony Athe Pains

4-5day1

## **ESTIMATE**

	NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	1
	1	REAR TAILGATE	1		\$1,096.00	_
	2	REAR TAILGATE INNER TRIM BOARD	1		\$351.00	X
	3	REAR TAILGATE INNER LOCK	1		<b>P</b> \$425.00	_
	4	REAR TAILGATE WEATHERSTRIPE	1		GA \$238.00	50
	5	REAR TAILGATE "PRIUS CX" EMBLEM	1		Me \$80.00	_
	6	REAR TAILGATE "HYBRID" EMBLEM	1	4 1 -	Ma \$80.00	_
	7	REAR TAILGATE "TOYOTA" EMBLEM	1	10	nn \$80.00	X
	8	REAR WINDSCREEN MOULDING	1		Ma \$180.00	_
	9	REAR TAIL LAMP LH	1		\$691.00	7
	10	REAR TAIL LAMP RH	1		Se \$691.00	x
	11	REAR TAIL LAMP BRACKET LH	1		\$60.00	7
L	12	REAR TAIL LAMP BRACKET RH	1		\$60.00	7
	13	REAR BUMPER	1		Bu \$549.00	_
	14	REAR BUMPER SIDE BRACKET LH	1		Dry \$95.00	_
	15	REAR BUMPER SIDE BRACKET RH	1		Dry \$95.00	_
	16	REAR END PANEL	1		\$696.00	7
Г	17	REAR END PANEL UPPER COVER	1		\$175.00	7
Г	18	REAR FLOOR PANEL TOOLBOX TRAY	1		\$666.00	7
	19	REAR FLOOR PANEL TRAY UPPER BOARD	1		In \$542.00	X
9						• (
	•			SUB TOTAL	\$6,850.00	
				LESS 25%	-\$1,712.50	

NO.	SPECIAL NETT	* Marin	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM BOARD CLIPS	4 a*	1	4 1	Na \$50.00
2	REAR BUMPER CLIPS	1	1		May \$60.00
3	REAR BUMPER REVERSE SENSOR		1		Sep \$300.00
4	REAR END PANEL UPPER COVER CLIPS		1		na \$30.00
5	REAR WINDSCREEN SEALANT		1		Ma \$80.00
6	REAR END PANEL JOINT SEALANT	( 0.5¢%-3	1	ROBERT CONTRACTOR	\$60.00
				S/N TOTAL	\$580.00

\$5,137.50

Head office

6 Kung Chong Road Singap ore 159143 Tet (-65) 6472 1313 | Fax: (-65) 6472 2112

9A Serangoon North Ave 5 Singapore 554500 Tel: (+85) 6484 9919 | Fax (+85) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

PARTS TOTAL





OPTIMA WERKZ PTE LTD Co. Reg. No. 20121245

www.ow.sg

[] /OptimaWerkz

/OntimaWerkz

Date:

29/11/2021

Vehicle No: SLZ6223E

Model:

TOYOTA PRIUS HYBIRD ALPHA 1.8S CVT

Chassis: Reg.Year:

ZVW400027337-2017 2018

Third Party Insurer:

**CHINA TAIPING** 

Third Party Veh No: Date of Accident:

SJU3899A 27/11/2021

Estimator:

**TING AN** 

Surveyor:

**LABOUR CHARGES:** 

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS

\$700.00

& ETC.

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.

\$700.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.

\$150.00 /201

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

\$120.00 601

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00 501

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$120.00

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00 201

**LABOUR TOTAL** 

\$1,970.00

**TING AN** 

TOTAL

\$7,687.50

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office 6 Kung Chong Road Singapore 159143 Tel: (-85) 8472 1313 | Fax: (-85) 8472 2112

9A Serangoon North Ave 5 Singapore 554500 Tel: (+85) 8484 9919 | Fax: (+85) 8481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



SC0921BT0006 / Cheng Hoe Motor Pte Ltd[568047] ENTRY DATE & TIME: 29/11/2021 19:08 (SGT) SUBMITTED BY: LI YAZHU DORLYN VERSION: 1 (29/11/2021 19:08 (SGT))

# **©** SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
   This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
   Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- A. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.

  5. Any false reporting may be referred to the Police for Investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## **ACCIDENT STATEMENT**

Date of Submission 29/11/2021 19:08 (SGT) Date of Accident 27/11/2021 19:40 (SGT) Exact Location of Accident Singapore Additional Location Information **CLEMENCEAU AVE** Country/State of Loss Singapore

## **DETAILS OF OWN VEHICLE**

Vehicle Registration Number **SLZ6223E** 

#### INSURED/POLICYHOLDER

Is company? ..... Yes Name Of Registered Owner KINETIC HOLDINGS PTE LTD Company Reg No ..... 201618392N Email Address support@kinetic-alliance.com Mobile Phone No ..... (Phone) +65-97849075 Alternative Phone No ..... +65-97849075

#### VEHICLE PARTICULARS

Manufacturer ..... Toyota Model ..... Prius Variant ..... Exact purpose for which vehicle was being used at time of accident ..... Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category ..... Private hire Transmission ..... Auto 1797

## INSURANCE COMPANY

Name of Insurance Company ..... China Taiping Insurance (Singapore) Pte. Ltd. Type of Coverage ..... Comprehensive Fleet Policy Policy Number DMHCSNA00005442101 

## DRIVER

Name of Driver

MUHAMMAD ALFIS BIN RASHID S8430951F

Accident report SC0921BT0006

