



E-CARE AUTO SERVICES PTE LTD

51 Ubi Ave 1, #01-29 Paya Ubi Industrial Park Singapore 408933

Tel: +65 68418892 Hotline: +65 97223678

GST Reg. No.: 20102442D

Smx8588m ACR507118894

Part item		TP China.	
1	Front bumper <i>Distorted</i>	1	98/ \$1,890.00
2	Front bumper side retainer <i>Hit New</i>	2	\$115.00 57.50
3	Front bumper lower grille <i>Debond</i>	1	\$320.00 +
4	Front center grille <i>New</i>	1	\$495.00 +
5	Front center grille emblem <i>New</i>	1	\$294.00 +
6	Front headlamp LH <i>Hit</i>	1	2180 \$2,394.00
7	Front headlamp lower bracket LH <i>New</i>	1	\$112.00 +
8	Front fog lamp LH <i>Cracked</i>	1	\$210.00 ✓
9	Front fog lamp cover LH <i>New</i>	1	\$95.00 ✓
10	Front towing cap <i>New</i>	1	\$65.00 +
11	Front reinforcement bar <i>New</i>	1	\$320.00 +
12	Front support panel <i>New</i>	1	\$790.00 +
13	Front support panel top garnish <i>New</i>	1	\$210.00 +
14	Front Fender Inner Shield LH <i>Torn</i>	1	\$160 ✓
15	Air Filter Tank <i>Cracked</i>	1	\$225 ✓
16	Fog Lamp Bracket LH <i>New</i>	1	160. \$280
Front Bumper Sponge. <i>Cracked</i>			\$7,975.00
		Discount 25%	\$1993.75
		TOTAL :	\$5,981.25

Speical Item			
1	Front bumper clips <i>New</i>	1	\$50.00 30
2	Front support panel top ganirhs clips <i>New</i>	1	\$50.00 +
3	Front number plate c/w garnish <i>New</i>	1	\$50.00 +
4	Front support panel seal <i>New</i>	1	\$50.00 +
5	Front center grille clips <i>New</i>	1	\$50.00 +
6	Front fog lamp cover clips <i>New</i>	1	\$50.00 10
			\$300.00
		Parts Total :	\$0.00
		S/N Item :	\$300.00
		TOTAL :	\$300.00



E-CARE AUTO SERVICES PTE LTD

51 Ubi Ave 1, #01-29 Paya Ubi Industrial Park Singapore 408933

Tel: +65 68418892 Hotline: +65 97223678

GST Reg. No.: 20102442D

LABOUR

1	To cut/weld and remove and refit above parts	\$ 400.00
2	To putty, re-spray painting affected areas.	\$ 250.00
3	To rust proof affected areas.	\$ 40.00
4	To conduct digarnotic system.	\$ 200.00
5	To remove and refit front aircond condenser and top up gas,	\$ 150.00
6	To check and rectify wiring.	\$ 30.00
7	To replace front sensor and check.	\$ 100.00

TOTAL : \$ 2,270.00
:
: 8,630.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King
w/s 01/12/21.

0384

total: 4137.62

2/s: 3.3K