



FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01 Suntec Tower 4, Singapore 038986

T: (65) 6727 5700 | F: (65) 6727 5799

Claim No: 1202100001912 Date: 29/04/2021
Repairer: SME MOTOR PTE LTD

REFERENCE

Insured: TNG JIA WEI Policy No: PNPV2019-00001889-02
Date of Loss: 02/04/2021 Nature of Claim: OD
Est. Duration of Repair: 8.0 days

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg. No: SLK1213X
Make & Model: HONDA CITY, 1.5 (A) Reg. Date: 25/01/2017
Engine No: L15Z14114312 Chassis No: MRHGM6660HP000485

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size:
Front Left Side: 0 mm Rear Left Side: 0 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable): Yes Engine Modification: No
Handbrake (Serviceable): Yes Steering (Serviceable): Yes Pre-accident Condition:

COST OF CLAIMS	Repairer's	Our Offer	Difference	Diff %
Parts	11,666.00	9,059.00	2,607.00	22.35
Miscellaneous Items	285.00	165.00	120.00	42.11
Labour	3,460.00	2,010.00	1,450.00	41.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	15,411.00	11,234.00	4,177.00	27.10
- Excess (\$)	0.00	750.00	-750.00	
(S\$)	15,411.00	10,484.00	4,927.00	31.97
+ GST 7.00/7.00% (S\$)	1,078.77	733.88	344.89	31.97
Nett Amount (S\$)	16,489.77	11,217.88	5,271.89	31.97

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT GRILLE		75.00 F	*75.00 F
2	0		*FRT GRILLE OUTER GARNISH		150.00 F	-
3	0		*FRT GRILLE LOGO		25.00 F	-
4	4		*FRT GRILLE CLIP		8.00 F	*8.00 F
5	1		*FRT BUMPER		230.00 F	*230.00 F
6	2		*FRT BUMPER RETAINER		30.00 F	*30.00 F
7	10		*FRT BUMPER CLIP		20.00 F	*20.00 F
8	0		*FRT BUMPER REINFORCEMENT		195.00 F	-
9	2		*FRT BUMPER BEAM (BELOW HEADLAMP)		50.00 F	*50.00 F
10	1		*FRT BUMPER LOWER GRILLE		65.00 F	*65.00 F
11	2		*FOG LAMP		560.00 F	*560.00 F
12	2		*FOG LAMP GARNISH		36.00 F	*36.00 F
13	1		*ENGINE UNDER COVER (FRT)		80.00 F	*80.00 F
14	10		*UNDER COVER CLIP		20.00 F	*20.00 F
15	0		*HEADLAMP		500.00 F	-
16	1		*HEADLAMP SUPPORT PANEL		230.00 F	*230.00 F
17	0		*SUPPORT PANEL TOP GARNISH		30.00 F	-
18	0		*TOP GARNISH CLIP		12.00 F	-
19	1		*AIRCON CONDENSER		360.00 F	*360.00 F
20	1		*RADIATOR		450.00 F	*450.00 F
21	1		*AIRCON MOTOR		175.00 F	*175.00 F
22	1		*AIRCON FAN COWLING		50.00 F	*50.00 F
23	1		*AIRCON FAN BLADE		75.00 F	*75.00 F
24	1		*RADIATOR MOTOR		185.00 F	*185.00 F
25	1		*RADIATOR FAN COWLING		75.00 F	*75.00 F
26	1		*RADIATOR FAN BLADE		60.00 F	*60.00 F
27	0		*RADIATOR SPARE TANK		35.00 F	-
28	0		*WASHER TANK		45.00 F	-
29	0		*ENGINE UNDER COVER REAR SAMPLE		-	-
30	0		*ENGINE MOUNTING RH		125.00 F	-
31	1		*ENGINE MOUNTING LH		120.00 F	*120.00 F
32	0		*REAR ENGINE MOUNTING		95.00 F	-
33	1		*FRT SHOCK ABSORBER LH		125.00 F	*125.00 F
34	1		*FRT KNUCKLE ARM LH		95.00 F	*95.00 F
35	1		*FRT LOWER ARM LH		145.00 F	*145.00 F
36	1		*FRT SPORT RIM LH (ORI)		450.00 F	*450.00 F
37	1		*STEERING AIRBAG		750.00 F	*750.00 F
38	1		*PASSENGER AIRBAG		1,200.00 F	*1,200.00 F
39	1		*DASHBOARD		600.00 F	*600.00 F
40	2		*FRT SAFETY BELT		900.00 F	*900.00 F
41	1		*AIRBAG CONTROL UNIT		680.00 F	*680.00 F
42	2		*AIRBAG SENSOR		150.00 F	*150.00 F
43	1		*CLOCK SPRING SENSOR		220.00 F	*220.00 F
44	0		*FRT BONNET LOCK		95.00 F	-
45	0		*ENGINE OIL SUMP		220.00 F	-
46	0		*GEAR BOX OIL SUMP		195.00 F	-
47	0		*STEERING CROSSMEMBER		350.00 F	-
48	0		*STEERING RACK		495.00 F	-
49	0		*GEARBOX OIL SUMP GASKET		40.00 F	-
Supplementary #1						
50	1		*OIL COOLER		195.00 F	*195.00 F
51	1		*GEARBOX SOLENOID SWITCH		80.00 F	*80.00 F
52	1		*STATOR		360.00 F	*360.00 F
53	2		*LH ENGINE UNDER SIDE COVER		50.00 F	*50.00 F
54	2		*FOG LAMP BULB		20.00 F	*20.00 F
55	1		*FRT LH KNUCKLE BEARING		85.00 F	*85.00 F

F=Franchise part.

Total Parts (S\$)	11,666.00	9,059.00
-------------------	-----------	----------

FWD Singapore Pte. Ltd./SLK1213X/29/04/2021 10:48. Not valid without Reference section.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT LH TYRE	220.00	100.00
2	1	FRT NUMBER PLATE	40.00	40.00
3	1	RADIATOR COOLANT	25.00	25.00
Sub Total (S\$)			285.00	165.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	REMOVE & REFIX FRT UNDERCARRIAGE (WITH CROSSMEMBER)	New	350.00	180.00
4	WHEEL ALIGNMENT	New	80.00	70.00
5	REMOVE & REFIX AIRBAG SYSTEM & SAFETY BELT	New	350.00	200.00
6	REMOVE & REFIX DASHBOARD	New	250.00	150.00
7	REPROGRAMME AIRBAG SYSTEM	New	450.00	150.00
8	REMOVE & REFIX ENGINE MOUNTING AND OIL SUMP	New	150.00	80.00
9	LABOUR CHARGE	New	850.00	660.00
10	SPRAY PAINTING	New	850.00	400.00
Gross Labour Cost (S\$)			3,460.00	2,010.00

FWD Singapore Pte. Ltd./SLK1213X/29/04/2021 10:48. Not valid without Reference section.

< END OF REPORT >