

Figure B-1: Schematic of Incident Site




Figure B-2: Schematic of Incident Site




Figure B-3: Schematic of Incident Site




Figure B-4: Schematic of Incident Site




Figure C-1: Right Side view of MID46356



Figure C-2: Left Side view of MID46356



Figure C-3: Front view of MID46356



Figure C-4: Rear view of MID46356



Figure C-5: Close up Damage on the front of MID46356



C - 1

Figure C-6: Damage on the Rear of GBD161Z.






Figure C-7: Closed up Damage on the Rear of GBD161Z.



## SINGAPORE ARMED FORCES

## STATEMENT OF DRIVER

STATEMENT OF	3SG CHEAH JUN AN DOUGLAS					ALIASES	N.A.		
NRIC NO	TXXXX9711	AGE	19				MALE/FEMALE	MALE	
EMPLOYMENT	NSF	DRIVING LICENCE NO	N.A.				NATIONALITY	SINGAPOREAN	
DIALECT	TEO CHEW	LANGUAGE SPOKEN	ENGLISH				TEL NO	[REDACTED]	
ADDRESS	[REDACTED]								
INTERPRETED BY	N.A.	RANK	N.A.	TIME	N.A.	DATE	N.A.	SIGN	N.A.
RECORDED BY	N.A.	RANK	N.A.	TIME	N.A.	DATE	N.A.	SIGN	N.A.
<p>Around 1330H, we were driving at Choa Chu Kang Drive, outside Mr The Tarik. In front of this vehicle, there was another vehicle turning left into The Tarik carpark. After this vehicle turn into the carpark, it was clear for the vehicle in front of us, and he proceeded to move forward. The vehicle in front of us stop, so we slow down. Afterwards, the vehicle in front of us started moving forward, so we continued moving forward. The vehicle in front of us jam break and stopped abruptly, we break but we couldn't stop in time to stop this incident</p>									
DATE	191021		SIGNATURE OF DRIVER/WITNESS						

STATEMENT OF	CPL LEE HUEY CHENG						ALIASES	N.A.	
NRIC NO	TXXXX094G	AGE	21				MALE/FEMALE	MALE	
EMPLOYMENT	NSF	DRIVING LICENCE NO	SAF/TPT/N/0061/21				NATIONALITY	SINGAPOREAN	
DIALECT	HOKKIEN	LANGUAGE SPOKEN	ENGLISH				TEL NO	[REDACTED]	
ADDRESS	[REDACTED]								
INTERPRETED BY	N.A.	RANK	N.A.	TIME	N.A.	DATE	N.A.	SIGN	N.A.
RECORDED BY	N.A.	RANK	N.A.	TIME	N.A.	DATE	N.A.	SIGN	N.A.
<p>Around 1.30pm we at Choa Chu Kang drive outside Mr The Tarik I have a accident. I have bang to a vehicle car plate is GBD161Z. What happen during the accident is when I was going straight towards back camp there is 2 vehicle infront of me the 1<sup>st</sup> car is turning left towards Mr The Tarik after the first car have turn the 2<sup>nd</sup> car which is GBD161Z he was on the accelerate paddle already then I start accelerating right after I accelerate the vehicle at the front out of sudden he jam break then I immediately jam break but my vehicle have not enough time for the vehicle to react because the distance is very short for me to stop the vehicle on time. Before that I was slowing down already because I know the first vehicle is turning left already that's why I slowed down.</p>									
DATE	191021		SIGNATURE OF DRIVER/WITNESS						



**SINGAPORE  
POLICE FORCE**



J/20211019/7055

1 of 2

**POLICE REPORT (NP299)**

Report No. J/20211019/7055

Police Station Of Origin  
Jurong Division HQ  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No:1800-7910000

Date/Time Report Made 19/10/2021 16:17	Vide Report No.	Station Diary No.
Name Of Informant LEE HUEY CHENG	Address [REDACTED]	
ID Type / ID No. NRIC NO / T [REDACTED] 094G	Contact No. Home/Office: [REDACTED]	Mobile: [REDACTED]
Nationality SINGAPORE CITIZEN	Email Address [REDACTED]	
Occupation Singapore Armed Forces personnel	Sex Male	Age 21
Institution/School Name	Date of Birth 05/04/2000	Race Chinese
Date/Time Of Incident 19/10/2021 01:00 - 19/10/2021 02:30	Location Of Incident Outside Mr teh tarik/ opposite North vale condo	
Brief details.		

Around 1.30 pm we at choa chu kang drive outside Mr teh tarik I have a car accident. I have rear ended a vehicle. The car plate is GBD161Z. I was on the route back to stagmont camp. there were 2 vehicle infront of me. The most front car was turning left towards Mr teh tarik. After the most front car turned left to Mr teh tarik, the vehicle in front of me, car plate GBD161Z, from my perspective, the vehicle brake light was not lit up. While maintaining my vehicle speed, the vehicle did a sudden brake. I immediately step on my brake. The next thing I know was I rear ended the vehicle. I got a vehicle commander with me call DOUGLAS.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 19/10/2021 16:17
Officer In-Charge Of Case:	Classification Of Case:



**SINGAPORE  
POLICE FORCE**



J/20211019/7055

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20211019/7055

Subjects Involved			
Victim			
Person Name	NG AH CHAI		
ID Type	NRIC NO	ID No	S [REDACTED] 218D
Gender	Male	Age	57
Language	Chinese		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 19/10/2021 16:17
Officer In-Charge Of Case:	Classification Of Case: