

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

United Overseas Insurance Ltd
 3 Anson Road
 # 20 - 01 Spring Tower
 Singapore 079909
 Tel : 6222 - 7733
 Fax : 6327 - 3869

OD U01
 Xiao Chen.

Estimate
 DATE : 01.12.2021
 VEH NO : GBL2255G
 MODEL : Citroen Berlingo
 D O A : 22.11.2021
 YR REF : Own Damage

Attn : Motor Claim Dept (Pls arrange vehicle survey)

RE : ESTIMATE FOR ACCIDENT REPAIR GBL2255G (CITROEN BERLINGO)

<u>Item</u>	<u>Descriptions</u>	<u>Qty</u>	<u>Amt</u>
1	Front Bumper <i>Distorted</i>	1	650.00 ✓
2	Front Bumper Clips <i>new</i>	1	40.00 ✓
3	Front Bumper Side Holder - RH <i>Distorted</i>	1	90.00 ✓
4	Front Bumper Towing Cover <i>Missing.</i>	1	25.00 ✓
5	Front Bumper Sponge <i>cracked.</i>	1	160.00 ✓
6	Front Bumper Reinforcement <i>Distorted</i>	1	480.00 ✓
7	Front Bumper Fog Lamp - RH <i>Missing.</i>	1	220.00 ✓ 150.
8	Front Bumper Fog Lamp Cover - RH <i>Missing.</i>	1	80.00 ✓
9	Front Bumper Upper Apron Panel <i>Distorted</i>	1	390.00 ✓
10	Front Bumper Under Cover <i>Distorted</i>	1	180.00 ✓
11	Front Bumper Under Cover Clips <i>new</i>	1	30.00 ✓
12	Front Grille <i>new</i>	1	360.00 +
13	Front Grille Clips <i>new</i>	1	25.00 +
14	Bonnet <i>new</i>	1	650.00 x
15	Bonnet Lock <i>new</i>	1	75.00 +
16	Head Lamp - RH <i>Missing</i>	1	1,150.00 ✓
17	Front Fender - RH <i>Distorted</i>	1	380.00 ✓
18	Front Fender Inner Shield - RH <i>new</i>	1	75.00 ✓
19	Front Fender Inner Shield Clips - RH <i>new</i>	1	40.00 ✓
20	Front Fender Inner Panel - RH <i>Distorted</i>	1	850.00 ✓ 650.
21	Front Fender Wheel House - RH <i>Cracked</i>	1	1,420.00 ✓ 780.
22	Front Fender Bracket - RH <i>Distorted</i>	1	60.00 ✓
23	Front Door - RH <i>new</i>	1	850.00 +
24	Rocker Panel - RH <i>new</i>	1	680.00 +
25	Front Support Panel <i>Cracked</i>	1	750.00 ✓ 580.
26	Air Con Condenser <i>new</i>	1	680.00 x
27	Air Con Suction Pipe <i>new</i>	1	220.00 +

RE : ESTIMATE FOR ACCIDENT REPAIR GBL2255G (CITROEN BERLINGO)

28	Air Con Discharge Pipe	New	1	280.00	X
29	Air Con Liquid Pipe		1	260.00	X
30	Radiator	New	1	480.00	+
31	Oil Cooler	Detct.	1	650.00	560
32	Oil Cooler Air Duct	Crack	1	280.00	150.
33	Oil Cooler Hose	New	1	200.00	+
34	Radiator Spare Tank	Detct.	1	180.00	-
35	Radiator Spare Tank Hose	New	1	45.00	+
36	Wiper Washer Tank	Dischd	1	260.00	120.
37	Wiper Washer Tank Motor	New	1	80.00	+
38	Wiper Washer Tank Hose	Dischd	1	60.00	✓
39	Engine Mounting - RH	Detct	1	320.00	✓
40	Engine Undercover	tozn	1	300.00	-
41	Engine Undercover Clips	new	1	20.00	-
42	Steering Wheel Air Bag	Activated	1	2,800.00	2200
43	Steering Wheel Clock Spring	Activated	1	650.00	✓
44	Roof Air Bag	Activated	1	2,400.00	1800
45	Roof Inner Trim Board	cracked	1	2,200.00	1500.
46	Roof inner Trim Clips	new	1	40.00	✓
47	Safety Belt - LH & RH	Activated	2	1,800.00	1200
48	Safety Belt Tensioner - LH & RH	New	2	1,200.00	+
49	Air Bag Sensor - LH & RH	Activated	2	680.00	-
50	Air Bag ECU	Activated	1	1,400.00	800.
51	Front Tyre - RH	Replaced	1	240.00	✓
52	Front Wheel Rim - RH	Distord	1	480.00	✓
53	Front Lower Arm - RH	Bent	1	380.00	-
54	Front Knuckle Arm - RH	Detct	1	690.00	-
55	Front Shock Absorber - RH	Bent	1	360.00	-
56	Front Wheel Hub - RH	Detct	1	280.00	-
57	Front Anti Roller Bar Linkage - RH	Bent	1	90.00	✓
58	Front Drive Shaft - RH	Detct	1	950.00	✓
59	Front Anti Roll Bar	New	1	340.00	+
60	Steering Rack & Pinion	New	1	2,200.00	+
61	Steering Cross Member	Bent.	1	2,600.00	1300.
62	Coolant	New	1	45.00	✓

21385
23523.50

35,850.00
3,585.00
39,435.00

Total parts \$ 39,435.00

LABOUR CHARGE

1	To knocking & pull out front portion and renew damage parts	\$	3,200.00	1600
2	To putty and spray up paint work	\$	2,400.00	1400.

RE : ESTIMATE FOR ACCIDENT REPAIR GBL2255G (CITROEN BERLINGO)

3	To spray tuff coat	\$	200.00 120
4	To check wiring	\$	200.00 30
5	To remove air con condenser & top up air con gas	\$	120.00 60
6	To remove radiator & top up coolant	\$	120.00 60
7	To replace engine mounting	\$	280.00 180
8	To transfer front door fitting	\$	150.00 x.
9	To remove air bags & to reset air bag settings	\$	500.00 350
10	To remove roof inner trim	\$	200.00 120
11	To remove front undercarriage	\$	450.00 350.
12	To perform wheel alignment	\$	150.00 80
13	Towing fee	\$	60.00 ✓
Total labour		\$	8,030.00
Grand Total		\$	47,465.00

4410.

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adnan Lij
P/P, H/S To be advised
Exem To be advised.
01/12/21. 81 Days.
Total: 27933.50
H/S: 22.31K