

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0955/2021/JT
DATE : 26-Nov-21
WIP : 55483

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/11/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHAN POH LAM FELIX
ADDRESS : 15 DAIRY FARM ROAD
#03-05
SINGAPORE 679042
TELEPHONE : HP +65 97803800
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900246149-01
VEHICLE NO : **SFG 73 G**
MODEL CODE : AUDI Q3 1.4 TFSI S
MODEL YEAR : 14/11/2019
ENGINE NO : CZD 886477
CHASSIS NO : WAUZZZF34L1013705
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Nov-21
PLACE OF ACCIDENT : ROUNDABOUT AT HILLVIEW

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFG 73 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING ATD.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	1000.
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,500.00	1100
5	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION.	S/N \$ 480.00	? X
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	? ✓
TOTAL LABOUR CHARGES		: \$ 6,852.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFG 73 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Repair</i> torn	2	\$ 2,161.00	+ ✓	922
2	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$ 118.00	+	
3	FRONT BUMPER GRILLE CENTER <i>new</i> deformed	1	\$ 217.00	+ ✓	173.2
4	FRONT BUMPER GRILLE COVER <i>new</i>	1	\$ 51.00	+	
5	FRONT BUMPER GRILLE - LH / RH <i>new</i>	2	\$ 220.00	?	
6	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 190.00	+	
7	FRONT BUMPER SPOILER <i>new</i> deformed	1	\$ 383.00	+ ✓	306.4
8	FRONT BUMPER AIR GUIDE GIRLLE - LH / RH <i>new</i>	2	\$ 306.00	+ ✓	122
9	RADIATOR GRILLE <i>cracked</i> LH cracked	1	\$ 1,433.00	+ ✓	1146.4
10	RADIATOR STRIKER PLATE <i>cracked</i>	1	\$ 244.00	+ ✓	194.8
11	RADIATOR CAP <i>nn</i>	1	\$ 45.00	?	
12	RADIATOR BRACKET <i>nn</i>	1	\$ 41.00	?	
13	FRONT CAMERA <i>new</i>	1	\$ 1,141.00	+	
14	FRONT BUMPER FOAM FILLER PIECE <i>nn</i>	1	\$ 102.00	?	
15	FRONT BUMPER REINFORCEMENT BEAM <i>nn</i>	1	\$ 916.00	?	
16	FRONT BUMPER TOP COVER <i>new</i> deformed	1	\$ 123.00	+ ✓	98
17	AIRCOND STICKER <i>new</i> NEC	1	\$ 8.00	+ ✓	5.68
18	FRONT PARKING AID SENSOR <i>new</i>	2	TBC	+	
19	HORN - LH / RH <i>new</i>	2	\$ 267.00	+	
20	HORN BRACKET - LH / RH <i>new</i>	2	\$ 44.00	+	
SUB TOTAL SPARE PARTS		:	\$ 8,010.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFG 73 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HEADLIGHT MOUNTING - LH / RH	2	\$ 236.00	+
22	HEADLIGHT - LH / RH	2	\$ 11,178.00	+
23	LIFT CYLINDER - LH / RH	2	\$ 420.00	+
24	LIFT CYLINDER HOSE <i>torn</i>	1	\$ 80.00	✓ 63.44
25	BONNET <i>Dented</i>	1	\$ 3,508.00	✓ 2806.4
26	BONNET IMPACT PROTECTION - CENTER <i>new</i>	1	\$ 28.00	✓ 21.84
27	BONNET RELEASE ELEMENT	1	\$ 58.00	+
28	BONNET RELEASE LEVER	1	\$ 14.00	+
29	BONNET ATTACHEMENT PARTS	1	\$ 296.00	+
30	FRONT RADIATOR AIR GUIDE - LH / RH <i>LH cracked</i>	2	\$ 76.00	✓ 29.76
31	FRONT RADIATOR AIR GUIDE UPPER	1	\$ 42.00	+
32	FRONT WHEEL COVER - LH / RH <i>new</i>	2	\$ 536.00	✓ 428.8
33	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓ 60
34	SUNDRIES <i>?</i> <i>nn</i>	1	\$ 350.00	✗
TOTAL SPARE PARTS		:	\$ 24,892.00	
TOTAL LABOUR CHARGES		:	\$ 6,852.00	
GRAND TOTAL		:	\$ 31,744.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *30/11/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT