

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0965/2021/
DATE : 29-Nov-21
WIP : 55683

Veron

\$321c

16 Days Cancel!

12 Days.

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/11/2021

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAM YEE KEONG
ADDRESS : BLK 723 TAMPINES ST 72
#09-09
SINGAPORE 520723
TELEPHONE : HP +65 9668 4662
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100499366-04
VEHICLE NO : SLK 7680 R
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 25/1/2017
ENGINE NO : CVN 021943
CHASSIS NO : WAUZZZF44HA055467
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Nov-21
PLACE OF ACCIDENT : TAMPINES STREET 71

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLK 7680 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNES FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	X ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	250 ✓
3	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	S/N \$	2,400.00	? ✓
4	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$	1,700.00	? ✓
5	TO RENEW LHS FRONT FENDER INNER AIRCON CONDENSER COOLANT PIPE	S/N \$	280.00	? ✓
SUB TOTAL LABOUR CHARGES		:	\$	<u>5,090.00</u>

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLK 7680 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY LHF FRONT DOOR	S/N \$ 280.00	✓ ✓
7	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO CUT OUT AND WELD LHS FRONT FENDER TOP SUPPORT. TO REPAIR LHS UPPER A-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.	\$ 6,650.00	1500 2750
8	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, LHS FRONT FENDER TOP SUPPORT, BONNET, LHS UPPER A-PILLAR AND LHS FRONT DOOR	\$ 4,850.00	2200 ✓
9	TO RENEW LHS FRONT RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT	S/N \$ 520.00	✓ ✓
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$ 384.00	152 ✓
11	TO RE-APPLY PAINT COATING FOR DAMAGE AREA.	TBC ?	380.00
TOTAL LABOUR CHARGES		: \$ <u>17,774.00</u>	



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLK 7680 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	S 2,111.00	✓ 1688.80
2	FRONT BUMPER ATTACHMENT PART <i>new</i>	1	TBC	✓
3	FRONT BUMPER SECURING STRIP <i>Anged</i>	2	S 71.00	✓ 56.32
4	FRONT BUMPER GRILLE <i>new</i>	1	S 196.00	✓
5	FRONT BUMPER CLOSING ELEMENT <i>to fn</i>	1	S 210.00	✓ 167.60
6	FRONT BUMPER AIR GUIDE - LH <i>backed</i>	1	S 63.00	✓ 50.08
7	RADIATOR GRILLE <i>new</i> <i>crushed</i>	1	S 1,152.00	✓ 921.60
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>lit</i>	1	S 135.00	✓ 108
9	FRONT BUMPER FOAM FILLER PIRECE <i>Not Nec</i>	1	S 124.00	✓ X
10	FRONT REINFORCEMENT BAR <i>Not Nec</i>	1	S 845.00	✓ X
11	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	S 36.00	✓ 28.72
12	FRONT BUMPER TOP COVER <i>new</i>	1	S 127.00	✓
13	CAUTION STICKER <i>new</i>	1	S 14.00	✓
14	AIR CONDITIONER STICKER <i>new</i>	1	S 8.00	✓
15	FRONT REINFORCEMENT BAR BRACKET <i>Not Nec</i>	1	S 137.00	✓ X
16	FRONT BUMPER SUPPORT - LH/ RH <i>new</i>	2	S 58.00	✓
17	HORN - LH <i>Not Nec</i>	1	S 126.00	✓ X
18	HORN BRACKET - LH <i>Not Nec</i>	1	S 29.00	✓ X
19	BONNET <i>Distorted</i>	1	S 3,246.00	✓ 2596.80
20	BONNET ATTACHMENT PART <i>new</i>	1	S 412.00	✓
SUB TOTAL SPARE PARTS		:	\$ 9,100.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLK 7680 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>neu</i>	3	S	84.00 ✓	65.68
22	BONNET STRIKER <i>neu</i>	1	S	50.00 X	
23	BONNET LOCK	1	S	214.00 +	
24	FRONT FENDER - LH <i>Distorted</i>	1	S	767.00 ✓	613.20
25	FRONT FENDER ATTACHMENT PART <i>neu</i>	1	S	202.00 +	
26	FRONT FENDER CLOSING ELEMENT - LH <i>Distorted</i>	1	S	72.00 ✓	57.52
27	FRONT FENDER BRACKET - LH <i>Distorted</i>	1	S	35.00 ✓	27.92
28	FRONT FENDER BRACKET - CENTER <i>Neu</i>	1	S	49.00 ? X	
29	FRONT FENDER BRACKET - BACK <i>Neu</i>	1	S	32.00 ? X	
30	FRONT FENDER BRACE <i>Bent</i>	1	S	118.00 ✓	94.40
31	FRONT WHEEL HOUSING LINER - LH <i>Distorted</i>	1	S	240.00 ✓	191.60
32	FRONT WHEEL HOUSING LINER ATTACHMENT PART <i>neu</i>	1		TBC +	
33	FRONT WHEEL SPOILER <i>Distorted</i>	1	S	73.00 ✓	58.40
34	FRONT WHEEL SPOILER - LH <i>Distorted</i>	1	S	35.00 ✓	27.76
35	FRONT FENDER STONE GUARD <i>neu</i>	1	S	51.00 +	
36	FRONT FENDER LEDGE COVER <i>neu</i>	1	S	31.00 ✓	24.64
37	FRONT FENDER LEDGE COVER - UPPER <i>neu</i>	1	S	23.00 ?	17.92
38	FRONT FENDER CONNECTING PLATE - LH <i>neu</i>	2	S	467.00 +	
39	HEADLIGHT - LH <i>Cracked</i>	1	S	7,693.00 ✓	6154.40
40	HEADLIGHT POWER MODULE <i>neu</i>	1	S	761.00 X	
SUB TOTAL SPARE PARTS		:	\$	10,997.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLK 7680 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HEADLIGHT CONTROL UNIT <i>Not in</i>	1	\$ 751.00	<i>X</i>
42	HEADLIGHT HOSE - LH <i>Not in</i>	1	\$ 36.00	<i>X</i>
43	COMPENSATING PIECE <i>Not Nec</i>	3	\$ 122.00	<i>? X</i>
44	HEADLIGHT LIFT CYLINDER - LH <i>Damaged</i>	1	\$ 210.00	<i>? 167.60</i>
45	CORRUGATED PIPE <i>Not Nec</i>	1	\$ 93.00	<i>? X</i>
46	LOCK CARRIER <i>Cracked</i>	1	\$ 1,016.00	<i>? 812.80</i>
47	LOCK CARRIER BRACKET <i>Not in</i>	1	\$ 19.00	<i>? X</i>
48	COOLANT <i>Nec</i>	6	\$ 266.00	<i>? 212.64</i>
49	FRONT RADIATOR AIR GUIDE - LH	1	\$ 28.00	<i>X</i>
50	FRONT RADIATOR INNER AIR GUIDE - LH <i>Not in</i>	1	\$ 12.00	<i>X</i>
51	FRONT RADIATOR AIR GUIDE - UPPER	1	\$ 16.00	<i>X</i>
52	REFRIGERANT LINE <i>Not Nec</i>	1	\$ 1,278.00	<i>? X</i>
53	FRONT WINDOW CHROME TRIM STRIP - LH <i>Not in</i>	1	\$ 307.00	<i>X</i>
54	FRONT WINDOW TRIM - LH <i>Not in</i>	1	\$ 257.00	<i>X</i>
55	FRONT ALUMINIUM RIM - LH <i>Not in</i>	1	\$ 1,297.00	<i>✓ 1037.60</i>
56	FRONT SUB FRAME <i>Not Nec</i>	1	\$ 1,891.00	<i>? X</i>
57	FRONT WISHBONE <i>Best</i>	1	\$ 539.00	<i>? 430.80</i>
58	FRONT SUSPENSION GUIDE - LH <i>Best</i>	1	\$ 943.00	<i>? 754.40</i>
59	FRONT SUSPENSION ARM - UPPER <i>Best</i>	2	\$ 1,024.00	<i>? 818.40</i>
60	WHEEL BEARING HOUSING - LH <i>Damaged</i>	1	\$ 968.00	<i>? 774.00</i>
TOTAL SPARE PARTS		:	\$ 11,073.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLK 7680 R

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
• 61	SWIVEL JOINT <i>Best</i>	1	\$ 193.00	? 154.40	
• 62	WHEEL HUB <i>Damaged.</i>	1	\$ 479.00	? 383.20	
• 63	DOUBLE BALL BEARING <i>Damaged.</i>	1	\$ 246.00	? 196.80	
64	SUSPENSION FORKS - LH <i>Not Nec</i>	1	\$ 264.00	? X	
65	COUPLING ROD <i>Not Nec</i>	2	\$ 240.00	? X	
66	ANTI ROLL BAR <i>Not in</i>	1	\$ 433.00	+	
67	SHOCK ABSORBER <i>Not Nec</i>	1	\$ 301.00	? X	
68	DRIVE SHAFT <i>Not in</i>	1	\$ 2,650.00	+	
• 69	STEERING GEAR <i>Damaged</i>	1	\$ 6,787.00	? 6911.20	
• 70	TIE ROD END <i>Best</i>	1	\$ 197.00	? 157.20	
71	TRACK ROD <i>Not Nec</i>	1	\$ 99.00	? X	
72	ACRYLIC SEALER <i>Not in</i>	S/N	\$ 180.00	+	
73	CAVITY WAX <i>Not in</i>	S/N	\$ 140.00	+	
74	STONE CHIP <i>Not in</i>	S/N	\$ 180.00	+	
75	METAL FILLER POWDER <i>Not in</i>	S/N	\$ 280.00	+	
• 76	FRONT NUMBER PLATE <i>Not Nec</i>	S/N	\$ 60.00	60	
77	SUNDRIES <i>Nec.</i>		\$ 500.00	? 211.52	
TOTAL SPARE PARTS		:	\$ 44,399.00		
TOTAL LABOUR CHARGES		:	\$ 17,774.00		
GRAND TOTAL		:	\$ 62,173.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *30/11/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 09 Days inclusive of undercarriage.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT