



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0961/2021/JT  
DATE : 29-Nov-21  
WIP : 55683

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/11/21

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ZHANG XIAO  
ADDRESS : BLK 305A PUNGGOL ROAD  
#03-707  
SINGAPORE 821305  
TELEPHONE : HP +65 96314702  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 7210040873  
VEHICLE NO : **SMZ 5354 E**  
MODEL CODE : AUDI A5 SB 2.0 TFSI  
MODEL YEAR : 30/4/2021  
ENGINE NO : DEM 031628  
CHASSIS NO : WAUZZZF5XMA039440  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 26-Nov-21  
PLACE OF ACCIDENT : ALONG CTE TOWARDS SLE AFTER  
BALESTIER ROAD

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 5354 E**

| S/N                             | NATURE OF JOBS                                                                                                                                                                                                            | ESTIMATED CHARGES |                    | SURVEYOR'S RECOMMENDATIONS |
|---------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|--------------------|----------------------------|
| 1                               | TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.                                                                                                                                                                        | S/N               | AIG                | X                          |
| 2                               | TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.                                                                                                                                                                       | S/N               | \$ 800.00          | ? X                        |
| 3                               | TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.                                                                         | S/N               | \$ 480.00          | ✓                          |
| 4                               | TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.                                                    | S/N               | \$ 2,200.00        | ✓                          |
| 5                               | TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS. | S/N               | \$ 3,600.00        | ✓                          |
| 6                               | TO PLACE VEHICLE ON CAR O-LINER                                                                                                                                                                                           | S/N               | \$ 2,400.00        | ? X                        |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                           | :                 | <b>\$ 9,480.00</b> |                            |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 5354 E**

| S/N                             | NATURE OF JOBS                                                                                                                        |        | ESTIMATED<br>CHARGES  | SURVEYOR'S<br>RECOMMENDATIONS |
|---------------------------------|---------------------------------------------------------------------------------------------------------------------------------------|--------|-----------------------|-------------------------------|
| 7                               | TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY LHS FRONT DOOR. | S/N \$ | 280.00                | X                             |
| 8                               | TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.                              | S/N \$ | <del>350.00</del> 280 | ✓                             |
| 9                               | TO RENEW ENGINE THROTTLE BODY AND OTHER ENGINE COMPONENTS.                                                                            | S/N \$ | 780.00                | ✓                             |
| 10                              | TO RENEW FRONT WINDSCREEN.                                                                                                            | S/N \$ | 480.00                | ✓                             |
| 11                              | TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.                                                                                           | S/N \$ | 400.00                | ✓                             |
| 12                              | TO CARRY OUT WATER SEEPAGE TEST ON FRONT WINDSCREEN.                                                                                  | S/N \$ | <del>200.00</del> 150 | ✓                             |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                       | :      | \$ <u>2,490.00</u>    |                               |

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 5354 E**

| S/N                         | NATURE OF JOBS                                                                                                                                                                                                                                             | ESTIMATED CHARGES     | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------|
| 13                          | TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS, RHS FRONT DOOR AND BOTH HEADLIGHTS. TO REPAIR BOTH UPPER A-PILLAR. RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓ ✓ ✓ | \$ 8,000.00           | 4000 4500                  |
| 14                          | TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH UPPER A-PILLAR AND BOTH FRONT DOORS. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT. ✓ ✓                                                                                       | \$ 8,000.00           | 3300 ✓                     |
| 15                          | TO CARRY OUT PRE WHEEL ALIGNMENT TEST.                                                                                                                                                                                                                     | S/N \$ 240.00         | 7 X                        |
| 16                          | TO CARRY OUT PRE-REPAIR DIAGNOSTIC CHECK AND POST-REPAIR DIAGNOSTIC CHECK.                                                                                                                                                                                 | S/N \$ 384.00         | 192 ✓                      |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                                                            | <b>: \$ 28,594.00</b> |                            |

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E**

|                              |                                                          |     | DAMAGED PARTS & PRICES   |          |
|------------------------------|----------------------------------------------------------|-----|--------------------------|----------|
| S/N                          | PARTS DESCRIPTION                                        | QTY | S/NETT                   | REMARKS  |
| 1                            | FRONT BUMPER <i>Distorted</i>                            | 1   | \$ 2,342.00 ✓            | 1,873.60 |
| 2                            | FRONT BUMPER SECURING STRIP <i>new</i>                   | 2   | \$ 71.00 +               |          |
| 3                            | FRONT BUMPER GRILLE CENTER <i>new</i>                    | 1   | \$ 196.00 +              |          |
| 4                            | FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>   | 1   | \$ 262.00 +              |          |
| 5                            | FRONT BUMPER SPOILER <i>new</i>                          | 1   | \$ 535.00 +              |          |
| 6                            | FRONT AIR GUIDE - LH / RH <i>new</i>                     | 2   | \$ 126.00 +              |          |
| 7                            | FRONT BUMPER CLOSING ELEMENT <i>new</i>                  | 1   | \$ 262.00 +              | 209.20   |
| 8                            | FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>LH cruked</i> | 2   | \$ <del>270.00</del> 135 | 108.00   |
| 9                            | FRONT BUMPER TRIM - LH / RH <i>new</i>                   | 2   | \$ 96.00 +               |          |
| 10                           | FRONT RADIATOR TRIM CENTER ?                             | 1   | \$ 114.00 ?              |          |
| 11                           | FRONT RADIATOR GRILLE <i>smushed</i>                     | 1   | \$ 1,694.00 ✓            | 1132.80  |
| 12                           | FRONT RADIATOR CAP <i>smushed</i>                        | 1   | \$ 166.00 ✓              | 132.80   |
| 13                           | FRONT RADIATOR BRACKET <i>cruked</i>                     | 1   | \$ 17.00 ✓               | 12.96    |
| 14                           | FRONT RADIATOR SECURING PLATE <i>cruked</i>              | 1   | \$ 11.00 ✓               | 8.08     |
| 15                           | FRONT RADIATOR CAMERA <i>cruked</i>                      | 1   | \$ 1,141.00 ✓            | 912.80   |
| 16                           | FRONT RADIATOR GRILLE CAMERA ADAPTER ? <b>BROKEN</b>     | 1   | \$ 198.00 ?              | 158.40   |
| 17                           | FRONT CAMERA ADAPTER ?                                   | 1   | \$ 288.00 ?              |          |
| 18                           | FRONT BUMPER FOAM FILLER PIECE <i>cruked</i>             | 1   | \$ 146.00 ✓              | 99.20    |
| 19                           | FRONT BUMPER REINFORCEMENT BEAM <i>Dented</i>            | 1   | \$ 845.00 ✓              | 675.60   |
| 20                           | FRONT BUMPER GUIDE SECTION - LH / RH ?                   | 2   | \$ 72.00 ?               | 57.44V   |
| <b>SUB TOTAL SPARE PARTS</b> |                                                          | :   | \$ <u>8,852.00</u>       |          |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E**

|                              |                                                    |     | DAMAGED PARTS & PRICES |          |
|------------------------------|----------------------------------------------------|-----|------------------------|----------|
| S/N                          | PARTS DESCRIPTION                                  | QTY | S/NETT                 | REMARKS  |
| 21                           | FRONT BUMPER BRACKET - LH / RH ? <b>BENT</b>       | 2   | \$ 428.00 ?            | 342.40   |
| 22                           | FRONT BUMPER TOP COVER <i>cracked</i>              | 1   | \$ 127.00 ✓            | 101.60   |
| 23                           | CAUTION STICKER <i>3 new</i>                       | 1   | \$ 14.00 ✓             | 12.40    |
| 24                           | AIR COND STICKER                                   | 1   | \$ 8.00 ✓              | 6.64     |
| 25                           | FRONT BUMPER LOCK CARRIER BRACKET <i>cracked</i>   | 1   | \$ 137.00 ✓            | 109.60   |
| 26                           | FRONT BUMPER SUPPORT - LH / RH <i>cracked</i>      | 2   | \$ 58.00 ✓             | 44.96    |
| 27                           | POP RIVET <i>per</i>                               | 4   | \$ 4.00 ✓              | 2.56     |
| 28                           | HORN - LH / RH                                     | 2   | \$ 252.00 ?            |          |
| 29                           | HORN SUPPORT - LH / RH ?                           | 2   | \$ 58.00 ?             |          |
| 30                           | FRONT PARKING AID SENSOR - INNER / OUTER           | 4   | TBC                    |          |
| 31                           | FRONT BUMPER WIRING SET                            | 1   | \$ 405.00 ?            |          |
| 32                           | FRONT FENDER- LH / RH <i>LH Buckled, RH Dented</i> | 2   | \$ 2,120.00 ✓          | 1,696.00 |
| 33                           | FRONT FENDER ATTACHEMENT PARTS <i>3 new</i>        | 1   | \$ 53.00 +             |          |
| 34                           | FRONT FENDER CLOSING ELEMENT - LH / RH <b>NEC</b>  | 2   | \$ 148.00 +            | 118.08   |
| 35                           | FRONT FENDER BRACKET - LH / RH ? <b>BENT</b>       | 2   | \$ 70.00 ?             | 55.84    |
| 36                           | POP RIVET <i>new</i>                               | 10  | \$ 33.00 ✓             | 26.40    |
| 37                           | FRONT FENDER BRACKET CENTER - LH / RH ?            | 2   | \$ 98.00 ?             |          |
| 38                           | FRONT FENDER BRACE - LH / RH ?                     | 2   | \$ 236.00 ?            |          |
| 39                           | FRONT FENDER BRACKET BACK - LH & RH ?              | 2   | \$ 70.00 ?             |          |
| 40                           | FRONT WHEEL HOUSING LINER - LH / RH <i>new</i>     | 2   | \$ 550.00 +            |          |
| <b>SUB TOTAL SPARE PARTS</b> |                                                    | :   | <b>\$ 4,869.00</b>     |          |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E**

|                              |                                                        |     | DAMAGED PARTS & PRICES |            |
|------------------------------|--------------------------------------------------------|-----|------------------------|------------|
| S/N                          | PARTS DESCRIPTION                                      | QTY | S/NETT                 | REMARKS    |
| 41                           | FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS <i>new</i> | 1   | \$ 169.00              | ✓          |
| 42                           | FRONT WHEEL SPOILER - LH / RH <i>new</i>               | 2   | \$ 146.00              | ✓          |
| 43                           | FRONT SPOILER - LH / RH <i>new</i>                     | 2   | \$ 71.00               | ✓          |
| 44                           | FRONT STONE CHIP GUARD - LH / RH <i>new</i>            | 2   | \$ 102.00              | ✓          |
| 45                           | FRONT FENDER TRIM - LH / RH <i>new</i>                 | 2   | \$ 328.00              | ✓ 262.40   |
| 46                           | BONNET <i>Distorted</i>                                | 1   | \$ 3,312.00            | ✓ 2,649.60 |
| 47                           | BONNET ATTACHEMENT PARTS <i>new</i>                    | 1   | \$ 123.00              | ✓          |
| 48                           | BONNET HINGE - LH / RH <i>new</i>                      | 2   | \$ 838.00              | ✓          |
| 49                           | BONNET IMPACT PROTECTION - CENTER / LH / RH <i>new</i> | 3   | \$ 84.00               | ✓ 65.68    |
| 50                           | BONNET SOUND ABSORBER <i>crushed</i>                   | 1   | \$ 343.00              | ✓ 274.40   |
| 51                           | BONNET STRIKER - LH / RH <i>crushed</i>                | 2   | \$ 100.00              | ✓ 79.84    |
| 52                           | BONNET LOCK <i>crushed</i>                             | 2   | \$ 427.00              | ✓ 341.30   |
| 53                           | BONNET BOWDEN CABLE - CENTER <i>crushed</i>            | 1   | \$ 58.00               | ✓ 46.00    |
| 54                           | BONNET RELEASE LEVER <i>new</i>                        | 1   | \$ 14.00               | ✓          |
| 55                           | BONNET BOWDEN CABLE INNER - CENTER <i>crushed</i>      | 1   | \$ 58.00               | ✓ 46.00    |
| 56                           | BONNET LOCK CABLE ?                                    | 1   | \$ 74.00               | ? 58.64    |
| 57                           | BONNET FLAT CONNECTOR ?                                | 1   | \$ 13.00               | ?          |
| 58                           | FRONT LEDGE LONG COVER - INNER / OUTER ? <b>BROKEN</b> | 2   | \$ 72.00               | ? 56.48    |
| 59                           | FRONT LEDGE SHORT COVER - INNER / OUTER ?              | 2   | \$ 32.00               | ?          |
| 60                           | HEADLAMPS COVER - LH / RH <i>crushed</i>               | 2   | \$ 88.00               | ✓ 68.96    |
| <b>SUB TOTAL SPARE PARTS</b> |                                                        | :   | <b>\$ 6,452.00</b>     |            |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E**

|                              |                                                     |     | DAMAGED PARTS & PRICES |           |
|------------------------------|-----------------------------------------------------|-----|------------------------|-----------|
| S/N                          | PARTS DESCRIPTION                                   | QTY | S/NETT                 | REMARKS   |
| 61                           | FRONT FENDER LEDGE COVER - LH / RH ?                | 2   | \$ 144.00 ?            |           |
| 62                           | PLENUM CHAMBER <i>new</i>                           | 1   | \$ 97.00 +             |           |
| 63                           | GAS FILLED STRUT <i>new</i>                         | 2   | \$ 241.00 +            |           |
| 64                           | HEADLIGHT MATRIX BEAM - LH / RH <i>Cracked</i>      | 2   | \$ 15,370.00 ✓         | 12,296.00 |
| 65                           | HEADLIGHT HOSE <i>new</i>                           | 2   | \$ 71.00 +             |           |
| 66                           | COMPENSATING PIECE ? <b>BROKEN</b>                  | 6   | \$ 243.00 >            | 193.28    |
| 67                           | LIFT CYLINDER - LH / RH ?                           | 2   | \$ 396.00 ?            |           |
| 68                           | LIFT CYLINDER BRACKET - LH / RH ?                   | 2   | \$ 30.00 ?             | 12.32     |
| 69                           | LIFT CYLINDER HOSE <i>new</i>                       | 1   | TBC                    | X         |
| 70                           | RADIATOR COOLANT LOCK CARRIER <i>Cracked</i>        | 1   | \$ 1,016.00 ✓          | 812.80    |
| 71                           | RADIATOR COOLANT SUPPORT - LH / RH <b>BROKEN</b>    | 2   | \$ 76.00               | 60.64     |
| 72                           | FLUID RESERVOIR A/C CONDENSER <i>Dented</i>         | 1   | \$ 622.00 ✓            | 497.60    |
| 73                           | REFRIGERANT PRESSURE SENSOR ?                       | 1   | \$ 186.00 ?            |           |
| 74                           | REFRIGERANT HIGH PRESSURE SWITCH ?                  | 1   | \$ 51.00 ?             |           |
| 75                           | REFRIGERANT SUCTION HOSE ?                          | 1   | \$ 167.00 ?            |           |
| 76                           | REFRIGERANT DISCHARGE HOSE ?                        | 1   | \$ 340.00 ?            |           |
| 77                           | REFRIGERANT COOLANT PIPE ?                          | 1   | \$ 248.00 ?            |           |
| 78                           | OUTSIDE TEMPERATURE SENSOR BRACKET ? <b>MISSING</b> | 1   | \$ 19.00 ?             | 14.56     |
| 79                           | OUTSIDE TEMPERATURE SENSOR ?                        | 1   | \$ 59.00 ?             |           |
| 80                           | AIR COOLER CHARGED <i>new</i> ?                     | 1   | \$ 587.00 <i>new</i> ? |           |
| <b>SUB TOTAL SPARE PARTS</b> |                                                     | :   | \$ <u>19,963.00</u>    |           |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E**

|                              |                                                             |     | DAMAGED PARTS & PRICES |                 |
|------------------------------|-------------------------------------------------------------|-----|------------------------|-----------------|
| S/N                          | PARTS DESCRIPTION                                           | QTY | S/NETT                 | REMARKS         |
| 81                           | AIR COOLER PRESSURE HOSE OUTER - RH ?                       | 1   | \$ 357.00 ?            |                 |
| 82                           | AIR COOLER PRESSURE HOSE INNER - RH ?                       | 1   | \$ 427.00 ?            |                 |
| 83                           | RADIATOR COOLER ? <b>BENT</b>                               | 1   | \$ 655.00 ?            | <b>523.60</b>   |
| 84                           | RADIATOR CONTROL UNIT ? <b>DENTED</b>                       | 1   | \$ 1,880.00 ?          | <b>1,548.00</b> |
| 85                           | RADIATOR RING ? <b>BROKEN</b>                               | 1   | \$ 220.00 ?            | <b>176.00</b>   |
| 86                           | RADIATOR COOLANT <i>new</i> ?                               | 6   | \$ 266.00 ✓            | <b>212.64</b>   |
| 87                           | A/C COMPRESSOR OIL ?                                        | 1   | \$ 622.00 ?            |                 |
| 88                           | RADIATOR AIR GUIDE OUTER - LH / RH ? <i>cracked</i>         | 2   | \$ 64.00 ✓             | <b>52.64</b>    |
| 89                           | RADIATOR AIR GUIDE INNER - UPPER / LH / RH ? <i>cracked</i> | 3   | \$ 48.00 ✓             | <b>39.84</b>    |
| 90                           | RADIATOR AIR GUIDE LOWER <i>cracked</i> ?                   | 1   | \$ 22.00 ✓             | <b>17.20</b>    |
| 91                           | RADIATOR COOLANT UPPER HOSE ?                               | 1   | \$ 71.00 ?             |                 |
| 92                           | RADIATOR CONNECTOR TUBE ?                                   | 1   | \$ 54.00 ?             |                 |
| 93                           | RADIATOR COOLANT INLET ?                                    | 1   | \$ 71.00 ?             |                 |
| 94                           | RADIATOR COOLANT HOSE ?                                     | 1   | \$ 22.00 ?             |                 |
| 95                           | RADIATOR BREATHER TUBE ?                                    | 1   | \$ 34.00 ?             | <b>26.88</b>    |
| 96                           | RADIATOR BREATHER TUBE UPPER ?                              | 1   | \$ 53.00 ?             |                 |
| 97                           | RADIATOR VENT HOSE UPPER CENTER ?                           | 1   | \$ 40.00 ?             |                 |
| 98                           | ENGINE TIMING CASE COVER - BOTTOM ?                         | 1   | \$ 277.00 ?            |                 |
| 99                           | ENGINE TIMING CASE COVER - UPPER ? <b>BROKEN</b>            | 1   | \$ 240.00 ?            | <b>191.60</b>   |
| 100                          | CAMSHAFT MAGNET ADJUSTER ?                                  | 2   | \$ 338.00 ?            |                 |
| <b>SUB TOTAL SPARE PARTS</b> |                                                             | :   | <b>\$ 5,761.00</b>     |                 |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E**

|                              |                                                     |     | DAMAGED PARTS & PRICES |          |
|------------------------------|-----------------------------------------------------|-----|------------------------|----------|
| S/N                          | PARTS DESCRIPTION                                   | QTY | S/NETT                 | REMARKS  |
| 101                          | THROTTLE VALVE ADAPTER ?                            | 1   | \$ 1,036.00 ?          |          |
| 102                          | THROTTLE INTAKE AIR DUCT - RH ? <b>BROKEN</b>       | 1   | \$ 22.00 ?             | 17.20    |
| 103                          | THROTTLE AIR GUIDE ? <b>BROKEN</b>                  | 1   | \$ 53.00 ?             | 42.40    |
| 104                          | AIR FILTER                                          | 1   | \$ 386.00              | } ?      |
| 105                          | THROTTLE INTAKE HOSE                                | 1   | \$ 95.00               |          |
| 106                          | FRONT AIR MASS METER                                | 1   | \$ 567.00              |          |
| 107                          | INTAKE MANIFOLD                                     | 1   | \$ 856.00              |          |
| 108                          | EXHAUST GAS TURBOCHARGER <i>Not in</i>              | 1   | \$ 5,405.00 +          |          |
| 109                          | FRONT WINDSCREEN <i>cracked</i>                     | 1   | \$ 1,461.00 ✓          | 1,168.80 |
| 110                          | FRONT RAIN SENSOR GEL FOIL }                        | 1   | \$ 137.00 ✓            | 109.20   |
| 111                          | FRONT RETAINING SPRING } <i>Not in</i>              | 1   | \$ 21.00 ✓             | 16.56    |
| 112                          | FRONT SPRING CLIP }                                 | 1   | \$ 21.00 ✓             | 16.56    |
| 113                          | FRONT CAMERA SILICONE PAD }                         | 1   | \$ 98.00 ✓             | 77.68    |
| 114                          | PRIMER <i>Not in</i>                                | 1   | \$ 20.00 ✓             | 15.76    |
| 115                          | FRONT WATER DEFLECTOR STRIP - LH / RH <i>Not in</i> | 2   | \$ 134.00 +            |          |
| 116                          | FRONT DOOR - RH <i>Repaired Dented</i>              | 1   | \$ 3,884.00 ✓          | 3,107.20 |
| 117                          | FRONT DOOR OUTER SEAL - RH } <b>NEC</b>             | 1   | \$ 222.00 +            | 177.60   |
| 118                          | BONDING AGENT }                                     | 1   | \$ 49.00 +             |          |
| 119                          | CLEANING SOLUTION }                                 | 1   | \$ 68.00 +             |          |
| 120                          | APPLICATOR }                                        | 1   | \$ 8.00 +              |          |
| <b>SUB TOTAL SPARE PARTS</b> |                                                     | :   | <b>\$ 14,543.00</b>    |          |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E**

|                              |                                                        |     | DAMAGED PARTS & PRICES           |          |
|------------------------------|--------------------------------------------------------|-----|----------------------------------|----------|
| S/N                          | PARTS DESCRIPTION                                      | QTY | S/NETT                           | REMARKS  |
| 121                          | FRONT DOOR CATCH - RH <i>new</i>                       | 1   | \$ 120.00 <i>x</i>               |          |
| 122                          | FRONT TYRE PRESSURE DATA PLATE <i>new</i>              | 1   | \$ 37.00 <i>+</i>                |          |
| 123                          | FRONT DOOR TRIM - LH / RH <i>new RH new</i>            | 2   | \$ <del>328.00</del> <i>164.</i> |          |
| 124                          | AIRBAG <i>{ Activated</i>                              | 1   | \$ 3,682.00 ✓                    | 2,945.60 |
| 125                          | AIRBAG UNIT <i>{ Activated</i>                         | 1   | \$ 4,374.00 ✓                    | 3,499.20 |
| 126                          | AIRBAG HEAD UNIT - LH / RH <i>{ Activated</i>          | 2   | \$ 3,726.00 ✓                    | 2,980.80 |
| 127                          | AIRBAG CONTROL UNIT <i>{ Activated</i>                 | 1   | \$ 2,112.00 ✓                    | 1,689.60 |
| 128                          | AIRBAG CRASH SENSOR                                    | 3   | 382.00 TBC ✓                     | 916.80   |
| 129                          | STEERING WHEEL <i>ut</i>                               | 1   | \$ 2,374.00 ✓                    | 1,899.20 |
| 130                          | FRONT DASHBOARD <i>for</i>                             | 1   | \$ 5,289.00 ✓                    | 4,231.20 |
| 131                          | FRONT MOULDED HEADLINER <i>comped Activated</i>        | 1   | \$ 2,048.00 ✓                    | 1,638.40 |
| 132                          | FRONT SEAT BELT TENSIONER - LH / RH <i>{ Activated</i> | 2   | \$ 2,206.00 ✓                    | 1,764.80 |
| 133                          | FRONT SEAT BELT ADJUSTER - LH / RH <i>{ Activated</i>  | 2   | \$ 342.00 ?                      | 273.60   |
| 134                          | FRONT GRAB HANDLE ?                                    | 2   | \$ 283.00 ?                      | 226.40   |
| 135                          | REAR GRAB HANDLE - LH / RH ?                           | 2   | \$ 284.00 ?                      | 226.40   |
| 136                          | A-PILLAR TRIM - LH / RH ?                              | 2   | \$ 408.00 ?                      | 326.40   |
| 137                          | B-PILLAR TRIM UPPER - LH / RH <i>new</i>               | 2   | \$ 470.00 <i>x</i>               |          |
| 138                          | C-PILLAR TRIM - LH / RH ?                              | 2   | \$ 298.00 ?                      |          |
| 139                          | D-PILLAR TRIM - LH / RH ?                              | 2   | \$ 408.00 ?                      |          |
| 140                          | FRONT NO PLATE <i>Missing</i>                          | S/N | \$ 100.00 ✓                      | 100      |
| <b>SUB TOTAL SPARE PARTS</b> |                                                        |     | <b>\$ 28,889.00</b>              |          |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E**

| S/N                         | PARTS DESCRIPTION                   | QTY | DAMAGED PARTS & PRICES |          |
|-----------------------------|-------------------------------------|-----|------------------------|----------|
|                             |                                     |     | S/NETT                 | REMARKS  |
| 141                         | FRONT WINDSCREEN SEALANT <i>New</i> | S/N | \$ 200.00              | ✓ 200    |
| 142                         | SUNDRIES ?                          |     | \$ 1,000.00            | ? 251.10 |
| <b>TOTAL SPARE PARTS</b>    |                                     | :   | \$ 90,529.00           |          |
| <b>TOTAL LABOUR CHARGES</b> |                                     | :   | \$ 28,594.00           |          |
| <b>GRAND TOTAL</b>          |                                     | :   | \$ 119,123.00          |          |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME  
SURVEYED DATE  
AUTHORISED DATE  
EXCESS COST  
LIABILITY  
REMARKS

: Adrian  
: 30/11/21  
:  
:  
:  
: Not Authorised, 18 Days.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE  
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER  
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF  
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR  
APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



## Supplementary Estimate-3

Denise.

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 / Fax: 6256 4315

**Estimate No.**  
**Date**  
**Service Advisor**  
**Pages**  
**Regn No**  
**Model No**

PA/OD/0961/2021/JT  
14-Jan-22  
CHANG  
1 of 1  
SMZ 5354 E  
AUDI A5 SB 2.0 TFSI

| Quantity           | Description                      | Unit Price       | Amount       |
|--------------------|----------------------------------|------------------|--------------|
| <u>Parts</u>       |                                  |                  |              |
| 1                  | ADAPTER CABLE LOOM <i>Denyed</i> | \$ 319.00        | <i>254.8</i> |
| <b>GRAND TOTAL</b> |                                  | <b>\$ 319.00</b> |              |

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling

17/01/22

*SS*

Car-in

3/12/21

wip: 55683

Kiam / Hong

1514-1414

- 18 days

## PREMIUM AUTOMOBILES

55 HILL ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAIR@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E

|                       |                                                    | DAMAGED PARTS & PRICE |            |        |
|-----------------------|----------------------------------------------------|-----------------------|------------|--------|
| S/N                   | PARTS DESCRIPTION                                  | QTY                   | S/NETT     | REMARK |
| 1                     | FRONT BUMPER Distorted                             | 1                     | S 2,342.00 |        |
| 2                     | FRONT BUMPER SECURING STRIP Not in                 | 2                     | S 71.00    |        |
| 3                     | FRONT BUMPER GRILLE CENTER Not in                  | 1                     | S 196.00   |        |
| 4                     | FRONT BUMPER CLOSING ELEMENT - LOWER CENTER Not in | 1                     | S 262.00   |        |
| 5                     | FRONT BUMPER SPOILER Not in                        | 1                     | S 535.00   |        |
| 6                     | FRONT AIR GUIDE - LH / RH Not in                   | 2                     | S 126.00   |        |
| 7                     | FRONT BUMPER CLOSING ELEMENT Dmgd.                 | 1                     | S 262.00   | ✓ H/S  |
| 8                     | FRONT BUMPER AIR GUIDE GRILLE - LH / RH Not in     | 2                     | S 270.00   | 135    |
| 9                     | FRONT BUMPER TRIM - LH / RH Not in                 | 2                     | S 96.00    |        |
| 10                    | FRONT RADIATOR TRIM CENTER ?                       | 1                     | S 114.00   |        |
| 11                    | FRONT RADIATOR GRILLE Smashed                      | 1                     | S 1,694.00 |        |
| 12                    | FRONT RADIATOR CAP Smashed                         | 1                     | S 166.00   |        |
| 13                    | FRONT RADIATOR BRACKET Cracked                     | 1                     | S 17.00    |        |
| 14                    | FRONT RADIATOR SECURING PLATE Cracked              | 1                     | S 11.00    |        |
| 15                    | FRONT RADIATOR CAMERA Cracked                      | 1                     | S 1,141.00 |        |
| 16                    | FRONT RADIATOR GRILLE CAMERA ADAPTER ? - OR        | 1                     | S 198.00   | ✓ H/S  |
| 17                    | FRONT CAMERA ADAPTER ?                             | 1                     | S 288.00   |        |
| 18                    | FRONT BUMPER FOAM FILLER PIECE Not in              | 1                     | S 146.00   |        |
| 19                    | FRONT BUMPER REINFORCEMENT BEAM Dented             | 1                     | S 845.00   |        |
| 20                    | FRONT BUMPER GUIDE SECTION - LH / RH ?             | 2                     | S 72.00    |        |
| SUB TOTAL SPARE PARTS |                                                    |                       | S 8,852.00 |        |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) - APPROVED, REMARKS (X) - NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

Resurveyed

Adrian Li

17/01/22

H/S

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



## Supplementary Estimate-1

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0961/2021/JT

8-Dec-21

CHANG

1 of 1

SMZ 5354 E

AUDI A5 SB 2.0 TFSI

| Quantity           | Description                                                  | Unit Price  | Amount             |
|--------------------|--------------------------------------------------------------|-------------|--------------------|
| <b>Parts</b>       |                                                              |             |                    |
| 1                  | BATTERY FUSE UNIT / <i>APC</i>                               | \$ 533.00   | 426.00             |
| 2                  | 1 SET SINGLE WIRES / <i>BR</i>                               | \$ 70.00    | 51.68              |
| 3                  | OIL PRESSURE SWITCH CONNECTOR / <i>BR</i>                    | \$ 8.00     | 5.92               |
| 4                  | OIL PRESSURE SWITCH ( <i>Alu</i> ) / <i>BR</i>               | \$ 51.00    | 40.48              |
| 5                  | POLY-V-BELT / <i>CUT</i>                                     | \$ 60.00    | 47.60              |
| 6                  | BELT TENSIONER / <i>CUT</i>                                  | \$ 459.00   | 366.80             |
| 7                  | STARTER GENERATOR / <i>BT</i>                                | \$ 1,987.00 | 1,589.60           |
| 8                  | VIBRATION DAMPER ( <i>Crank pulley</i> ) / <i>BT</i>         | \$ 427.00   | 341.60             |
| 9                  | BUTT CONNECTOR / <i>APC</i>                                  | \$ 62.00    | 48.96              |
| 10                 | 1 SET SINGLE WIRES / <i>BR</i>                               | \$ 63.00    | 50.16              |
| 11                 | WINDSCREEN DEFROSTER NOZZLE GRILLE / <i>BR</i>               | \$ 123.00   | 98.40              |
| 12                 | WINDSCREEN DEFROSTER NOZZLE / <i>BR</i>                      | \$ 167.00   | 133.60             |
| 13                 | FLATCONTACT HOUSING WITH CABLE / <i>BR</i> ( <i>Alu</i> )    | \$ 186.00   | 148.80             |
| 14                 | ROUND CONNECTOR HSG WITH CABLE / <i>BR</i> ( <i>Alu</i> )    | \$ 259.00   | 206.80             |
| 15                 | FRT DOOR WINDOW SLOT SEAL - RH / <i>BT</i> ( <i>chrome</i> ) | \$ 399.00   | 318.80             |
| <b>GRAND TOTAL</b> |                                                              |             | <b>\$ 4,854.00</b> |

For Premium Automobiles Pte Ltd

*Steve (LKK)*  
*9/12/21*



Authorised Signature

Car-in

3/12/21

wip=55683

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Kiam / Hong

AIG - Aduan

- 18 days

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E

| S/N                   | PARTS DESCRIPTION                                  | QTY | DAMAGED PARTS & PRICES |          | REMARKS  |
|-----------------------|----------------------------------------------------|-----|------------------------|----------|----------|
|                       |                                                    |     | S/NETT                 |          |          |
| 1                     | FRONT BUMPER Distorted                             | 1   | \$                     | 2,342.00 | ✓        |
| 2                     | FRONT BUMPER SECURING STRIP Not in                 | 2   | \$                     | 71.00    | ✗        |
| 3                     | FRONT BUMPER GRILLE CENTER Not in                  | 1   | \$                     | 196.00   | ✗        |
| 4                     | FRONT BUMPER CLOSING ELEMENT - LOWER CENTER Not in | 1   | \$                     | 262.00   | ✗        |
| 5                     | FRONT BUMPER SPOILER Not in                        | 1   | \$                     | 535.00   | ✗        |
| 6                     | FRONT AIR GUIDE - LH / RH Not in                   | 2   | \$                     | 126.00   | ✗        |
| 7                     | FRONT BUMPER CLOSING ELEMENT Not in                | 1   | \$                     | 262.00   | ✗        |
| 8                     | FRONT BUMPER AIR GUIDE GRILLE - LH / RH LH could   | 2   | \$                     | 270.00   | 135      |
| 9                     | FRONT BUMPER TRIM - LH / RH Not in                 | 2   | \$                     | 96.00    | ✗        |
| 10                    | FRONT RADIATOR TRIM CENTER ?                       | 1   | \$                     | 114.00   | ?        |
| 11                    | FRONT RADIATOR GRILLE Smashed                      | 1   | \$                     | 1,694.00 | ✓        |
| 12                    | FRONT RADIATOR CAP Smashed                         | 1   | \$                     | 166.00   | ✓        |
| 13                    | FRONT RADIATOR BRACKET Cracked                     | 1   | \$                     | 17.00    | ✓        |
| 14                    | FRONT RADIATOR SECURING PLATE Cracked              | 1   | \$                     | 11.00    | ✓        |
| 15                    | FRONT RADIATOR CAMERA Cracked                      | 1   | \$                     | 1,141.00 | ✓        |
| 16                    | FRONT RADIATOR GRILLE CAMERA ADAPTER ? - BR        | 1   | \$                     | 198.00   | ?        |
| 17                    | FRONT CAMERA ADAPTER ?                             | 1   | \$                     | 288.00   | ?        |
| 18                    | FRONT BUMPER FOAM FILLER PIECE Cracked             | 1   | \$                     | 146.00   | ✓        |
| 19                    | FRONT BUMPER REINFORCEMENT BEAM Dented             | 1   | \$                     | 845.00   | ✓        |
| 20                    | FRONT BUMPER GUIDE SECTION - LH / RH ?             | 2   | \$                     | 72.00    | ?        |
| SUB TOTAL SPARE PARTS |                                                    |     | :                      | \$       | 8,852.00 |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAL@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E

| S/N                   | PARTS DESCRIPTION                                   | QTY | DAMAGED PARTS & PRICES |          | REMARKS |
|-----------------------|-----------------------------------------------------|-----|------------------------|----------|---------|
|                       |                                                     |     | S/NETT                 |          |         |
| 21                    | FRONT BUMPER BRACKET - LH / RH <i>BT</i>            | 2   | \$                     | 428.00   | ?       |
| 22                    | FRONT BUMPER TOP COVER <i>cracked</i>               | 1   | \$                     | 127.00   | ✓       |
| 23                    | CAUTION STICKER <i>2 nec</i>                        | 1   | \$                     | 14.00    | ✓       |
| 24                    | AIR COND STICKER                                    | 1   | \$                     | 8.00     | ✓       |
| 25                    | FRONT BUMPER LOCK CARRIER BRACKET <i>cracked</i>    | 1   | \$                     | 137.00   | ✓       |
| 26                    | FRONT BUMPER SUPPORT - LH / RH <i>cracked</i>       | 2   | \$                     | 58.00    | ✓       |
| 27                    | POP RIVET <i>per</i>                                | 4   | \$                     | 4.00     | ✓       |
| 28                    | HORN - LH / RH                                      | 2   | \$                     | 252.00   | ?       |
| 29                    | HORN SUPPORT - LH / RH                              | 2   | \$                     | 58.00    | ?       |
| 30                    | FRONT PARKING AID SENSOR - INNER / OUTER            | 4   |                        | TBC      | ?       |
| 31                    | FRONT BUMPER WIRING SET                             | 1   | \$                     | 405.00   | ?       |
| 32                    | FRONT FENDER - LH / RH <i>LH Broken, RH Dented</i>  | 2   | \$                     | 2,120.00 | ✓       |
| 33                    | FRONT FENDER ATTACHMENT PARTS <i>2 nec</i>          | 1   | \$                     | 53.00    | +       |
| 34                    | FRONT FENDER CLOSING ELEMENT - LH / RH <i>2 nec</i> | 2   | \$                     | 148.00   | +       |
| 35                    | FRONT FENDER BRACKET - LH / RH <i>BT</i>            | 2   | \$                     | 70.00    | ?       |
| 36                    | POP RIVET <i>per</i>                                | 10  | \$                     | 33.00    | ✓       |
| 37                    | FRONT FENDER BRACKET CENTER - LH / RH               | 2   | \$                     | 98.00    | ?       |
| 38                    | FRONT FENDER BRACE - LH / RH                        | 2   | \$                     | 236.00   | ?       |
| 39                    | FRONT FENDER BRACKET BACK - LH & RH                 | 2   | \$                     | 70.00    | ?       |
| 40                    | FRONT WHEEL HOUSING LINER - LH / RH <i>per nec</i>  | 2   | \$                     | 550.00   | +       |
| SUB TOTAL SPARE PARTS |                                                     | :   | \$                     | 4,869.00 |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 406699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E

| S/N                          | PARTS DESCRIPTION                                             | QTY | DAMAGED PARTS & PRICES |                 | REMARKS |
|------------------------------|---------------------------------------------------------------|-----|------------------------|-----------------|---------|
|                              |                                                               |     | S/NETT                 |                 |         |
| 41                           | FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS <i>new</i>        | 1   | \$                     | 169.00          | ✓       |
| 42                           | FRONT WHEEL SPOILER - LH / RH <i>new</i>                      | 2   | \$                     | 146.00          | ✓       |
| 43                           | FRONT SPOILER - LH / RH <i>new</i>                            | 2   | \$                     | 71.00           | ✓       |
| 44                           | FRONT STONE CHIP GUARD - LH / RH <i>new</i>                   | 2   | \$                     | 102.00          | ✓       |
| 45                           | FRONT FENDER TRIM - LH / RH <i>new</i>                        | 2   | \$                     | 328.00          | ✓       |
| 46                           | <b>BONNET</b> <i>Distorted</i>                                | 1   | \$                     | 3,312.00        | ✓       |
| 47                           | BONNET ATTACHEMENT PARTS <i>new</i>                           | 1   | \$                     | 123.00          | ✓       |
| 48                           | BONNET HINGE (LH / RH) <i>new</i>                             | 2   | \$                     | 838.00          | ✓       |
| 49                           | <b>BONNET IMPACT PROTECTION - CENTER / LH / RH</b> <i>new</i> | 3   | \$                     | 84.00           | ✓       |
| 50                           | <b>BONNET SOUND ABSORBER</b> <i>crushed</i>                   | 1   | \$                     | 343.00          | ✓       |
| 51                           | <b>BONNET STRIKER - LH / RH</b> <i>BR</i>                     | 2   | \$                     | 100.00          | ✓       |
| 52                           | <b>BONNET LOCK</b> <i>BR</i>                                  | 2   | \$                     | 427.00          | ✓       |
| 53                           | <b>BONNET BOWDEN CABLE - CENTER</b> <i>BR</i>                 | 1   | \$                     | 58.00           | ✓       |
| 54                           | BONNET RELEASE LEVER <i>new</i>                               | 1   | \$                     | 14.00           | ✓       |
| 55                           | <b>BONNET BOWDEN CABLE INNER - CENTER</b> <i>BR</i>           | 1   | \$                     | 58.00           | ✓       |
| 56                           | BONNET LOCK CABLE <i>BR</i>                                   | 1   | \$                     | 74.00           | ✓       |
| 57                           | BONNET FLAT CONNECTOR                                         | 1   | \$                     | 13.00           | ✓       |
| 58                           | FRONT LEDGE LONG COVER (INNER / OUTER) <i>BR</i>              | 2   | \$                     | 72.00           | ✓       |
| 59                           | FRONT LEDGE SHORT COVER - INNER / OUTER                       | 2   | \$                     | 32.00           | ✓       |
| 60                           | <b>HEADLAMPS COVER - LH / RH</b> <i>crushed</i>               | 2   | \$                     | 88.00           | ✓       |
| <b>SUB TOTAL SPARE PARTS</b> |                                                               |     | \$                     | <b>6,452.00</b> |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6341 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E**

|                       |                                                 |     | DAMAGED PARTS & PRICES |         |
|-----------------------|-------------------------------------------------|-----|------------------------|---------|
| S/N                   | PARTS DESCRIPTION                               | QTY | S/NETT                 | REMARKS |
| 61                    | FRONT FENDER LEDGE COVER - LH / RH ?            | 2   | \$ 144.00              | ?       |
| 62                    | PLENUM CHAMBER <i>new</i>                       | 1   | \$ 97.00               | +       |
| 63                    | GAS FILLED STRUT <i>new</i>                     | 2   | \$ 241.00              | +       |
| 64                    | HEADLIGHT MATRIX BEAM - LH / RH <i>Graded</i>   | 2   | \$ 15,370.00           | ✓       |
| 65                    | HEADLIGHT HOSE <i>new</i>                       | 2   | \$ 71.00               | +       |
| 66                    | COMPENSATING PIECE ? <i>BR (Headlight)</i>      | 6   | \$ 243.00              | ?       |
| 67                    | LIFT CYLINDER - LH / RH ?                       | 2   | \$ 396.00              | ?       |
| 68                    | LIFT CYLINDER BRACKET - LH / RH ?               | 2   | \$ 30.00               | ?       |
| 69                    | LIFT CYLINDER HOSE <i>new</i>                   | 1   | TBC                    | x       |
| 70                    | RADIATOR COOLANT LOCK CARRIER <i>Graded</i>     | 1   | \$ 1,016.00            | ✓       |
| 71                    | RADIATOR COOLANT SUPPORT <i>BR</i>              | 2   | \$ 76.00               | ✓       |
| 72                    | FLUID RESERVOIR A/C CONDENSER <i>Dented</i>     | 1   | \$ 622.00              | ✓       |
| 73                    | REFRIGERANT PRESSURE SENSOR ?                   | 1   | \$ 186.00              | ?       |
| 74                    | REFRIGERANT HIGH PRESSURE SWITCH ?              | 1   | \$ 51.00               | ?       |
| 75                    | REFRIGERANT SUCTION HOSE ?                      | 1   | \$ 167.00              | ?       |
| 76                    | REFRIGERANT DISCHARGE HOSE ?                    | 1   | \$ 340.00              | ?       |
| 77                    | REFRIGERANT COOLANT PIPE ?                      | 1   | \$ 248.00              | ?       |
| 78                    | OUTSIDE TEMPERATURE SENSOR BRACKET ? <i>MIS</i> | 1   | \$ 19.00               | ?       |
| 79                    | OUTSIDE TEMPERATURE SENSOR ?                    | 1   | \$ 59.00               | ?       |
| 80                    | AIR COOLER CHARGED <i>new</i>                   | 1   | \$ 587.00              | ?       |
| SUB TOTAL SPARE PARTS |                                                 |     | \$ 19,963.00           |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55, UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E**

|                       |                                            |     | DAMAGED PARTS & PRICES |         |
|-----------------------|--------------------------------------------|-----|------------------------|---------|
| S/N                   | PARTS DESCRIPTION                          | QTY | S/NETT                 | REMARKS |
| 81                    | AIR COOLER PRESSURE HOSE OUTER - RH ?      | 1   | \$ 357.00              | ?       |
| 82                    | AIR COOLER PRESSURE HOSE INNER - RH ?      | 1   | \$ 427.00              | ?       |
| 83                    | RADIATOR COOLER ? - BT                     | 1   | \$ 655.00              | ?       |
| 84                    | RADIATOR CONTROL UNIT ? - DD               | 1   | \$ 1,880.00            | ?       |
| 85                    | RADIATOR RING ? - BR                       | 1   | \$ 220.00              | ?       |
| 86                    | RADIATOR COOLANT New                       | 6   | \$ 266.00              | ✓       |
| 87                    | A/C COMPRESSOR OIL ?                       | 1   | \$ 622.00              | ?       |
| 88                    | RADIATOR AIR GUIDE OUTER - LH / RH         | 2   | \$ 64.00               | ✓       |
| 89                    | RADIATOR AIR GUIDE INNER - UPPER / LH / RH | 3   | \$ 48.00               | ✓       |
| 90                    | RADIATOR AIR GUIDE LOWER                   | 1   | \$ 22.00               | ✓       |
| 91                    | RADIATOR COOLANT UPPER HOSE ?              | 1   | \$ 71.00               | ?       |
| 92                    | RADIATOR CONNECTOR TUBE ?                  | 1   | \$ 54.00               | ?       |
| 93                    | RADIATOR COOLANT INLET ?                   | 1   | \$ 71.00               | ?       |
| 94                    | RADIATOR COOLANT HOSE ?                    | 1   | \$ 22.00               | ?       |
| 95                    | RADIATOR COOLANT HOSE ?                    | 1   | \$ 34.00               | ?       |
| 96                    | RADIATOR BREATHER TUBE ?                   | 1   | \$ 53.00               | ?       |
| 97                    | RADIATOR BREATHER TUBE UPPER ?             | 1   | \$ 40.00               | ?       |
| 98                    | RADIATOR VENT HOSE UPPER CENTER ?          | 1   | \$ 277.00              | ?       |
| 99                    | ENGINE TIMING CASE COVER - BOTTOM ?        | 1   | \$ 240.00              | ?       |
| 99                    | ENGINE TIMING CASE COVER - UPPER ? BR      | 1   | \$ 338.00              | ?       |
| 100                   | CAMSHAFT MAGNET ADJUSTER ?                 | 2   | \$ 338.00              | ?       |
| SUB TOTAL SPARE PARTS |                                            |     | \$ 5,761.00            |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E**

| S/N                          | PARTS DESCRIPTION                     | QTY | DAMAGED PARTS & PRICES |                  | REMARKS |
|------------------------------|---------------------------------------|-----|------------------------|------------------|---------|
|                              |                                       |     | S/NETT                 |                  |         |
| 101                          | THROTTLE VALVE ADAPTER                | 1   | \$                     | 1,036.00         | ?       |
| 102                          | THROTTLE INTAKE AIR DUCT - RH         | 1   | \$                     | 22.00            | ?       |
| 103                          | THROTTLE AIR GUIDE                    | 1   | \$                     | 53.00            | ?       |
| 104                          | AIR FILTER                            | 1   | \$                     | 386.00           |         |
| 105                          | THROTTLE INTAKE HOSE                  | 1   | \$                     | 95.00            |         |
| 106                          | FRONT AIR MASS METER                  | 1   | \$                     | 567.00           |         |
| 107                          | INTAKE MANIFOLD                       | 1   | \$                     | 856.00           |         |
| 108                          | EXHAUST GAS TURBOCHARGER              | 1   | \$                     | 5,405.00         | +       |
| 109                          | FRONT WINDSCREEN                      | 1   | \$                     | 1,461.00         | ✓       |
| 110                          | FRONT RAIN SENSOR GEL FOIL            | 1   | \$                     | 137.00           | ✓       |
| 111                          | FRONT RETAINING SPRING                | 1   | \$                     | 21.00            | ✓       |
| 112                          | FRONT SPRING CLIP                     | 1   | \$                     | 21.00            | ✓       |
| 113                          | FRONT CAMERA SILICONE PAD             | 1   | \$                     | 98.00            | ✓       |
| 114                          | PRIMER                                | 1   | \$                     | 20.00            | ✓       |
| 115                          | FRONT WATER DEFLECTOR STRIP - LH / RH | 2   | \$                     | 134.00           | +       |
| 116                          | FRONT DOOR - RH                       | 1   | \$                     | 3,884.00         | ✓       |
| 117                          | FRONT DOOR OUTER SEAL - RH            | 1   | \$                     | 222.00           | +       |
| 118                          | BONDING AGENT                         | 1   | \$                     | 49.00            | +       |
| 119                          | CLEANING SOLUTION                     | 1   | \$                     | 68.00            | +       |
| 120                          | APPLICATOR                            | 1   | \$                     | 8.00             | +       |
| <b>SUB TOTAL SPARE PARTS</b> |                                       | :   | \$                     | <b>14,543.00</b> |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E

| S/N                   | PARTS DESCRIPTION                                      | QTY | DAMAGED PARTS & PRICES |         |
|-----------------------|--------------------------------------------------------|-----|------------------------|---------|
|                       |                                                        |     | S/NETT                 | REMARKS |
| 121                   | FRONT DOOR CATCH - RH <i>new</i>                       | 1   | \$ 120.00              | ✓       |
| 122                   | FRONT TYRE PRESSURE DATA PLATE <i>new</i>              | 1   | \$ 37.00               | +       |
| 123                   | FRONT DOOR TRIM - LH / RH <i>new RH new</i>            | 2   | \$ 328.00              | ✓ 164   |
| 124                   | AIRBAG <i>{ Activated</i>                              | 1   | \$ 3,682.00            | ✓       |
| 125                   | AIRBAG UNIT                                            | 1   | \$ 4,374.00            | ✓       |
| 126                   | AIRBAG HEAD UNIT - LH / RH <i>{ Activated</i>          | 2   | \$ 3,726.00            | ✓       |
| 127                   | AIRBAG CONTROL UNIT                                    | 1   | \$ 2,112.00            | ✓       |
| 128                   | AIRBAG CRASH SENSOR                                    | 3   | TBC                    | ✓       |
| 129                   | STEERING WHEEL <i>ut</i>                               | 1   | \$ 2,374.00            | ✓       |
| 130                   | FRONT DASHBOARD <i>for</i>                             | 1   | \$ 5,289.00            | ✓       |
| 131                   | FRONT MOULDED HEADLINER <i>compd Activated</i>         | 1   | \$ 2,048.00            | ✓       |
| 132                   | FRONT SEAT BELT TENSIONER - LH / RH <i>{ Activated</i> | 2   | \$ 2,206.00            | ✓       |
| 133                   | FRONT SEAT BELT ADJUSTER - LH / RH                     | 2   | \$ 342.00              | ?       |
| 134                   | FRONT GRAB HANDLE                                      | 2   | \$ 283.00              | ?       |
| 135                   | REAR GRAB HANDLE - LH / RH                             | 2   | \$ 284.00              | ?       |
| 136                   | A-PILLAR TRIM - LH / RH                                | 2   | \$ 408.00              | ?       |
| 137                   | B-PILLAR TRIM UPPER - LH / RH <i>new</i>               | 2   | \$ 470.00              | ✓       |
| 138                   | C-PILLAR TRIM - LH / RH                                | 2   | \$ 298.00              | ?       |
| 139                   | D-PILLAR TRIM - LH / RH                                | 2   | \$ 408.00              | ?       |
| 140                   | FRONT NO PLATE <i>Missing</i>                          | S/N | \$ 100.00              | ✓       |
| SUB TOTAL SPARE PARTS |                                                        | :   | \$ 28,889.00           |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

1) Supp Add 8W0 915 459 E five unit .X/ 533

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E**

| S/N                  | PARTS DESCRIPTION                  | QTY | DAMAGED PARTS & PRICES |         |
|----------------------|------------------------------------|-----|------------------------|---------|
|                      |                                    |     | S/NETT                 | REMARKS |
| 141                  | FRONT WINDSCREEN SEALANT <i>Nu</i> | S/N | \$ 200.00              | ✓       |
| 142                  | SUNDRIES                           |     | \$ 1,000.00            | ?       |
| TOTAL SPARE PARTS    |                                    | :   | \$ 90,529.00           |         |
| TOTAL LABOUR CHARGES |                                    | :   | \$ 28,594.00           |         |
| GRAND TOTAL          |                                    | :   | \$ 119,123.00          |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.