



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0961/2021/JT
DATE : 29-Nov-21
WIP : 55683

Denise .

\$78353.92 .

18 Days .

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/11/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ZHANG XIAO
ADDRESS : BLK 305A PUNGGOL ROAD
#03-707
SINGAPORE 821305
TELEPHONE : HP +65 96314702
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210040873
VEHICLE NO : SMZ 5354 E
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 30/4/2021
ENGINE NO : DEM 031628
CHASSIS NO : WAUZZZF5XMA039440
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Nov-21
PLACE OF ACCIDENT : ALONG CTE TOWARDS SLE AFTER
BALESTIER ROAD

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 5354 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N AIG	X
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$ 800.00	X
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
4	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR, CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 2,200.00	✓
5	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS.	S/N \$ 3,600.00	✓
6	TO PLACE VEHICLE ON CAR O-LINER	S/N \$ 2,400.00	X
SUB TOTAL LABOUR CHARGES		: \$ 9,480.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 5354 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY LHS FRONT DOOR.	S/N \$	280.00	X
8	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00	280 ✓
9	TO RENEW ENGINE THROTTLE BODY AND OTHER ENGINE COMPONENTS.	S/N \$	780.00	✓
10	TO RENEW FRONT WINDSCREEN.	S/N \$	480.00	✓
11	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$	400.00	✓
12	TO CARRY OUT WATER SEEPAGE TEST ON FRONT WINDSCREEN.	S/N \$	200.00	150 ✓
SUB TOTAL LABOUR CHARGES		:	\$ 2,490.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 5354 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS, RHS FRONT DOOR AND BOTH HEADLIGHTS. TO REPAIR BOTH UPPER A-PILLAR. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓ ✓ ✓	S 8,000.00	4000 4500
14	✓ TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH UPPER A-PILLAR AND BOTH FRONT DOORS. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT. ✓	S 8,000.00	3300 ✓
15	TO CARRY OUT PRE WHEEL ALIGNMENT TEST. S/N S	240.00	7X
16	TO CARRY OUT PRE-REPAIR DIAGNOSTIC CHECK AND POST-REPAIR DIAGNOSTIC CHECK. S/N S	384.00	192. ✓
TOTAL LABOUR CHARGES		: \$ 28,594.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Distorted</i>	1	S 2,342.00 ✓	1,873.60	
2	FRONT BUMPER SECURING STRIP <i>Not new</i>	2	S 71.00 ✗		
3	FRONT BUMPER GRILLE CENTER <i>Not new</i>	1	S 196.00 ✗		
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>Not new</i>	1	S 262.00 ✗		
5	FRONT BUMPER SPOILER <i>Not new</i>	1	S 535.00 ✗		
6	FRONT AIR GUIDE - LH / RH <i>Not new</i>	2	S 126.00 ✗		
7	FRONT BUMPER CLOSING ELEMENT <i>Not new</i>	1	S 262.00 ✗	209.20	
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Not new</i>	2	S 270.00 135	108.00	
9	FRONT BUMPER TRIM - LH / RH <i>Not new</i>	2	S 96.00 ✗		
10	FRONT RADIATOR TRIM CENTER <i>Not new</i>	1	S 114.00 ✗		
11	FRONT RADIATOR GRILLE <i>Smashed</i>	1	S 1,694.00 ✓	1132.80	
12	FRONT RADIATOR CAP <i>Smashed</i>	1	S 166.00 ✓	132.80	
13	FRONT RADIATOR BRACKET <i>Crushed</i>	1	S 17.00 ✓	12.96	
14	FRONT RADIATOR SECURING PLATE <i>Crushed</i>	1	S 11.00 ✓	8.08	
15	FRONT RADIATOR CAMERA <i>Crushed</i>	1	S 1,141.00 ✓	912.80	
16	FRONT RADIATOR GRILLE CAMERA ADAPTER <i>? BROKEN</i>	1	S 198.00 ?	158.40	
17	FRONT CAMERA ADAPTER <i>Not new</i>	1	S 288.00 ✗		
18	FRONT BUMPER FOAM FILLER PIECE <i>Crushed</i>	1	S 146.00 ✓	99.20	
19	FRONT BUMPER REINFORCEMENT BEAM <i>Distorted</i>	1	S 845.00 ✓	675.60	
20	FRONT BUMPER GUIDE SECTION - LH / RH <i>Distorted</i>	2	S 72.00 ?	57.44V	
SUB TOTAL SPARE PARTS		:	\$ 8,852.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER BRACKET - LH / RH <i>BENT</i>	2 S	428.00	✓ 342.40
22	FRONT BUMPER TOP COVER <i>cracked</i>	1 S	127.00	✓ 101.60
23	CAUTION STICKER <i>3 Nec</i>	1 S	14.00	✓ 12.40
24	AIR COND STICKER	1 S	8.00	✓ 6.64
25	FRONT BUMPER LOCK CARRIER BRACKET <i>cracked</i>	1 S	137.00	✓ 109.60
26	FRONT BUMPER SUPPORT - LH / RH <i>cracked</i>	2 S	58.00	✓ 44.96
27	POP RIVET <i>per</i>	4 S	4.00	✓ 2.56
28	HORN - LH / RH <i>3 Not Nec</i>	2 S	252.00	X
29	HORN SUPPORT - LH / RH	2 S	58.00	X
30	FRONT PARKING AID SENSOR - INNER / OUTER <i>3 Not Nec</i>	4	TBC	X
31	FRONT BUMPER WIRING SET	1 S	405.00	X
32	FRONT FENDER - LH / RH <i>LH Broken, RH Dented</i>	2 S	2,120.00	✓ 1,696.00
33	FRONT FENDER ATTACHEMENT PARTS <i>3 Nec</i>	1 S	53.00	X
34	FRONT FENDER CLOSING ELEMENT - LH / RH <i>NEC</i>	2 S	148.00	X 118.08
35	FRONT FENDER BRACKET - LH / RH <i>BENT</i>	2 S	70.00	✓ 55.84
36	POP RIVET <i>Nec</i>	10 S	33.00	✓ 26.40
37	FRONT FENDER BRACKET CENTER - LH / RH <i>Not Nec</i>	2 S	98.00	X
38	FRONT FENDER BRACE - LH / RH <i>3 Not Nec</i>	2 S	236.00	X
39	FRONT FENDER BRACKET BACK - LH & RH	2 S	70.00	X
40	FRONT WHEEL HOUSING LINER - LH / RH <i>Not Nec</i>	2 S	550.00	X
SUB TOTAL SPARE PARTS			\$ 4,869.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS <i>new</i>	1	\$ 169.00	<i>L</i>
42	FRONT WHEEL SPOILER - LH / RH <i>new</i>	2	\$ 146.00	<i>L</i>
43	FRONT SPOILER - LH / RH <i>new</i>	2	\$ 71.00	<i>X</i>
44	FRONT STONE CHIP GUARD - LH / RH <i>new</i>	2	\$ 102.00	<i>X</i>
45	FRONT FENDER TRIM - LH / RH <i>new</i>	2	\$ 328.00	262.40
46	BONNET <i>Distorted</i>	1	\$ 3,312.00	2,649.60
47	BONNET ATTACHEMENT PARTS <i>new</i>	1	\$ 123.00	<i>X</i>
48	BONNET HINGE - LH / RH <i>new</i>	2	\$ 838.00	<i>X</i>
49	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>new</i>	3	\$ 84.00	65.68
50	BONNET SOUND ABSORBER <i>crushed</i>	1	\$ 343.00	274.40
51	BONNET STRIKER - LH / RH <i>damaged</i>	2	\$ 100.00	79.84
52	BONNET LOCK <i>damaged</i>	2	\$ 427.00	341.30
53	BONNET BOWDEN CABLE - CENTER <i>damaged</i>	1	\$ 58.00	46.00
54	BONNET RELEASE LEVER <i>new</i>	1	\$ 14.00	<i>X</i>
55	BONNET BOWDEN CABLE INNER - CENTER <i>damaged</i>	1	\$ 58.00	46.00
56	BONNET LOCK CABLE <i>damaged</i>	1	\$ 74.00	58.64
57	BONNET FLAT CONNECTOR <i>new</i>	1	\$ 13.00	<i>X</i>
58	FRONT LEDGE LONG COVER - INNER / OUTER <i>BROKEN</i>	2	\$ 72.00	56.48
59	FRONT LEDGE SHORT COVER - INNER / OUTER <i>new</i>	2	\$ 32.00	<i>X</i>
60	HEADLAMPS COVER - LH / RH <i>crushed</i>	2	\$ 88.00	68.96
SUB TOTAL SPARE PARTS		:	\$ 6,452.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT FENDER LEDGE COVER - LH / RH <i>None</i>	2	\$ 144.00	X
62	PLENUM CHAMBER <i>None</i>	1	\$ 97.00	X
63	GAS FILLED STRUT <i>None</i>	2	\$ 241.00	X
64	HEADLIGHT MATRIX BEAM - LH / RH <i>Cracked</i>	2	\$ 15,370.00	✓ 12,296.00
65	HEADLIGHT HOSE <i>None</i>	2	\$ 71.00	X
66	COMPENSATING PIECE ? BROKEN	6	\$ 243.00	> 193.28
67	LIFT CYLINDER - LH / RH <i>None</i>	2	\$ 396.00	X
68	LIFT CYLINDER BRACKET - LH / RH <i>None</i>	2	\$ 30.00	? 12.32
69	LIFT CYLINDER HOSE <i>None</i>	1	TBC	X
70	RADIATOR COOLANT LOCK CARRIER <i>Cracked</i>	1	\$ 1,016.00	✓ 812.80
71	RADIATOR COOLANT SUPPORT - LH / RH BROKEN	2	\$ 76.00	60.64
72	FLUID RESERVOIR A/C CONDENSER <i>Dented</i>	1	\$ 622.00	✓ 497.60
73	REFRIGERANT PRESSURE SENSOR <i>None</i>	1	\$ 186.00	X
74	REFRIGERANT HIGH PRESSURE SWITCH <i>None</i>	1	\$ 51.00	X
75	REFRIGERANT SUCTION HOSE	1	\$ 167.00	X
76	REFRIGERANT DISCHARGE HOSE <i>None</i>	1	\$ 340.00	X
77	REFRIGERANT COOLANT PIPE	1	\$ 248.00	X
78	OUTSIDE TEMPERATURE SENSOR BRACKET ? MISSING	1	\$ 19.00	? 14.56
79	OUTSIDE TEMPERATURE SENSOR <i>None</i>	1	\$ 59.00	X
80	AIR COOLER CHARGED <i>None</i>	1	\$ 587.00	X
SUB TOTAL SPARE PARTS		:	\$ 19,963.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	AIR COOLER PRESSURE HOSE OUTER - RH	1 S	357.00	X
82	AIR COOLER PRESSURE HOSE INNER - RH	1 S	427.00	X
83	RADIATOR COOLER BENT	1 S	655.00	? 523.60
84	RADIATOR CONTROL UNIT DENTED	1 S	1,880.00	? 1,548.00
85	RADIATOR RING BROKEN	1 S	220.00	? 176.00
86	RADIATOR COOLANT	6 S	266.00	✓ 212.64
87	A/C COMPRESSOR OIL	1 S	622.00	?
88	RADIATOR AIR GUIDE OUTER - LH / RH	2 S	64.00	✓ 52.64
89	RADIATOR AIR GUIDE INNER - UPPER / LH / RH	3 S	48.00	✓ 39.84
90	RADIATOR AIR GUIDE LOWER	1 S	22.00	✓ 17.20
91	RADIATOR COOLANT UPPER HOSE	1 S	71.00	X
92	RADIATOR CONNECTOR TUBE	1 S	54.00	X
93	RADIATOR COOLANT INLET	1 S	71.00	X
94	RADIATOR COOLANT HOSE	1 S	22.00	X
95	RADIATOR BREATHER TUBE	1 S	34.00	? 26.88
96	RADIATOR BREATHER TUBE UPPER	1 S	53.00	X
97	RADIATOR VENT HOSE UPPER CENTER	1 S	40.00	X
98	ENGINE TIMING CASE COVER - BOTTOM	1 S	277.00	X
99	ENGINE TIMING CASE COVER - UPPER	1 S	240.00	? 191.60
100	CAMSHAFT MAGNET ADJUSTER	2 S	338.00	X
SUB TOTAL SPARE PARTS			: \$	5,761.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
101	THROTTLE VALVE ADAPTER <i>Neu</i>	1	\$ 1,036.00	?	
102	THROTTLE INTAKE AIR DUCT - RH <i>? BROKEN</i>	1	\$ 22.00	?	17.20
103	THROTTLE AIR GUIDE <i>? BROKEN</i>	1	\$ 53.00	?	42.40
104	AIR FILTER	1	\$ 386.00	} ? x.	
105	THROTTLE INTAKE HOSE	1	\$ 95.00		
106	FRONT AIR MASS METER	1	\$ 567.00		
107	INTAKE MANIFOLD	1	\$ 856.00		
108	EXHAUST GAS TURBOCHARGER <i>Neu</i>	1	\$ 5,405.00	+	
109	FRONT WINDSCREEN <i>cracked</i>	1	\$ 1,461.00	✓	1,168.80
110	FRONT RAIN SENSOR GEL FOIL	1	\$ 137.00	✓	109.20
111	FRONT RETAINING SPRING	1	\$ 21.00	✓	16.56
112	FRONT SPRING CLIP	1	\$ 21.00	✓	16.56
113	FRONT CAMERA SILICONE PAD	1	\$ 98.00	✓	77.68
114	PRIMER <i>Neu</i>	1	\$ 20.00	✓	15.76
115	FRONT WATER DEFLECTOR STRIP - LH / RH <i>Neu</i>	2	\$ 134.00	+	
116	FRONT DOOR - RH <i>Dented</i>	1	\$ 3,884.00	✓	3,107.20
117	FRONT DOOR OUTER SEAL - RH <i>NEC</i>	1	\$ 222.00	+	177.60
118	BONDING AGENT	1	\$ 49.00	+	
119	CLEANING SOLUTION	1	\$ 68.00	+	
120	APPLICATOR	1	\$ 8.00	+	
SUB TOTAL SPARE PARTS		:	\$ 14,543.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
121	FRONT DOOR CATCH - RH <i>new</i>	1	S 120.00	X
122	FRONT TYRE PRESSURE DATA PLATE <i>new</i>	1	S 37.00	X
123	FRONT DOOR TRIM - LH / RH <i>new RH new</i>	2	S 328.00	164 X.
124	AIRBAG <i>{ Activated</i>	1	S 3,682.00	✓ 2,945.60
125	AIRBAG UNIT <i>{ Activated</i>	1	S 4,374.00	✓ 3,499.20
126	AIRBAG HEAD UNIT - LH / RH <i>{ Activated</i>	2	S 3,726.00	✓ 2,980.80
127	AIRBAG CONTROL UNIT <i>{ Activated</i>	1	S 2,112.00	✓ 1,689.60
128	AIRBAG CRASH SENSOR	3	382.00 TBC	✓ 916.80
129	STEERING WHEEL <i>lt</i>	1	S 2,374.00	✓ 1,899.20
130	FRONT DASHBOARD <i>for</i>	1	S 5,289.00	✓ 4,231.20
131	FRONT MOULDED HEADLINER <i>compd Activated</i>	1	S 2,048.00	✓ 1,638.40
132	FRONT SEAT BELT TENSIONER - LH / RH <i>{ Activated</i>	2	S 2,206.00	✓ 1,764.80
133	FRONT SEAT BELT ADJUSTER - LH / RH <i>{ Activated</i>	2	S 342.00	? 273.60
134	FRONT GRAB HANDLE <i>{ Damaged</i>	2	S 283.00	? 226.40
135	REAR GRAB HANDLE - LH / RH	2	S 284.00	? 226.40
136	A-PILLAR TRIM - LH / RH <i>lt.</i>	2	S 408.00	? 326.40
137	B-PILLAR TRIM UPPER - LH / RH <i>new</i>	2	S 470.00	X
138	C-PILLAR TRIM - LH / RH <i>{ new</i>	2	S 298.00	X
139	D-PILLAR TRIM - LH / RH <i>{ new</i>	2	S 408.00	X
140	FRONT NO PLATE <i>Missing</i>	S/N	S 100.00	✓ 100
SUB TOTAL SPARE PARTS			S 28,889.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 5354 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
141	FRONT WINDSCREEN SEALANT <i>Nw</i>	S/N	\$ 200.00	✓	200
142	SUNDRIES <i>Nec</i>		\$ 1,000.00	?	251.10
TOTAL SPARE PARTS			:	\$ 90,529.00	
TOTAL LABOUR CHARGES			:	\$ 28,594.00	
GRAND TOTAL			:	\$ 119,123.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

:
:
:
:
:
:

Adrian Ly
30/11/21

Not Authorised, 18 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT