

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CS/AIG21012190/EQF3Q2

Date:

20/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

7210023177

Claimant Vehicle No : SMF8737U**Insured Vehicle No :**

SGE1123M

Date of Loss: 28/11/2021

Nature of Claim:

TP

Claim No:

7025525061SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMF8737U**

Make & Model: NISSAN SYLPHY, 1.5 (A)

Engine No:

HR16934868C

Reg. Date: 28/11/2018 (Man. Year: 2018)

Chassis No:

MNTBBAB17Z0033529

Colour: Blue

Odometer:

71967 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 285/55 R16

Rear Tyre Size:

285/55 R16

Front Left Side: Nexen 4 mm

Rear Left Side:

Nexen 4 mm

Front Right Side: Nexen 4 mm

Rear Right Side:

Nexen 4 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,457.70	3,068.30	5,389.40	63.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	2,020.00	710.00	26.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,187.70	5,088.30	6,099.40	54.52
Approved Total (Overridden) (S\$)		4,050.00		

Nett Amount (S\$)**11,187.70****4,050.00****7,137.70****63.80**INSPECTION

Date of Assignment: 01/12/2021

Date Inspected: 01/12/2021 Inspected At:

Win Automotive Services (HQ)
BLK 6 WOODLANDS ROAD, 399J YEW TEE INDUSTRIAL ESTATE
Singapore 678008

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT DOOR	Dented	1,130.00 FL	*961.00 FL
2	2		*LH FRONT DOOR HINGES	Not Necessary	115.00 FL	*- FL
3	1		*LH FRONT DOOR INNER LOCK	Not Necessary	188.00 FL	*- FL
4	1		*LH FRONT DOOR WEATHERSTRIP	Not Necessary	155.00 FL	*- FL
5	1		*LH FRONT DOOR GLASS REGULATOR	Not Necessary	95.00 FL	*- FL
6	1		*LH FRONT DOOR GLASS REGULATOR MOTOR	Not Necessary	520.00 FL	*- FL
7	1		*LH FRONT DOOR GLASS OUTER MOULDING	Not Necessary	115.00 FL	*- FL
8	1		*LH FRONT DOOR GLASS CHANNEL	Not Necessary	218.00 FL	*- FL
9	1		*LH FRONT DOOR FRAME STICKER	Necessary	35.00 FL	*35.00 FL
10	1		*LH FRONT DOOR CHECKER	Not Necessary	60.00 FL	*- FL
11	1		*LH REAR DOOR	Dented	1,050.00 FL	*943.00 FL
12	2		*LH REAR DOOR HINGES	Not Necessary	115.00 FL	*- FL
13	1		*LH REAR DOOR INNER LOCK	Jammed	188.00 FL	*188.00 FL
14	1		*LH REAR DOOR WEATHERSTRIP	Not Necessary	155.00 FL	*- FL
15	1		*LH REAR DOOR GLASS REGULATOR	Not Necessary	95.00 FL	*- FL
16	1		*LH REAR DOOR GLASS REGULATOR MOTOR	Not Necessary	520.00 FL	*- FL
17	1		*LH REAR DOOR OUTER MOULDING	Not Necessary	115.00 FL	*- FL
18	1		*LH REAR DOOR GLASS CHANNEL	Not Necessary	218.00 FL	*- FL
19	1		*LH REAR DOOR FRAME STICKERS	Necessary	35.00 FL	*35.00 FL
20	1		*LH REAR DOOR CHECKER	Not Necessary	60.00 FL	*- FL
21	1		*LH REAR DOOR INNER TRIM BOARD	Not Necessary	388.00 FL	*- FL
22	1		*LH REAR DOOR INNER TRIM BOARD FASTENERS	Not Necessary	35.00 FL	*- FL
23	1		*LH REAR LOWER ARM	Not Necessary	280.00 FL	*- FL
24	1		*LH REAR WHEEL BEARING	Jammed	280.00 FL	*280.00 FL
25	1		*LH REAR ABSORBER	Not Necessary	368.00 FL	*- FL
26	1		*LH REAR KNUCKLE ARM	Not Necessary	420.00 FL	*- FL
27	1		*REAR BUMPER	Broken	500.00 FL	*500.00 FL
28	1		*REAR BUMPER SIDE RETAINER	Broken	45.00 FL	*45.00 FL
29	1		*REAR LH FENDER	Repair	880.00 FL	*- FL
30	1		*REAR LH FENDER INNER SHIELD	Not Necessary	155.00 FL	*- FL
31	1		*REAR LH FENDER INNER SHIELD FASTENERS	Not Necessary	20.00 FL	*- FL
32	1		*REAR ORIGINAL NISSAN RIM	Cut	350.00 FS	*300.00 FS
33	1		*REAR LEFT TYRE	Not Necessary	250.00 FS	*- FS
34	1		*LH FRONT DOOR SEALANT	Necessary	80.00 FS	*40.00 FS
35	1		*LH REAR DOOR SEALANT	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					9,313.00	3,367.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					855.30	298.70
Total Parts (\$\$)					8,457.70	3,068.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS	New	800.00	700.00
2	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY REPLACED AND OTHER AFFECTED PANELS	New	1,000.00	1,000.00
3	TO REMOVE N REPLACE DOOR COMPONENTS FRONT AND REAR	New	200.00	100.00
4	TO CHECK WIRING SYSTEM FOR PROPER FUNCTIONS	New	60.00	30.00
5	TO REMOVE & REPLACE REAR UNDERCARRIAGE PARTS ITEM	New	250.00	100.00
6	TO CARRY OUT ANTI RUST TREATMENT	New	100.00	30.00
7	TO CARRY OUT 4 WHEEL ALIGNMENT TO SPECIFICATIONS	New	100.00	60.00
8	TO REMOVE AND REINSTALL FRONT AND REAR SEAT UPHOLSTERY	New	120.00	0.00
9	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	100.00	0.00
Gross Labour Cost (\$\$)			2,730.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >