

REC BY: Steve | Ref: CS/A1621012190/Eqf3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No: _____
Claims No: 7025525061SG
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: _____ % 3-Val.: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMF87374 Yr Regn: 28/11/18
Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Nissan Sylphy c.c. 1598
Colour: Blue A/C: _____ Insured / Std / NI / NA
Sp. Reading: 71967 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MNTBBAB1720033579
Gen. Cond: Good / ☒ Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rlm / STD A/Rlm or
Tyre Size: F: 205/55R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Nexen
Front Rear
R/Bal. 4 mm R/Bal. 4 mm
L/Bal. 4 mm L/Bal. 4 mm
D.O.A. 28/11/21 D.O.I. 1/12/21
Survey held at Win Automotive
Des. of Damages: Frl / Rear / O/S ☒ N/S / U/C / Roof/tp or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV-66K
	Steve finalised LS \$4050, 5 days (Red \$7137.70, 64%)

Date/Time, File Pass to? ☐ : Prelim. Report
16/12 Typist ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: 5
Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Inve (\$ _____)
☐ : Wash and _____

Survey Fee:	
Transportation:	
\$ + RS. \$:	
Printing:	
Other:	
TOTAL:	

Report Form: MER-TP
Lump Sum: 4050

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SMF 8737L

Adjustment of Spare Parts Costs for Repairs

Item	Qty	Vehicle parts description	Condition / Remark	Estimated by workshop
1	1	LH front door / DD		1130.00
2	2	LH Front door hinges X		115.00
3	1	LH Front door inner lock X		188.00
4	1	LH Front door weatherstrip X		155.00
5	1	LH Front door glass regulator X		95.00
6	1	LH Front door glass regulator motor X		520.00
7	1	LH Front door glass outer moulding X		115.00
8	1	LH Front door glass channel X		218.00
9	1	LH Front door frame sticker / nec		35.00
10	1	LH front door checker X		60.00
11	1	LH rear door / DD		1050.00
12	2	LH rear door hinges X		115.00
13	1	LH rear door inner lock ?		188.00
14	1	LH rear door weatherstip X		155.00
15	1	LH rear door glass regulator X ?		95.00
16	1	LH rear door glass regulator motor X		520.00
17	1	LH rear door outer moulding X		115.00
18	1	LH rear door glass channel X		218.00
19	1	LH rear door frame stickers / nec		35.00
20	1	LH rear door checker X		60.00
21	1	LH rear door inner trim board X		388.00
22	1	LH rear door inner trim baord fasteners X		35.00
23	1	LH rear lower arm X		280.00
24	1	LH rear wheel bearing ?		280.00
25	1	LH rear absorber X		368.00
26	1	LH rear knuckle arm X		420.00
27	1	rear bumper (Dismantle) ?		500.00
28	1	rear bumper side retainer / BR		45.00
29	1	rear LH fender X R		880.00
30	1	rear LH fender inner sheild X		155.00
31	1	rear LH fender inner sheild fasteners X		20.00
				8553.00
				855.30
Less 10%				7697.70

Special nett item

1	1	rear original nissan rim / cut	390	350.00
2	1	rear left tyre X		250.00
3	1	LH front door sealant / nec	40	80.00
4	1	LH rear door sealant / nec	40	80.00

Adjustment of Labour Costs for Repairs

To remove and replaced damaged parts including straightening and repositioning replacement parts.

800.00 700

Supply paint material and necessary items. To respray replaced and other affected panels.

1000.00 /

To remove n replace door components front and rear

200.00 100

To check wiring system for proper functions.

60.00 30

To remove & replace rear undercarriage parts item.

(photo)

250.00 ?

To carry out anti rust treatment.

100.00 30

To carry out 4 wheel alignment to specifications.

100.00 60

to remove and reinstall front and rear seat upholstery

120.00 X

to remove and reinstall rear windscreen

100.00 X

Total labour 2730.00

Steve (LKK)
1/12/21, 3:00pm

ML PL
L/S
My AL sy
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: