

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SMF 8737U

Adjustment of Spare Parts Costs for Repairs

Item	Qty	LIST ITEM	Vehicle parts description	Condition / Remark	Estimated by workshop
1	1	LH front door	/ DD		1130.00 961 /
2	2	LH Front door hinges	X nn		115.00
3	1	LH Front door inner lock	X nn		188.00
4	1	LH Front door weatherstrip	X nn		155.00
5	1	LH Front door glass regulator	X nn		95.00
6	1	LH Front door glass regulator motor	X nn		520.00
7	1	LH Front door glass outer moulding	X nn		115.00
8	1	LH Front door glass channel	X nn		218.00
9	1	LH Front door frame sticker	/ ne		35.00 /
10	1	LH front door checker	X nn		60.00
11	1	LH rear door	/ DD		1050.00 943 /
12	2	LH rear door hinges	X nn		115.00
13	1	LH rear door inner lock	? / Jammed		188.00 /
14	1	LH rear door weatherstrip	X nn		155.00
15	1	LH rear door glass regulator	X ? X nn		95.00
16	1	LH rear door glass regulator motor	X nn		520.00
17	1	LH rear door outer moulding	X nn		115.00
18	1	LH rear door glass channel	X nn		218.00
19	1	LH rear door frame stickers	/ ne		35.00 /
20	1	LH rear door checker	X nn		60.00
21	1	LH rear door inner trim board	X nn		388.00
22	1	LH rear door inner trim board fasteners	X nn		35.00
23	1	LH rear lower arm	X nn		280.00
24	1	LH rear wheel bearing	? / Jammed		280.00 /
25	1	LH rear absorber	X nn		368.00
26	1	LH rear knuckle arm	X nn		420.00
27	1	rear bumper (Dismantle)	? / BR		500.00 /
28	1	rear bumper side retainer	/ BR		45.00 /
29	1	rear LH fender	X R		880.00
30	1	rear LH fender inner shield	X nn		155.00
31	1	rear LH fender inner shield fasteners	X nn		20.00
					8553.00
					855.30
Less 10%					7697.70

2987
-10%
2688.30

Special nett item

1	1	rear original nissan rim	/ CUT	390	350.00
2	1	rear left tyre	X nn		250.00
3	1	LH front door sealant	/ ne	40	80.00
4	1	LH rear door sealant	/ ne	40	80.00

380

Adjustment of Labour Costs for Repairs

To remove and replaced damaged parts including straightening and repositioning replacement parts.	800.00	700
Supply paint material and necessary items. To respray replaced and other affected panels.	1000.00	/
To remove n replace door components front and rear	200.00	100
To check wiring system for proper functions.	60.00	30
To remove & replace rear undercarriage parts item. (photo)	250.00	9 100
To carry out anti rust treatment.	100.00	30
To carry out 4 wheel alignment to specifications.	100.00	60
to remove and reinstall front and rear seat upholstery	120.00	X
to remove and reinstall rear windscreen	100.00	X 2020
Total labour	2730.00	

=5088.30

Steve (LKK)
1/12/21, 3.00pm

ML PL L/S-4070.64
L/S
=4050
My AL sy
5 dgs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: