

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9769R***Not Authored* AAD2111-*Rebody B& paint**2347.43*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**01 DEC 2021****SHD9769R**

JTDKB3FU503091201

TOYOTA

PRIUS GEN 4

29/11/2021

FCI

14/07/2020

**PART****LIST**

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH

\$	Bu	485.60	—
\$	Bu	332.70	—
\$	Sm	22.00	X
\$	nd/br	374.50	—
\$	Sm	132.60	X
\$	Sm	132.60	X
\$	R	1,147.80	X
\$	na	54.60	—
\$	na	54.60	—
\$	na	47.90	—
\$	Sm	913.60	X
\$	Sm	126.70	X
\$	R	651.00	X
\$	Sm	242.50	X
\$	Sm	242.50	X
\$	R	61.00	X
\$	R	61.00	X

**TOTAL \$ 5,083.20****25% \$ 1,270.80****\$ 3,812.40****Special Nett**

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"

\$	Sm	700.00	X
\$	na	95.00	505na
\$	na	150.00	X
\$	na	200.00	X
\$	na	130.00	X
\$	na	80.00	305na

**Trans-cab Auto Services Pte Ltd****AAD2111-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9769R**

1 REAR TAILGATE STICKER "6555-3333"	\$	<i>me</i> 80.00	<i>30sn</i>
1 REAR BUMPER PROTECTOR	\$	<i>nn</i> 180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	<i>nn</i> 85.00	X
1 END PANEL TRIM CLIP	\$	<i>nn</i> 65.00	X
<b>TOTAL</b>	<b>\$</b>	<b>1,765.00</b>	

<b>TOTAL PARTS</b>	<b>\$</b>	<b>5,577.40</b>
--------------------	-----------	-----------------

**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ *nn* 300.00 X

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 *5001*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *nn* 180.00 X

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ *nn* 480.00 X

To transfer of Fender fittings, attachments and perform water seepage test.

\$ *nn* 480.00 X

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$ *nn* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

**Trans-cab Auto Services Pte Ltd****AAD2111-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9769R**

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i> 250.00	<i>X</i>
Towing Fees	\$	<i>nn</i> 150.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	<i>6601</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>151</i>
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 220.00	<i>X</i>
To replace, refix and top up coolant for radiator	\$	<i>4</i> 170.00	<i>X</i>
To lift-up / out engine with gear box and refit.	\$	<i>4</i> 440.00	<i>X</i>
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	<i>4</i> 380.00	<i>X</i>
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	<i>4</i> 380.00	<i>X</i>
<b>TOTAL</b>	<b>\$</b>	<b>10,290.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>15,867.40</b>	

**(PART-BY-PART) Repair Days****25 DAYS***3 days***LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: