



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

TP AXA.

Ashes.

ZHOU CHAOQUN

BLK 664 WOODLANDS RING ROAD #07-208

SINGAPORE 730664

Contact : 83229569, 88783862

TAX INVOICE

Repair Code : CLM17005

Date in : 29/11/2021

Vehicle Num. : SKS2861M

Model : MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT

Chassis/Eng# : JM6GJ1072G0203941/PE20630971

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>torn</i>	1	1230.00	✓ 1,230.00
REAR BUMPER RH END SEAL COVER <i>new</i>	1	56.00	X 56.00
REAR BUMPER SIDE RETAINER L/R <i>RH New</i>	2	39.60	39.60 79.20
REAR RH ARCH PANEL <i>Dented.</i>	1	1475.00	X 1,475.00
REAR RH ARCH PANEL INNER PANEL <i>Repair</i>	1	530.00	X 530.00
REAR RH DOOR <i>Distorted.</i>	1	1249.00	✓ 1,249.00
REAR RH DOOR GLASS REGULATOR <i>Damaged</i>	1	159.00	✓ 159.00
REAR RH DOOR INNER TRIM BOARD <i>crushed</i>	1	895.00	595 895.00
REAR RH DOOR RUBBER SEAL <i>new</i>	1	160.00	X 160.00
REAR RH DOOR VERTICAL GARNISH <i>new</i>	1	75.00	X 75.00
REAR RH KNUCKLE ARM <i>Damaged</i>	1	673.00	✓ 673.00
REAR RH KNUCKLE ARM BEARING <i>Damaged</i>	1	457.00	✓ 457.00
REAR RH LOWER ARM <i>Bent</i>	1	265.00	✓ 265.00
REAR RH LOWER ARM STAY ARM <i>Bent</i>	1	138.00	✓ 138.00
REAR RH SHOCK ABSORBER <i>Bent</i>	1	286.00	✓ 286.00
REAR RH SPORT RIM <i>at</i>	1	1341.00	600(SN) 1,341.00
REAR RH TRAILING ARM <i>Bent</i>	1	230.00	✓ 230.00
REAR RH UPPER ARM <i>Bent</i>	1	248.00	✓ 248.00

*** This is a computer-generated document which requires no signature.***

KaKi Bukit AuroHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ZHOU CHAOQUN
BLK 664 WOODLANDS RING ROAD #07-208
SINGAPORE 730664

Contact : 83229569, 88783862

TAX INVOICE

Repair Code : CLM17005

Date in : 29/11/2021

Vehicle Num. : SKS2861M

Model : MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT

Chassis/Eng# : JM6GJ1072G0203941/PE20630971

Subtotal before discount	7044.60	9,546.20
Percentage discount 20%	5635.68	1,909.24
Sub-total 1	SN: 600	7,636.96
REAR BUMPER CLIPS - SET	1	50.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00
REAR RH TYRE	1	480.00
Subtotal before discount	60	580.00
Percentage discount 0%		0.00
Sub-total 2		580.00
Parts-total		8,216.96

LABOUR

- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.
- To road test driving, check and resetting wheel alignments system.
- To remove, r install roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.
- To re-spray painting on the change body parts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

60.00
220.00
80.00
60.00
80.00
600.00
800.00
60.00

Labour Total

2,960.00

Parts & Labour Total

11,176.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*** This is a computer-generated document which requires no signature.***

page 2

total: 8255.68

h/s: G.6K.

08 Days

6.6K

08 Days