

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 01/12/2021

Estimated repair cost for vehicle no: SJX2054L TOYOTA VIOS E AUTO

CHASSIS: MR053HY9305165582 (2010)

01/12/2021

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Rehd</i>	\$548.90	\$548.90 ✓
2	2	REAR BUMPER SIDE RETAINER <i>new</i>	\$74.60	\$149.20 <i>130.</i>
3	2	REAR BUMPER REFLECTOR <i>LH cracked</i>	\$87.60	\$175.20 <i>8760</i>
4	1	REAR BOOTLID <i>Bruckled</i>	\$645.20	\$645.20 ✓
5	1	REAR BOOTLID LOCK <i>Rehd</i>	\$102.30	\$102.30 ✓
6	1	REAR BOOTLID INNER TRIME <i>new</i>	\$294.70	\$294.70 +
7	1	REAR BOOTLID OUTER MOULDING <i>new</i>	\$188.30	\$188.30 +
8	1	REAR BOOTLID EMBLEM LOGO <i>2</i>	\$55.60	\$55.60 ✓
9	1	REAR BOOTLID EMBLEM VIOS <i>new</i>	\$84.60	\$84.60 ✓
10	1	REAR BOOTLID EMBLEM E	\$34.60	\$34.60 ✓
11	2	REAR BOOTLID HINGE <i>new</i>	\$65.10	\$130.20 +
12	1	REAR WEATHER STRIPE <i>lit</i>	\$175.80	\$175.80 ✓
13	2	REAR TAILLAMP <i>cracked</i>	\$457.60	\$915.20 <i>570.</i>
14	2	REAR TAILLAMP INNER PANEL <i>LH Dented</i>	\$194.70	\$389.40 <i>194.70</i>
15	1	REAR END PANEL <i>Dented</i>	\$455.60	\$455.60 ✓
16	1	REAR END PANEL TOP GARNISH <i>cracked</i>	\$189.10	\$189.10 ✓
17	1	REAR SPARE TYRE COMPARTMENT PANEL <i>Rehd</i>	\$863.70	\$863.70 +
18	1	REAR SPARE TYRE TOP BOARD <i>torn</i>	\$185.10	\$185.10 ✓
19	1	REAR TOOLS SPONGE <i>Rehd</i>	\$186.40	\$186.40 ✓
20	1	REAR FENDER <i>2</i>	\$873.10	\$873.10 +
21	2	REAR FENDER AIR VENT <i>2</i>	\$93.60	\$187.20 +
22	2	REAR FENDER INNER TRIM <i>2</i>	\$445.60	\$891.20 +

TOTAL : \$7,720.60

LESS 25 % \$1,930.15

SUB-TOTAL : \$5,790.45

3469.70

2602.7

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>3 All</i>	\$80.00	\$80.00 <i>30</i>
2	1	REAR END PANEL TOP GARNISH CLIPS	\$60.00	\$60.00 <i>10</i>
3	1	REAR REVERSE SENSOR <i>Revd</i>	\$250.00	\$250.00 <i>200</i>
4	1	REAR WINDSCREEN GLASS SEALANT <i>Rea</i>	\$120.00	\$120.00 <i>x</i>
5	1	REAR REVERSE CAMERA <i>Re m</i>	\$380.00	\$380.00 <i>x</i>
6	1	REAR END PANEL SEALANT <i>Rea</i>	\$60.00	\$60.00 <i>-</i>
7	1	REAR FENDER SEALANT <i>Re m</i>	\$60.00	\$120.00 <i>+</i>
8	1	REAR NUMBER PLATE WITH CASING <i>Re m</i>	\$60.00	\$60.00 <i>+</i>
TOTAL:				\$1,130.00
			TOTAL PARTS:	\$6,920.45

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,400.00 <i>90</i>
2	LABOUR FOR SPRAYPAINTING	\$1,200.00 <i>90</i>
3	WIRING CHECK	\$80.00 <i>30</i>
4	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS	\$300.00 <i>80</i>
5	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	\$150.00 <i>x</i>
6	LABOUR FOR REMOVE & TRANSFER ALL REAR BOOTLID FITTING	\$200.00 <i>60</i>
<i>7 Labour for removal of reverse sensor</i>		<i>100 50</i>
<i>8 Labour for removal of upholstery</i>		<i>150 80</i>
Subtotal :-		\$3,330.00
Total:-		\$10,250.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan Lij
L/S - 02/12/21.

06 days

Total: 5002.27

L/S: 4K

4K