



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI21012197/Uuf3e2 Date: 09/12/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 5596K	Veh. Inspected	SJJ 2525T	
Policy No.	D-21098232MVPC	Coverage (\$)	0.00	
Claim No.	D21003317MVPC	Excess (\$)	0.00	
Assign From	CAROLINE CABRERA	Assign Date	01/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180KCOUPE (A)	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	WDB2037462A944620	Colour	BLACK	
Odometer	54644 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	6 mm	
L/H Front Tyre	205/55 R16	DUNLOP	6 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	6 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/11/2021	Inspection Date	01/12/2021	
Survey held at	KAI LIANG MOTOR SERVICE BLK 1 KAKI BUKIT AVE 6 #01-101 AUTOBAY @KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	