



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

TP AxA
Denise

LKK

DATE: 02/12/2021 OUR REF: UAPL1499
REPAIR ESTIMATE TO THE MIT-ATTRAGE NO: SKU3423C
REAR ITEM

1 REAR BOOT ASSY	Distorted	\$ 848.00	✓
2 REAR BOOT HINGES	NEW	\$ 384.00	X
1 REAR BOOT LOCK	Distorted	\$ 216.00	✓
1 REAR BOOT LOCK STRIKER	NEW	\$ 58.00	X
1 REAR BOOT WEATHERSTRIP	cut	\$ 212.00	✓
1 REAR BOOT OUTER CHROME STRIP	NEW	\$ 258.00	X
1 REAR BOOT EMBLEM		\$ 61.00	✓
1 REAR BOOT (ATTRAGE) EMBLEM	given	\$ 74.00	✓
1 REAR BOOT (MIVEC) EMBLEM		\$ 58.00	✓
2 REAR TAILLAMP ASSY	could	\$ 790.00	✓
2 REAR TAILLAMP PANEL	LH Dented	\$ 422.00	211
1 REAR TAIL END PANEL	Distorted	\$ 515.00	✓
1 REAR TAIL END PANEL AIR DUCT (INNER)	Distorted	\$ 98.00	✓
1 REAR TAIL END PANEL AIR DUCT (OUTER)	Distorted	\$ 98.00	✓
1 REAR TAIL END PANEL INNER GARNISH	could	\$ 187.00	✓
1 REAR SMART KEYLESS SENSOR	NEW	\$ 223.00	X
1 REAR KEYLESS SENSOR JOINT UNIT	NEW	\$ 211.00	X
1 REAR BUMPER FACE	Distorted	\$ 765.00	✓
2 REAR BUMPER SIDE RETAINERS	NEW	\$ 64.00	✓
1 REAR BUMPER CLIPS (1 SET)	NEW	\$ 55.00	30
2 REAR BUMPER LOWER RELETOR	LH could	\$ 118.00	59
1 REAR L/H FENDER ASSY	Breached	\$ 813.00	✓
1 REAR R/H FENDER ASSY	Repair	\$ 813.00	X
2 REAR FENDER INNER SIDE GARNISH	tom	\$ 442.00	✓
1 REAR WINDSCREEN MOULDING	NEW	\$ 187.00	✓
1 REAR SPARE TYRE TOP COVER	torn	\$ 255.00	✓
1 REAR FLOOR PANEL	Breached	\$ 677.00	✓
1 REAR EXHAUST BOX	NEW	\$ 467.00	X
2 REAR EXHAUST BOX RUBBER HOLDER	NEW	\$ 56.00	X
		\$ 9,425.00	
	LESS 10%.....	\$ 942.50	
		\$ 8,482.50	

6660
5994

SPECIAL NETT:-

1 SET REAR REVERSE SENSOR	Distorted	\$ 280.00	200
1 REAR WINDSCREEN GLASS RUBBER GUM	NEW	\$ 60.00	✓
1 REAR NUMBER PLATE	Bank	\$ 50.00	✓

310

LABOUR CHARGES:-

TO TOW VEHICLE TO WORKSHOP		\$ 100.00	60
TO DISM/REFIX REAR WINDSCREEN GLASS		\$ 160.00	120
TO SPRAY UNDERCOATING IN REPAIR		\$ 200.00	120
TO DISM/REWIRED DAMAGED PORTION		\$ 200.00	30
TO DISM/RENEW REAR REVERSE SENSOR		\$ 80.00	50
TO DISM/REFIX ROOF LINING, SEAT, GARNISH IN REPAIR		\$ 220.00	120
TO DISM/RENEW REAR EXHAUST PIPE		\$ 120.00	X
TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS		\$ 1,000.00	1600
TO PUTTY AND RESPRAY DAMAGED PORTION		\$ 1,300.00	1200
		\$ 13,152.50	

3300

Insurance adjusters hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total: 9604
C/S: 7.6K.
12 Days