



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 8002R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FORK ASSY	SERVICEABLE	980.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	285.00	-
1	FRONT RIM	CUT	355.00	355.00
1	FRONT BRAKE DISC	SERVICEABLE	198.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	58.00	-
1	FRONT RIM BEARING	NECESSARY	280.00	60.00
1	HEADLAMP ASSY	CRACKED	960.00	960.00
1	LAMP STAY	TO REPAIR SEE LABOUR	225.00	-
2	SIDE MIRROR	CUT	360.00	360.00
1	HANDLE BAR	BENT	135.00	135.00
1	SET HANDLE BAR BALANCER	NOT NECESSARY	80.00	-
1	SET HAND GRIP	NOT NECESSARY	60.00	-
2	BRAKE LEVER	NOT NECESSARY	104.00	-
1	FRONT INNER LOWER PANEL (FUEL TANK)	CRACKED	155.00	155.00
2	FOOTSTEP PANEL	CUT	310.00	310.00
1	FRONT COMPARTMENT COVER	NOT NECESSARY	178.00	-
1	SET FAIRING COVER	CRACKED	1,150.00	900.00
	LESS 10% DISCOUNT		-587.30	-323.50
			5,285.70	2,911.50
<u>SPECIAL NETT ITEMS</u>				
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEAL (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	120.00	-
1	SET NUMBER PLATE (SN)	NOT NECESSARY	38.00	-
1	PCX EMBLEM (SN)	NECESSARY	80.00	80.00
			324.00	80.00
<u>LABOUR</u>				
	TO PROVIDE TOWING SERVICE (LOD).		80.00	50.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-

Report Ref No. CS/GAI21012199/Utf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING.		500.00	380.00
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF LAMP STAY.		480.00	300.00
			1,140.00	730.00
	GRAND TOTAL		6,749.70	3,721.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS/GAI21012199/Uff3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.