

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN LENG KHIM
 78 LUXUS HILL AVE

SINGAPORE 804913

TEL: 98899623

ATTN:

Your Ref No: SMJ2858Y

Claim Type: Third Party → India

Accident Date: 27/11/2021

TP Veh Reg No: SNB6704L

Estimate No: MC1902316

Date: 30 Nov 2021

Policy No: 21-MS001866

Veh Reg No: SMJ2858Y

Make/Model: HONDA JAZZ 1.3 CVT

*Like
13/11
3/12*

*Not authorized
8280/-
1 day*

Estimate Repair Cost to Vehicle No :SMJ2858Y

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BUMPER	1 PC	<i>12</i> 529.40 X	
2 REAR BUMPER GRILLE LH	1 PC	<i>12</i> 31.90 X	
3 REAR BUMPER SIDE RETAINER LH	1 PC	<i>12</i> 23.50 X	
4 REAR BUMPER CLIPS	5 PC	<i>12</i> 17.50 X	
		602.30	
	Less 20%	120.46	481.84
Special Nett			
5 REVERSE SENSOR	1 SET	<i>12</i> 350.00 X	
		350.00	350.00
LABOUR			
6 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR REAR INNER PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	300.00	<i>80/-</i>
7 TO SPRAY REAR BUMPER	1 PC	300.00	<i>200/-</i>
		600.00	600.00
	Total		SS 1,431.84
	Add GST @ 7%		100.23
	Total Amount Payable		SS 1,532.07

TOTAL: SINGAPORE DOLLAR ONE THOUSAND FIVE HUNDRED THIRTY TWO AND CENTS SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
 Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For AH LIM MOTOR COMPANY

Zila
 Ah Lim Motor Company
 AUTHORIZED SIGNATURE