

REF: C72/21012204/k7

ASSIGNMENT

Date:

Veh No:

GBG 6982R

&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:

Repairer Reference: 044956

Date calculated: 08/12/2021 2:44 PM

Full Report

Registration: GBG6982R

Printed: 08/12/2021 2:44 PM

Summary Information

Claim

Location: Singapore (SG)

Work Provider:

China Taiping Insurance

(Singapore) Pte Ltd

Printed by:

SH Motor

Currency:

SGD

Claim Reference:

Date of Incident:

07/12/21

Estimated Repair Time:

Hire Car Start:

Actual Repair Days:

Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

NISSAN

Model:

NV200 (M20)

Sub Model:

BASE MODEL

Model Sheet Number:

71 89 01

Registration:

GBG6982R

VIN number:

Odometer:

Model Specs

COMBI

WING DOORS GLAZED

REAR S/PANEL GLAZED

TWO COAT METALLIC

PAINTING OFF VEHICLE

*Not Authorised
 Repair after 4 days*

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	JOB ALLOWANCE		5.0	21.00
6712A1ZAX	R + R L/WING DOOR		6.0	25.20
5411A1	RENEW L/WING DOOR (REMOVED)		12.0	50.40
UG14A1	R + R L/R WING DOOR WINDOW		16.0	67.20
	INCLUDES: R + R DOOR TRIM			
6611A1)	R + R REAR BUMPER		3.0	12.60
5010A1ZAX	RENEW REAR BUMPER (REMOVED)		1.0	4.20
2934	R/R LOADING DOOR REPAIR		10 28:0*	84.00

Labour Cost

Panel / Mechanical Labour

Hrs 6.30 WU 63.0 Price SGD 264.60

Total of Labour

264.60

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Audatex System Using Manufacturer Times

Page 1 of 3

PRINT DATE 08/12/2021

REF: C72/21012204/K7

ASSIGNMENT

Date:

Veh No:

GAG 6982R

C

Code	Description - TWO COAT METALLIC	Time Basis 10 WU/h
	L/R LOADING DOOR NEW PART PAINTING	WU Price SGD
	R/R LOADING DOOR NEW PART PAINTING	18.0
		18.0

Paint Material Per Part

Code	Description	Price SGD
2933	L/R LOADING DOOR NEW PART PAINTING	53.66
2934	R/R LOADING DOOR NEW PART PAINTING	53.66

Labour Cost - Paint

Factor	Hrs	WU	Price SGD
Time Paint	42.00 SGD/h	36.0	
Preparation Comp. Work Metal		9.0	37.80
Total	10 WU/h	45.0	189.00

Material Cost - Paint

	Price SGD
New Part Painting	107.32
Material-constant Metal	18.10
Total	125.42

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01
				Price SGD
2581	REAR BUMPER	H5022 3LGEH	Original	360.00
2933	L/R LOADING DOOR	K0101 3LGDB	Original	850.00
3015	MANUFACTURER BADGE	90890 JX00A	Original	55.00
3017	BADGE MODEL	90895 JX00A	Original	60.00
3159	L/R WDW ADHESIVE KIT	KE150 10002		0.00
				Savings
				Subtotal
				Total

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Extras

Code	Description	Price SGD
1000	STICKER "70kmh" REAR DOOR	5.00*
1001	STICKER "5 PAX" REAR DOOR	5.00*
1002	LH WINDOW SEALANT REAR DOOR	35.00*
1003	LH WINDOW INNER SEAL REAR DOOR	10.00*
1004	REAR PARKING SENSORS REAR BUMPER	260.00*2000
1005	TUFF KOTE LH REAR DOOR	100.00*301
1006	Electrical work Electrical work	25.00*151
Total Extras		440.00

REF: C72/21012204/k7

ASSIGNMENT

Date:

Veh No: 1

GAG 69820

C

Description		Price SGD	
Final Calculation			
Parts		SGD	SGD
Total Parts		1,325.00	1,325.00
Labour Time Base 10 WU/h			
Total 63.0 WU X 42.00 SGD/h			
Total of Labour		264.60	264.60
Total Of Extras	222.60		440.00
Paint Work Time Base 10 WU/h			
Labour Cost 45.0 WU X 42.00 SGD/h		189.00	
Material Cost		125.42	
Total Paint Including Material			314.42
Repair Cost Excludes GST			2,344.02
GST (+7.0%)			164.08
Repair Cost Included GST			2,508.10

Comments

- * - USER SUPPLIED DATA
- UN - NO MANUFACTURERS CODE EXISTS
- WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.