

ASS. REC. BY:

REF:

C72/ 21012204/K7

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ S & H

of _____ 5100

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Soon: _____ Consistent? : Yes or No

Est. Repairs: 09 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GAG 6982R Yr Regn: 09, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MS NV200 c.c. 1461

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 131885 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSKY BAM 208 0145964

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S / Rim / STD A / Rim or

Tyre Size: F: Mando _____

R: Aplus 175/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 5 mm

L/Bal. 9 mm L/Bal. 5 mm

D.O.A. 23/11/21 D.O.I. 18/12/21

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

/

LUMP SUM \$1700, 4DAYS

RED: 644.02:27%

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trlp: _____

Survey Fee:

Transportation:

S + RS: \$

Fees:

Others:

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format:

Lump Sum / I.B.I. (\$) _____

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
 Repairer Reference: 044956
 Date calculated: 08/12/2021 2:44 PM

Full Report
Registration: GBG6982R
Printed: 08/12/2021 2:44 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	07/12/21
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
 Manufacturer: NISSAN
 Model: NV200 (M20)
 Sub Model: BASE MODEL
 Model Sheet Number: 71 89 01
 Registration: GBG6982R
 VIN number:
 Odometer:

Not Authorise
Repair after 4 days
6/12/21

Model Specs
 COMBI WING DOORS GLAZED REAR S/PANEL GLAZED TWO COAT METALLIC
 PAINTING OFF VEHICLE

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	JOB ALLOWANCE		5.0	21.00
6712A1ZAX	R + R L/WING DOOR		6.0	25.20
5411A1	RENEW L/WING DOOR (REMOVED)		12.0	50.40
UG14A1	R + R L/R WING DOOR WINDOW INCLUDES: R + R DOOR TRIM		16.0	67.20
6611A1)	R + R REAR BUMPER		3.0	12.60
5010A1ZAX	RENEW REAR BUMPER (REMOVED)		1.0	4.20
2934	R/R LOADING DOOR REPAIR		10 20.0*	84.00

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	6.30	63.0	264.60
Total of Labour			264.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature
 Date:

PRINT DATE 08/12/2021

Paint

Paint Work

Code	Description - TWO COAT METALLIC	SYSTEM AZT		Time Basis 10 WU/h	
		WU	Price SGD		
	L/R LOADING DOOR NEW PART PAINTING	18.0			
	R/R LOADING DOOR NEW PART PAINTING	18.0			

Paint Material Per Part

Code	Description	Price SGD
2933	L/R LOADING DOOR NEW PART PAINTING	53.66
2934	R/R LOADING DOOR NEW PART PAINTING	53.66

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			36.0	
Preparation Comp. Work Metal		0.90	9.0	37.80
Total	10 WU/h	4.50	45.0	189.00

Material Cost - Paint

	Price SGD
New Part Painting	107.32
Material-constant Metal	18.10
Total	125.42

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
2581	REAR BUMPER	H5022 3LGEH	Original	Per	360.00
2933	L/R LOADING DOOR	K0101 3LGDB	Original	Per	850.00
3015	MANUFACTURER BADGE	90890 JX00A	Original	Per	55.00
3017	BADGE MODEL	90895 JX00A	Original	Per	60.00
3159	L/R WDW ADHESIVE KIT	KE150 10002			0.00
f: OEM Parts					
n: Non-OEM Parts					
u: Used parts					
Savings					0.00
Subtotal					1,325.00
Total					1,325.00

Extras

Code	Description	Price SGD
1000	STICKER "70kmh" REAR DOOR	Per 5.00*
1001	STICKER "5 PAX" REAR DOOR	Per 5.00*
1002	LH WINDOW SEALANT REAR DOOR	Per 35.00*
1003	LH WINDOW INNER SEAL REAR DOOR	Per 10.00*
1004	REAR PARKING SENSORS REAR BUMPER	Per 260.00*2000
1005	TUFF KOTE LH REAR DOOR	100.00* 30l
1006	Electrical work Electrical work	25.00* 15l
Total Extras		440.00

Code	Description	Price SGD
------	-------------	-----------

Final Calculation

	SGD	SGD
Parts	1,325.00	
Total Parts		1,325.00
Labour Time Base 10 WU/h		
Total 63.0 WU X 42.00 SGD/h	264.60	
Total of Labour		264.60
Total Of Extras		440.00
Paint Work Time Base 10 WU/h		
Labour Cost 45.0 WU X 42.00 SGD/h	189.00	
Material Cost	125.42	
Total Paint Including Material		314.42
Repair Cost Excludes GST		2,344.02
GST (+7.0%)		164.08
Repair Cost Included GST		2,508.10

Comments
 * - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 29/11/2021 16:19 (SGT)
Date of Accident 25/11/2021 15:15 (SGT)
Exact Location of Accident Guillemard Rd, Singapore
Additional Location Information Lorong 32 Geylang
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBG6982R

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner Autovill Export and Lease
Company Reg No 5XXXX510D
Email Address kangsheng978@gmail.com
Mobile Phone No (Phone) +65-83553124
Alternative Phone No (Home) +65-83553124

VEHICLE PARTICULARS

Manufacturer Nissan
Model Nv200
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Manual
CC 1455

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMCVSNA00094542100
Cover Note Number -

DRIVER

Name of Driver Azim Nadim Yaham
Work Permit No GXXXX909K



**SINGAPORE
POLICE FORCE**



T/20211129/7019

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No: T/20211129/7019

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/11/2021 12:30		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: ONG TING KANG			Address: 762 WOODLANDS AVENUE 6 #09-78 SINGAPORE 730762		
ID Type / ID No.: NRIC NO / S8127044I			Contact No.: Home/Office: Mobile: 83553124		
Nationality: SINGAPORE CITIZEN			Email: kangsheng978@gmail.com		
Sex: Male	Age: 40	Date of Birth: 24/08/1981	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Other painters and related workers			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 25/11/2021 15:15	Type of Location: T-Junction
Location: GUILLEMARD ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 20 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: head to rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of
GBG6982R	Van					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20211129/7019

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

Report No. T/20211129/7019

CONTINUATION OF REPORT

Driver Name	AZIM NADIM JAHAM	ID No.	G8121909K
Related Vehicle	GBG6982R (Van)	Contact No.	83553124
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: 27/03/2023
Date	27/11/2021	Date	27/11/2021
No. of Days granted Medical Leave	05	Degree of	Serious
Driver Name	ONG TING KANG	ID No.	S8127044I
Related Vehicle	GBG6982R (Van)	Contact No.	83553124
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Brief Details.

On 25th Nov 2021 @ 1515 hrs, I stopped my vehicle (GBG6982R) at the stop line at Lor 32 Geylang rd. while waiting to exit and turn left onto main road to the direction of Guillemard rd when suddenly, there was an impact from behind by SJJ 956 X. I was rear ended by it and hence, suffered injury.