

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012207/APA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070091312
Claimant Vehicle No :	SLV9448A	Insured Vehicle No :	SMC5892P
Date of Loss:	27/11/2021	Nature of Claim:	TP
		Claim No:	2785885553SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV9448A	Engine No:	G4FGHH691092
Make & Model:	KIA CERATO K3, 1.6 (A)	Chassis No:	KNAFX411MJ5761166
Reg. Date:	24/01/2018 (Man. Year: 2017)	Odometer:	57182 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,741.50	3,540.80	7,200.70	67.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,910.00	1,700.00	3,210.00	65.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,651.50	5,240.80	10,410.70	66.52
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	15,651.50	4,200.00	11,451.50	73.17
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,807.45		

INSPECTION

Date of Assignment:	30/11/2021	
Date Inspected:	30/11/2021	Inspected At: Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	783.50 FL	*- FL
2	1		*REAR BUMPER SIDE RETAINERS	Not Necessary	75.30 FL	*- FL
3	1		*SET REAR BUMPER CLIPS	Not Necessary	50.00 FL	*- FL
4	1		*REAR FENDER RH	Repair	1,187.90 FL	*- FL
5	1		*REAR FENDER ARCH STICKER RH	Necessary	32.00 FL	*32.00 FL
6	1		*REAR FENDER INNER COWLING RH	Not Necessary	165.20 FL	*- FL
7	1		*REAR W/SCREEN MOULDING	Not Necessary	126.90 FL	*- FL
8	1		*REAR W/SCREEN INNER SEAL	Not Necessary	60.00 FL	*- FL
9	1		*TAILLAMP RH	Not Necessary	398.70 FL	*- FL
10	1		*TAILLAMP INNER SEALER RH	Not Necessary	38.00 FL	*- FL
11	1		*REAR ABSORBER RH	Not Necessary	298.60 FL	*- FL
12	1		*REAR WHEEL BEARING RH	Damaged	385.20 FL	*385.20 FL
13	1		*REAR AXLE	Not Necessary	1,126.80 FL	*- FL
14	1		*REAR DOOR RH	Distorted	876.90 FL	*876.90 FL
15	2		*REAR DOOR BLACK STICKER RH	Necessary	130.40 FL	*130.40 FL
16	1		*REAR DOOR OUTER CHROME MOULDING RH	Not Necessary	129.00 FL	*- FL
17	2		*REAR DOOR HINGE RH	Not Necessary	119.40 FL	*- FL
18	1		*REAR DOOR CHECKER RH	Not Necessary	75.20 FL	*- FL
19	1		*REAR DOOR INNER LOCK RH	Not Necessary	356.90 FL	*- FL
20	1		*REAR DOOR W/STRIP RH	Not Necessary	168.90 FL	*- FL
21	1		*REAR DOOR SIDE RUBBER RH	Not Necessary	52.00 FL	*- FL
22	1		*REAR DOOR REGULATOR MOTOR RH	Not Necessary	209.80 FL	*- FL
23	1		*REAR DOOR REGULATOR GEAR RH	Not Necessary	467.00 FL	*- FL
24	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	185.00 FL	*- FL
25	1		*REAR DOOR OUTER HANDLE COVER RH	Not Necessary	65.90 FL	*- FL
26	1		*REAR DOOR INNER TRIM RH	Cracked	658.90 FL	*658.90 FL
27	1		*SET REAR DOOR INNER TRIM CLIP	Necessary	40.00 FL	*30.00 FL
28	1		*REAR DOOR SPEAKER RH	Not Necessary	195.00 FL	*- FL
29	1		*SIDE ROCKER PANEL RH	Dented	798.60 FL	*798.60 FL
30	1		*FRONT DOOR RH	Not Necessary	925.00 FL	*- FL
31	1		*FRONT DOOR BLACK STICKER RH	Not Necessary	53.00 FL	*- FL
32	1		*REAR W/SCREEN SEALANT	Not Necessary	60.00 FS	*- FS
33	1		*SET DOOR SUN VISOR	Necessary	280.00 FS	*60.00 FS
34	1		*SPORT RIM LH	Cut	750.00 FS	*600.00 FS
35	1		*SPORT RIM TYRE LH	Torn	280.00 FS	*200.00 FS
36	1		*SET BODY SEALANT	Necessary	60.00 FS	*60.00 FS
37	1		*TAILAMP CLIPS	Not Necessary	30.00 FS	*- FS
38	1		*FRONT NO PLATE W/COVER	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,765.00	3,832.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,023.50	291.20
Total Parts (\$\$)	10,741.50	3,540.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	800.00
2	SPRAY PAINTING CHARGE	New	1,800.00	600.00
3	CHECK WIRING ON TAILLAMP	New	50.00	0.00
4	ANTI RUST	New	120.00	60.00
5	REMOVE AND INSTALL W/SCREEN	New	120.00	0.00
6	REMOVE AND INSTALL FRONT AND REAR DOOR PART	New	200.00	80.00
7	REMOVE AND INSTALL INTERIOR UPHOLSTERY	New	150.00	0.00
8	REMOVE AND INSTALL REAR UNDER CARRIAGE	New	350.00	80.00
9	TO CHECK FOUR WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (\$\$)			4,910.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >