

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19960/196R GS1 Reg. No. 19-960/196-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI21012208/Utf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	15/12/2021	
			С	ode:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMV 9267T	Veh. Inspected		SMN 3113K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10012703/KY	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		01/12/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ CLA200 (A)	c.c		1332	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	WDD1183872N005260	Colour		RED	
	Odometer	58719 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/45 R18	HANKOOK		5 mm	
	L/H Front Tyre	225/45 R18	HANKOOK		5 mm	
	R/H Rear Tyre	225/45 R18	HANKOOK		5 mm	
	L/H Rear Tyre	225/45 R18	HANKOOK		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	29/11/2021	Inspection Date		06/12/2021	
	Survey held at AUTO BAY @ KAKI BUKIT AVENUE 6					
	Repairer	KT GARAGE PTE LTD				
5a.						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: