



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /TAN BOON SOO Reg No/Reg Date SFT7710L / 07/12/201 Date In/Mileage 01/12/2021/ 0 Chassis No KNAF3416MK5022966 Engine No G4FGJH712643 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	01/12/2021/ 15:29	BLK	282 / Kevin Leong	43264

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE ON REAR LH DOOR & AFFECTED AREA REPAIR ON REAR BUMPER, REAR LH FENDER & LH SIDE SILL	2.5 x 400			1000 2000.00
E PNT98000 PAINT WORK ON REAR BUMPER, REAR LH FENDER, REAR LH DOOR & LH SIDE SILL	4 x 350			1400.00
E PNT88000 TO TRANSFER REAR LH DOOR ATTACHMENTS TO NEW PANEL				120.00
M SUNDRY PERFORM RUST PREVENTION				40 80.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA				40 80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY TO TRANSFER REAR LH RIM INCLUDING BALANCING				30.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR				80 80.00
M SUNDRY SUNDRIES				20 40.00
M SUNDRY TO SUPPLY REAR SPORT RIM				380.00
M PANEL ASSY-REAR DOOR, LH	1.00	1377.00	20.00	1101.60
M MOULDING ASSY-RR DR FRAME, LH	1.00	44.00	20.00	35.20
M W/STRIP ASSY-RR DR BELT O/S LH	1.00	60.00	20.00	48.00
M W/STRIP ASSY-RR DR SIDE LH	1.00	102.00	20.00	81.60
M FILM-ANTI CHIPPAGE LH	1.00	27.00	20.00	21.60
M GUARD-REAR WHEEL, LH	1.00	75.00	20.00	60.00

Confirm & accepted by

CLK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damage - 4 part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis

Authorized signatory and company stamp

EXCISE - ?

P/P, My B/L M

5 days

Nett

5788.00

Total Payable

5,788.00

405.16

6,193.16

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.