



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/TAN BOON SOO
	Reg No/Reg Date	SFT7710L / 07/12/201
	Date In/Mileage	01/12/2021/ 0
	Chassis No	KNAF3416MK5022966
	Engine No	G4FGJH712643
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	01/12/2021/ 15:29	BLK	282 / Kevin Leong	43264			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000		REPLACE ON REAR LH DOOR & AFFECTED AREA						2000.00
		REPAIR ON REAR BUMPER, REAR LH FENDER & LH SIDE SILL						
E PNT98000		PAINT WORK ON REAR BUMPER, REAR LH FENDER, REAR LH DOOR & LH SIDE SILL						1400.00
E PNT88000		TO TRANSFER REAR LH DOOR ATTACHMENTS TO NEW PANEL						120.00
M SUNDRY		PERFORM RUST PREVENTION						80.00
M SUNDRY		TO APPLY SEALANT ON AFFECTED AREA						40.00
A 54900099		CHECK WIRING & CHASSIS ELECTRICAL SYSTEM						30.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM						120.00
M SUNDRY		TO TRANSFER REAR LH RIM INCLUDING BALANCING						30.00
B WHEELALIGNMENT		To Conduct Computerize Full Wheel Alignment						120.00
E PNT88000		REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR						80.00
M SUNDRY		SUNDRIES						40.00
M SUNDRY		TO SUPPLY REAR SPORT RIM						380.00
M PANEL ASSY-REAR DOOR,LH					1.00	1377.00	20.00	1101.60
M MOULDING ASSY-RR DR FRAME,LH					1.00	44.00	20.00	35.20
M W/STRIP ASSY-RR DR BELT O/S LH					1.00	60.00	20.00	48.00
M W/STRIP ASSY-RR DR SIDE LH					1.00	102.00	20.00	81.60
M FILM-ANTI CHIPPG LH					1.00	27.00	20.00	21.60
M GUARD-REAR WHEEL,LH					1.00	75.00	20.00	60.00

Confirm & accepted by

Nett **5,788.00**
7% GST on **5788.00** **405.16**
Total Payable **6,193.16**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.