

Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)
Email: motor@wahhong.sg

(199806235M)

Vehicle No.

SJS9163K SUZUKI SWIFT

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
1 1 1 1	Front fender LH ON Front fender signal lamp LH OK Front bumper (Repair refer to labour) X N N Front door LH (Repair refer to labour) X N Front bumper signal lamp LH OK Front bumper clips X N Front bumper clips X N Front fender shield clips X N	Part Items Total:	259.00 / 20.00 / 0.00 0.00	
		SN Items Total:	60.00	
		Total Parts	297.15	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg (199806235M)

Vehicle No. SJS9163K SUZUKI SWIFT

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	900
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	30.00 /	
4	To perform anti-rust treatment on affected areas	30.00	20
5	Check and wheel computerize alignment	80.00	60
6	To remove and refixs front tyre and wheel balancing in order to front rim	50.00 🤾	Flor
			200
	Labour Total :	1790.00	
	TOTAL (PARTS & LABOUR):	2087.15	

Steve (LKK) 6/12/21, 1-12/2 ML PL =70

3 dys 4/3
1/5

1/5

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: