

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melody Teoh

Date: 03 Dec 2021

Preliminary Advice

Insured Vehicle No	: SFM8628Y	Accident Date	: 30/11/2021
TP Vehicle No	: SMJ4955L	Assignment Date	: 01/12/2021
Make	: HONDA FIT	Est. Duration of Repair	: 12
Date of Inspection	: 02/12/2021		
Inspection At	: WAH HONG MOTORS & CREDIT PTE LTD (HQ) 38 TOH GUAN ROAD EAST, #01-57, ENTERPRISE HUB SINGAPORE 608581		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,183.90
Revised Amount	:S\$	7,424.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,424.20

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.